

THE SOFTWARE DISPATCH

DOS/BOSS

digital

THE SOFTWARE DISPATCH

DOS/BOSS

NOVEMBER 1973

The material in this document is for information purposes only and is subject to change without notice. Digital Equipment Corporation assumes no responsibility for any errors which may appear in this document.

SOFTWARE ENGINEERING AND SERVICES
SOFTWARE COMMUNICATIONS
Digital Equipment Corporation
Maynard, MA 01754

digital

The following are trademarks of Digital Equipment Corporation,
Maynard, Massachusetts:

DIGITAL	LAB-K	DEC DATA SYSTEMS
DEC	SABR	COMTEX-11
PDP	TYPESET-8	QUICKPOINT
UNIBUS	DECtape	DDT
COMPUTER LABS	IDACS	CDP
EDGRIN	INDACS	RAD-8
FLIP CHIP	DIBOL	RSX
FOCAL	OMNIBUS	RSTS
GLC-8	EDUSYSTEM	DECCOMM
KA10	OS/8	PHA
DECsystem-10	DECpac	LAB-8
	DECSET	DECwriter

TABLE OF CONTENTS

1.0	INTRODUCTION	
2.0	HOW TO USE YOUR SOFTWARE DISPATCH	
2.1	Introductory Section	
2.2	General Format of Articles	
2.3	Filing	
2.3.1	Software Product Components and Descriptions	
3.0	REFERENCE MANUALS	
	DOS-15 Software Review	
	<u>Bootstrap</u>	
	Programming Note Regarding .GET & .PUT MACROS	#1
	Programming Note on Special Bits Meaning in Reserved Word	#2
	<u>Card Reader Handlers</u>	
	Handler for the CR15 Card Reader	#1
	Problems when conditionalized for the CR15 Card Reader	#2
	<u>Chain</u>	
	Programming Notes	#1
	<u>Chain & Execute</u>	
	Clarification of obscure points	#1
	<u>Checkout Package</u>	
	Functional Description	#1

SOFTWARE DISPATCH

DOS/BOSS

November, 1973

DDT

Programming Notes #1

DECTape Handlers

Functional Change #1

Source change to prevent .WAIT X from getting a buffer #2

Support of .TRAN Function on PDP-8/10/11 Tapes #3

Disk Handlers

Programming Note on Use of .USER Macro #1

DOSSAV

Operating Instructions #1

DUMP

Information on .DAT slot Assignments #1

Some Information on QAREA's #2

Patch to correct problem with selective dumps #3

Patch to correct looping problem #4

DUMP described in DOS Keyboard Command Guide #5

FOCAL

The Random Number Generator #1

FORTRAN

Usage Restriction and Precaution #1

Usage of ADSS Versus DOS Magtape Handler MTF #2

Corrected Version of ADJ to Remove Incompatibility with
FORTRAN Object Time System #3

SOFTWARE DISPATCH

DOS/BOSS

November, 1973

FORTRAN Compiler

Patch to Correct Improper Imbedded Subscript Calculation	#1
Errors not Detected During Compilation	#2
Programming to avoid Incorrect Mode Typing of Functions Declared EXTERNAL	#3
Incomplete DO Statement Difficulties	#4

FORTRAN OTS

Programming Note to Eliminate Carriage Return	#1
Programming Note	#2
Numerical Restrictions	#3
Reading INTEGER Variables Causing IOPS Ø	#4

Line Printer Handlers

Source Change to Prevent Return to Mainstream, at API Level 4 on .WAIT	#1
--	----

Linking Loader

Features of this Version	#1
--------------------------	----

LK35 Keyboard Handler

Functional Description	#1
------------------------	----

MACRO-15

New Switches in this Version	#1
Macros Implemented Specifically for DOS-15	#2
Pseudo-op, .CBD	#3

MACRO-15 (Continued)

Note on Binary Output File Extensions	#4
Problems Corrected	#5
Programming Note on Usage of 'T' Switch	#6
Patch to Expand .RTRAN Correctly	#7
Patch to Correct Printing of Erroneous Message	#8
Solutions to Miscellaneous Problems	#9
Leading Commas in Command String Foiled BOSS-15 Operation	#10
Problem with Parameter File Name Being Assigned to Listing File	#11
Patch to Prevent NEXM System Crash in an X4K Environment	#12

Magtape Handlers

Functional Changes	#1
Returning Status on a .WAIT	#2

Monitor

Operational Note: IOPS 77 After Control Q	#1
Operational Note on Overprinting	#2
Problem in Restoring UIC's to DAT Slots on LOGOUT	#3
Patch to Support LA30 at 300 Baud	#4
Patch to Restore System Configuration on "LOGOUT"	#5
Teletype Handler .INIT Function Limitations	#6
Document Number Change Notice	#7
Documentation Error	#8
Typographical Error in Patch to PIP	#9

SOFTWARE DISPATCH

DOS/BOSS

November, 1973

Paper Tape Punch Handlers

Difference in End-of-File Code Between ADSS and DOS #1

Patch

Operation under DOS-15 #1

PIP

Note on Implicit Data Modes #1

Restriction on Diskpack to Diskpack Copies #2

Segmenting Files Under BOSS-15 #3

Patch to Transfer all Files in a 'C' Function #4

Patch to Correct Problem in Transferring Multiple Files
from Card Readers #5

Patch to Correct Problem with 'N' Function when 'Snn'
Switch Option is Used #6

Problem with 'C' Switch Option in a 'T' Function #7

System

Conversion from ADSS-15: Programs May Not Fit #1

Minimum and Optional Hardware for DOS-15 System #2

Programming Note #3

System Generator

Relative Positions of the Clock and Line Printer Skip IOT's #1

Update

Note on Program File Extensions #1

SOFTWARE DISPATCH

DOS/BOSS

November, 1973

Update (Continued)

Note on G Option and FREE Command	#2
Note on Error Conditions	#3
Why V10B and not V11A	#4
Patch to Correctly Read the EOF/EOM Record	#5

VT15 Graphics

Functional Description - Rotate (SRC)	#1
Functional Description - Circle (SRC)	#2

Writing Tablet Handler

Functional Description	#1
------------------------	----

BOSS-15 Software Review

Monitor

Patch to Correct Problems in Closing Run Time Files & MICLOG being Active on Exit from BOSS-15	#1
Patch to Correct Problem in Assigning Non-default File Names in \$CRT and \$ADD Procedure Files	#2

Procedure Files

Correction to FOR and ASM to Permit Usage of the Default File Name	#1
Correction to JOB Procedure File to Permit Usage of Default UIC	#2

SOFTWARE DISPATCH

DOS/BOSS

November, 1973

1.0 Introduction

The Software Dispatch is a cumulative report (updated monthly) which provides each subscriber with a quick reference library of:

1. Announcements of new software products.
2. Current software status - outstanding problems and problems with solution.

The name Software Dispatch was chosen in accordance with its definition.

"... a written message; particularly an official communication sent with speed."

With this in mind, it is our intent to assure the subscriber of timeliness and technical quality.

Comments and suggestions from our readers are welcome.

2.0 How to Use Your Software Dispatch

The Software Dispatch is intended to supplement your software and aid in its maintenance. Updates will be supplied monthly to subscribers.

Changes to relocatable/absolute files/programs will be based on the current version and edit number of the file/program. It is recommended that users make all the published patches. Users possessing source files are suggested to make the indicated source level changes and suitably update their Software System.

2.1 Introductory Section

This introductory material should be filed at the beginning of your notebook and will be referred to as chapter and paragraph numbers. To date, these are the chapters in the Introductory Section:

- 1.0 - Introduction
- 2.0 - How to Use Your Software Dispatch
- 3.0 - Software Manuals for DOS/BOSS

For example, if a new paragraph were to be inserted as the fifth paragraph of Chapter 1, the article would have a chapter and paragraph number of 1.5 (or section 1.5).

2.2 General format of the article

Each article is formatted so that you can easily recognize to what the article refers.

This is an overall example of the format. Each part will be explained in detail.

SOFTWARE DISPATCH		DATE
(A)	TITLE	
(B)	SUBTITLE	
(C)	PROBLEM: (C1) Functional Description	
(D)	DISPOSITION:	
	(E) CODING	

(A) Title

The title of articles pertaining to programs include the latest Version and/or Edit number (whichever applicable). Source level changes will always change the Edit number, e.g., Edit #052 to Edit #053. The Version number will be changed, if applicable, e.g., V6A to V7A. A change to core image system programs (via binary patches) will change the version number, e.g., V6A to V6B, and the Edit number remains the same. Changes to relocatable files will appear only in the form of source code changes.

(B) Subtitle

This brief statement gives the reader a hint about the content of the article. The subtitle is used in the Table of Contents for identifying the problem.

(C) Problem:

A paragraph or two is used to describe the problem in general terms. It may include examples, warning, etc.

The purpose of this paragraph is to make the user aware of an existing problem in the software and its documentation.

(C1) In some cases, the text of the article contains a functional description which may not have been included in the system software document.

(D) Disposition:

This is the section of the article which tells the reader the status of the problem. The disposition of the problem may be one of the following categories:

° No Disposition

An article just states the problem and will not have an answer. This is to inform you that we are aware of the problem, but at this time there is no fix available.

SOFTWARE DISPATCH

DOS/BOSS

November, 1973

° Solution

If there is a way to avoid the problem, or a patch to fix it, it is stated here.

In some articles you will find that the only solution given is "fixed in the next version".

(E) Coding

This block is used for filing purposes and is further expanded in section 2.3.

2.3 Filing

A system has been devised to help you file each article in its proper place. The key to this system is the block at the bottom of the page.

Below is a close-up view of the coding block for Systems Software.

Software Product (1)	Version (1A)	
Component (2)	Version (2A)	Edit # (2B)
Subprogram or Additional Information (2C)	Sequence # (3)	PAGE OF (3A)
New (4)	Replacement Article (5)	Original Date (5A)

Each month, you should take the update and insert the pages in your notebook according to the following instructions.

First, the article is filed by Software Product (1). In this case, all articles will be classified under the major heading.

Secondly, the Software Product is broken down by its components (2). See section 2.3.1 for the list of DOS/BOSS Components.

SOFTWARE DISPATCH

DOS/BOSS

November, 1973

Lastly, the article is referenced by sequence # (3). As an article is added to each component, it is assigned the next highest sequence number.

All other information in the coding block is to further clarify the article and not specifically for filing.

Explanation of all the other information included in the coding block follows:

- (1A) Version of the entire Software Product.
- (2A) Version number of components.
- (2B) Edit numbers.
- (2C) If more information is necessary to help the user, it will be inserted in this block.
- (3A) This block indicates how many pages the article has.
- (4) A new article is indicated by an "X" in this block. This article has not been published before.
- (5) An article which was previously published and is being published again for reasons of revision or correction is indicated by a number in this block.

The number in the block specifies the number of times the original article has been revised.

For example: the second revision of an article which originally appeared in June, 1973 would be indicated as follows:

New <input type="checkbox"/>	Replacement Article <input type="checkbox" value="2"/>	Original Date June, 1973
---------------------------------	---	-----------------------------

The customer will find the date of revision #2 in the upper right corner of the article.

- (5A) Original date of a revised article is placed here.

SOFTWARE DISPATCH

DOS/BOSS

November, 1973

2.3.1 COMPONENTS

A list of the components and program names for DOS/BOSS along with relevant comments is found below. The component names always appear in the coding block for filing purposes. The program names, used only if necessary, appear in the coding block under "additional information" and are not used for filing.

Articles concerning changes to manuals will be coded and filed along with changes to programs. For example, an article containing a binary patch to the CHAIN program could be followed by an article amending the CHAIN and EXECUTE manual. Changes to the monitor manuals and other general system documents will appear under the code MONITOR.

DOS-15:

<u>Components</u>	<u>Additional Information</u>	<u>Comment</u>
BOOTSTRAP	RFBOOT RPBOOT	RF Disk Bootstrap RP Disk Bootstrap
CARD READER HANDLERS	CD.DOS DOSBCD	Non-Batch Card Reader Handler Batch Card Reader Handler
CHAIN		
DDT		
DECTAPE HANDLERS	DTA. DTC. DTD. DTE. DTF.	
DISK HANDLERS	DKA. DKB. DKC. DKL. DPA. DPB. DPC. DPL.	RF Disk Handler RF Disk Handler RF Disk Handler RP Disk Handler RP Disk Handler RP Disk Handler

SOFTWARE DISPATCH

DOS/BOSS

November, 1973

COMPONENTS (Cont'd)

DOSSAV

System
save/restore program

DTCOPY

DUMP

EDITOR

EDITVP

EDITVT

EXECUTE

FOCAL

FOCAL
FNEW

FORTRAN

COMPILER
OTS

object time system
utility routines
relocatable file loader

LINKING LOADER

.LOAD

LINE PRINTER HANDLERS

LPA.09
LPA.15
LP.647

PDP-9 Line Printer Handler
PDP-15 Line Printer Handler
647 Line Printer Handler

LK35 KEYBOARD HANDLER

LKA.

MACRO-15

MACRO
CREF

cross reference program

MAGTAPE HANDLERS

MTA.
MTC.
MTF.

MONITOR

DOSNRM
RESMON
TELETYPE HANDLER

Non-Resident MONITOR
Resident Monitor

MTDUMP

PAPERTAPE PUNCH HANDLERS

PPA.
PPB.
PPC.

SOFTWARE DISPATCH

DOS/BOSS

November, 1973

COMPONENTS (Cont'd)

PAPERTAPE READER HANDLERS PRA.
PRB.

PATCH

PIP

QFILE

SRCCOM

SYSTEM

all system information that does not fall under any other component will appear here.

SYSTEM GENERATOR SGEN

SYSTEM LOADER .SYSLD system program loader

UPDATE

VP15 GRAPHICS VPA.
VPA.S
FORT
NUVAL
VECTOR

VT15 GRAPHICS VTA.
VTPRIM
LTPRPB
DYLDR
TRACK
ROTATE
CIRCLE

WRITING TABLET HANDLER VWA.

8TRAN

89TRAN

BOSS-15:

MONITOR B.PRE pre-processor
NRBOSS non-resident monitor
PROCEDURE FILES The additional information may contain any of the procedure files listed in the BOSS-15 USERS MANUAL.

SOFTWARE DISPATCH

DOS/BOSS

November, 1973

3.0 DOCUMENTATION FOR DOS-15 SYSTEM

A. Required Documentation

DOS USERS MANUAL	DEC-15-ODUMA-A-D
FORTRAN IV LANGUAGE MANUAL	DEC-15-GFWA-D
FORTRAN IV OPERATING ENVIRONMENT	DEC-15-GFZA-D
PIP DOS MONITOR UTILITY PROGRAM	DEC-15-YWZB-DN13
SGEN DOS UTILITY PROGRAM	DEC-15-YWZB-DN12
DOS KEYBOARD COMMAND GUIDE	DEC-15-NGKA-D
DOS SYSTEM MANUAL	DEC-15-ODFFA-A-D

B. Suggested Additional Manuals

PDP-15 MACRO-15 ASSEMBLER	DEC-15-AMZB-D
FOCAL PROGRAMMING MANUAL	DEC-15-KJZB-D
PDP-15 8-TRAN MANUAL	DEC-15-ENZA-D
PDP-15 DDT UTILITY PROGRAM	DEC-15-YWZA-DN1
PDP-15 CHAIN & EXECUTE UTILITY PROGRAM	DEC-15-YWZB-DN2
PDP-15 MTDUMP UTILITY PROGRAM	DEC-15-YWZB-DN4
PDP-15 PATCH UTILITY PROGRAM	DEC-15-YWZB-DN5
PDP-15 EDIT UTILITY PROGRAM	DEC-15-YWZB-DN6
PDP-15 UPDATE UTILITY PROGRAM	DEC-15-YWZB-DN7
PDP-15 LINKING LOADER UTILITY PROGRAM	DEC-15-YWZB-DN8
PDP-15 SRCCOM UTILITY PROGRAM	DEC-15-YWZB-DN11
VT15 GRAPHICS SYSTEM PROGRAMMING MANUAL	DEC-15-ZFSB-D
VP15A GRAPHICS SOFTWARE MANUAL	DEC-15-UXSB-D



SOFTWARE DISPATCH

DOS-15

PRE-1973

BOOTSTRAP

Programming Note Regarding .GET & .PUT MACROS

In DOS-15, .GET and .PUT MACRO's use the bootstrap for communication with the system device. On DECdisk systems, the bootstrap will ignore unit numbers in .PUT MACRO's. It will assume unit zero.

The source name of the RF DECdisk Bootstrap is RFB00T 011

The source name of the RP02 Bootstrap is RPBOOT 003

Software Product	Version	
DOS-15	V1A	
Component	Version	Edit #
Bootstrap	N/A	
Subprogram or Additional Information	Sequence #	PAGE
	1	1 OF 1
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date



SOFTWARE DISPATCH

DOS-15

PRE-1973

BOOTSTRAP

Programming Note on Special Bits Meaning in Reserved Word

There is an important transfer vector in the Bootstrap, located in word 17777 of the highest bank. The high order three bits of this word are reserved for the Monitor, and have the following meanings:

WORD	BIT	MEANING
17777	0	1=In batching mode 0=Not in batching mode
	1	1=\$JOB ASCII line or card just read by batch device 0=Last line or card not \$JOB
	2	1=Batch device is card reader 0=Batch device is paper tape reader

The system loader will refresh the Resident Monitor's patch area only on a bootstrap load or restart. This allows communication between two programs that require a new system configuration.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
Bootstrap		N/A	
Subprogram or Additional Information		Sequence #	PAGE
		2	1 OF 1
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	



SOFTWARE DISPATCH

DOS-15

PRE-1973

CD.DOS (EDIT #012) and DOSBCD (EDIT #003)

Handler for the CR15 Card Reader

The card reader handler (CD.DOS) has undergone the following modifications. It should be noted that none of these changes were implemented in the batch card reader handler (DOSBCD).

1. Defining the parameter "CR15=0" for assembly obtains the CR15 version of the card reader handler. The CR15 is a card reader controller which operates on data channel and can handle a variety of card readers up to the 1000 card per minute model.
2. The card reader handlers will recognize two different punches for end-of-file (EOF) cards-
 - a. All rows punched in column one (ADSS-15 usage)
 - b. The 12, 11, 0, 1 multi-punch in column one
3. The card reader now returns an EOF code (1005) instead of an EOM code (1006).
4. When a hopper empty, stacker full, or reader not ready condition arises, the following expanded message follows the IOPS4:

'CD NOT READY'

5. If a card is encountered with an illegal card punch the message 'IOPS4 CD-ILLEGAL PUNCH' is printed. At this point the user can punch the card correctly and continue by typing CTRL R.

Restrictions:

DOSBCD 003 may not be used as a batch device handler for the CR15 device. It may, however, be used as an input device handler.

Software Product	Version	
DOS-15	V1A	
Component	Version	Edit #
CARD READER HANDLERS	N/A	
Subprogram or Additional Information	Sequence #	PAGE
CDB.	1	1 OF 1
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date



SOFTWARE DISPATCH

DOS-15

PRE-1973

CD.DOS (EDIT #013)

Problems when conditionalized for the CR15 card reader

1. Problem: The handler did not handle any error conditions properly. On errors like pick failure, block missed, data missed, motion error and photo error the handler moved (offset) the card to the reader station and exited without issuing a message or a .READ MACRO.

As a result of the above the system would hang up.

Correction: Since all errors are potentially recoverable the new version of the handler issues an expanded error message "IOPS4 ERR,CHK-CD, RLD-CD" permitting continuation of operation by reloading a fresh image of the bad card.

The user has the option of aborting the .READ operation by typing ↑P/↑C.

2. Problem: The handler temporarily returned an EOF (in the line buffer header word pair (HWP)) on exit from a .READ MACRO. When the interrupt was received the HWP was set to the appropriate value.

Although this does not affect the user since he cannot process the data being read until it is complete, it is logically erroneous and time-wise wasteful.

Correction: Do not alter the HWP.

The following SRC level changes to CD.DOS edit #012, correct these problems.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
CARD READER HANDLERS		N/A	13
Subprogram or Additional Information		Sequence #	PAGE
CDB.		2	1 OF 3
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Problems when conditionalized for the CR15 card reader (Cont'd)

PAGE 7 CD.DOS 013 .READ

```

204 .TITLE .READ
205 /INITIATE READ TO CARD READER.
206 00100 R 100214 R CDREAD JMS IOUWAY /ARE WE DONE YET
207 00101 R 767000 A LAW 7000 /YES, PICK UP CAL

224 00117 R 440755 R ISZ CDARGP /BUMP TO RETURN
225 00120 R 200033 R LAC CDRBMP+1 /SET RETU
226 00121 R 040143 R DAC CDRRET /FROM REA
227 .IFDEF NOTGDI
228 CURRTN CREF /EOF BUTTON OR HO
    
```

PAGE 17 CD.DOS 013 CDB. CARD READER INTERRUPT HANDLING SECTION

```

603 .TITLE CDB. CARD READER INTERRUPT
604 /CARD READER INTERRUPT SECTION.
605 00460 R 741000 A CDRINT SKP /CONTROL COMES HE

647 00475 R 040772 R DAC CDSTAT /AND SAVE
648 00476 R 501020 R AND (400 /TROUBLE BIT
649 00477 R 751200 A SNA!CLA /SKIP ON TRO
650 00500 R 600537 R JMP CROONE /NO ERRORS
651 00501 R 200772 R LAC CDSTAT /TROUBLE???????
652 00502 R 501021 R AND (037000 /WHAT TROUBLE?
653 00503 R 541004 R SAD (2000 /HOPPER EMPTY?
654 00504 R 600537 R JMP CRDONE /YES, DONE RETURN
655 00505 R 140760 R DZM CDIOSW /TO ENABLE CTL P
    
```

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
CARD READER HANDLERS		N/A	13
Subprogram or Additional Information		Sequence #	PAGE
CDB		2	2 OF 3
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Problems when conditionalized for the CR15 card reader (Cont'd)

PAGE 18 CD.DOS 013 CDB. CARD READER INTERRUPT HANDLING SECTION

656	00506	R	760020	A	LAW 20	/CLEAR INTERRUPT
657	00507	R	706704	A	CRLC	
658	00510	R	760004	A	LAW 4	/OR READER; PRIN
659	00511	R	121012	R	JMS* (EXERRS	/IOPS 4 MESSAGE
660	00512	R	600522	R	JMP CDRST	/TRY AGAIN, REST
661	00513	R	777772	A	LAW -6	
662	00514	R	052222	A	.SIXBT /ERR CHK-CD,	RLD-CD/
	00515	R	400310	A		
	00516	R	135503	A		
	00517	R	045440	A		
	00520	R	221404	A		
	00521	R	550304	A		
663	00522	R	201022	R	CDRST LAC (JMP CDIRET	/RESTORE RE
664	00523	R	040143	R	DAC CDRRET	/ADDRESS
665	00524	R	600123	R	JMP CDOK+1	/RESTART READ
666					.ENDC	
667					/-----	
668	00525	R	060043	R	DAC* CDIPTR	/INSERT THIS COL
669	00526	R	440043	R	ISZ CDIPTR	/BUMP BUFFER PO1
670					.IFDEF NOTGDI	

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
CARD READER HANDLERS		N/A	13
Subprogram or Additional Information		Sequence #	PAGE
CDB.		2	3 OF 3
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

PRE-1973

CHAIN V7A (EDIT #148)

Programming Notes

CHAIN will accept library indicators (#) on internal and external link components. The name given must correspond to the GLOBAL name of the routine desired in the library. Also note that the .IODEV Pseudo-op should come after the .GLOBL Pseudo-op so that CHAIN will not skip over the .IODEV information when doing a library search.

CHAIN will accept .IODEV information from -18 thru +71 decimal. This is so that it can accommodate the 77 octal .DAT slots allowed DOS-15 by the system.

CHAIN will do a .USER for the "PAG" or "BNK" UIC on .UFDT - 1 if the "PGR" or "BKR" option respectively is given. This is so the correct system library will be searched for the relocation mode in effect.

Since I/O handlers are in the "IOS" UFD as separate files, the user must transfer to his UFD, using PIP, any handlers he may want to include in his overlay system. Also, the user must include the handler's file name (global name) in the link description command string.

CHAIN calculates the number of 400(8) word blocks needed to store the overlay system, by links, as a core image. This information is stored in the environment indicator in bits 0 through 11 as a right-justified octal number. This total does not include the link table (link 377777) or the resident code (link 0).

There is an option in CHAIN which allows the user to restrict COMMON areas to bank boundaries. This is useful to the VT15 user who builds display files in COMMON, since the VT15 cannot cross bank boundaries directly (i.e., 13-bit addressing). There are two forms of the option and the giving of one will cancel out the other form if it was given previously.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
CHAIN		V7A	148
Subprogram or Additional Information		Sequence #	PAGE
		1	1 OF 2
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Programming Notes (Cont'd)

"VTC" option without names restricts all common areas to bank boundaries. The "VTC" option is delimited by being the first option in the command string or by a comma on the left, and by a comma or altmode on the right.

"VTC/NAM1,NAM2,...NAM3/" option with names restricts to bank boundaries only those COMMON areas named (note: blank common is .XX). More than one VTC option with names may be given in the command string and all names specified will be restricted. The option is delimited by being the first option in the command string or by a comma on the left, and a slash on the right. The name field within the option is delimited by a slash right after the "VTC" and the slash that terminates the option. Names in the list are separated by commas.

Notes:

The "VTC" option will not restrict common areas declared in BLOCK DATA SUBPROGRAMS.

The common area will be restricted to bank boundaries even if CHAIN is running in page relocation mode.

CHAIN ignores the Linking Loader code '33'.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
CHAIN		V7A	148
Subprogram or Additional Information		Sequence #	PAGE
		1	2 OF 2
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

June, 1973

CHAIN & EXECUTE (DEC-15-YWZB-DN2)

Clarification of obscure points

Note on operation of CHAIN:

1. Routines/subroutines declared as part of the resident code by using the library indicator (#) in the command string are entered into a dummy global symbol table. Hence, it is necessary for a ".GLOBL name" identical to the name accompanying the "#" to be present within the routine to be called. An identical file name is not sufficient; in fact, file names are ignored when searching for library indicator (#) routines. In the absence of this declaration, the error message "UNRESOLVED GLOBAL" will result.
2. CHAIN scans the user library (.LIBR5) before scanning the system library (.LIBR) to load library routines and to resolve unresolved globals.
3. CHAIN V10A (supplied with DOS-15 V3A forthcoming update release) will resolve globals in a manner similar to the LINKING LOADER.

Restrictions in building an overlay structure:

Pages 12 and 13 of the CHAIN & EXECUTE manual define a set of rules that govern the building of an overlay structure through the definition of links and structures.

There are a few overlay structures that cannot be defined within the framework of these rules. Any attempt to define one of these overlay structures will result in the printout of any one of the appropriate error messages.


An example of one such overlay structure that cannot be built follows.

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
CHAIN & EXECUTE			
Subprogram or Additional Information		Sequence #	PAGE
DOCUMENTATION CORRECTION		1	1 OF 3
New	Replacement Article	Original Date	
<input type="checkbox"/>	<input type="checkbox"/> 1	May, 1973	

SOFTWARE DISPATCH

DOS-15


June, 1973



high core



low core



equivalent
tree
structure

The following attempt to define this overlay structure will cause the error message indicated to be printed out.


```
>LA=A
>LB=B,BA
>LC=C,CA
>BA:BB:BC
↑COMPONENT NAME USED AS LINK NAME ---BA
```

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
CHAIN & EXECUTE			
Subprogram or Additional Information		Sequence #	PAGE
DOCUMENTATION CORRECTION		1	2 OF 3
New	Replacement Article	Original Date	
<input type="checkbox"/>	<input type="checkbox"/> 1	May, 1973	

SOFTWARE DISPATCH

DOS-15

June, 1973




It is possible to define the above overlay structure by the definitions:

- >A:B,BA
- >B:C,CA
- >CA:CB
- >BA:BB:BC

In general there can be only one link in an overlay structure whose link components, if any, are allocated contiguously in core (as in link "C, CA"). Hence, there will be holes in core if an overlay structure like the one above is built.

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
CHAIN & EXECUTE			
Subprogram or Additional Information		Sequence #	PAGE
DOCUMENTATION CORRECTION		1	3 OF 3
New	Replacement Article	Original Date	
<input type="checkbox"/>	<input type="checkbox"/> 1	May, 1973	



SOFTWARE DISPATCH

DOS-15

PRE-1973

CHECKOUT PACKAGE

Functional Description

The following is a description of the Software Checkout Package. The description and the paper tape are distributed as part of the system. See DOSSAV Operating Instructions for installing the system.

1.0 INTRODUCTION

The purpose of the checkout package is to show that the system has been properly installed onto DECdisk or Disk Pack. It does so by briefly testing all the basic pieces of the system. The following is a list of programs tested:

1. Resident and Nonresident Monitors
2. PIP
3. FORTRAN Compiler and Object Time System
4. Macro Assembler
5. Linking Loader and System Loader
6. Chain and Execute programs
7. System Device Handler (DECdisk or Disk Pack)
8. Paper Tape Reader Handler
9. Teleprinter Handler
10. Batching Mode System Commands
11. DOSSAV system SAVE/RESTORE program

2.0 IDENTIFICATION

The batch paper tapes for the Checkout Package are identified as follows:

RF.CHK	DEC-15-CIDA-PA	(for the RF15 DECdisk System)
RP.CHK	DEC-15-CTAA-PA	(for the RP02 Disk Pack System)

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
<u>CHECKOUT PACKAGE</u>		N/A	N/A
Subprogram or Additional Information		Sequence #	PAGE
		1	1 OF 5
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	

SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Description (Cont'd)

3.0 CHECKOUT PACKAGE RESULTS

The result of the FORTRAN Object Time System (shortly after the GLOAD Command) should be:

$-\emptyset.1235E+\emptyset3$

Also, the result of the Chain and Execute programs should be:

$-\emptyset.1234E+\emptyset5$

4.0 CHECKOUT PACKAGE OPERATION

The following are the procedures for an RF DECdisk system having two (2) platters or an RP02 system.

Take the ASCII paper tape labeled 'RF.CHK' (or RP.CHK, if Disk Pack system), and place it in the high speed paper tape reader. Then type:

BATCH PR)

The Batch commands will then run the checkout package to completion and will so indicate on the teleprinter, before leaving Batch Mode.

4.1 The following are the procedures for an RF DECdisk system having only one (1) platter and DECTAPE:

1. Load the System Software (following the DOSSAV Operating Instructions).
2. When the system monitor announces itself, type in the current date:

Software Product		Version	
DOS-15		v1A	
Component		Version	Edit #
CHECKOUT PACKAGE		N/A	N/A
Subprogram or Additional Information		Sequence #	PAGE
		1	2 OF 5
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Description (Cont'd)

Example:

11/29/71

3. Mount a scratch tape on DT Unit #1 and write enable.
4. Type the underlined commands which follow:

\$LOGIN PER ↵

\$PIP ↵

> C DT1← DK ↵

> N DK ↵

> ↑C

5. Now again read in the RF Bootstrap, and enter the date which the monitor requests.
6. Take the ASCII paper tape labeled RF.CHK and place it in the high speed papertape reader, then type:

\$ BATCH PR ↵

The Batch Commands will then run on the Checkout Package to completion and will so indicate on the teleprinter - before leaving Batch Mode.

4.2 SPECIAL PROCEDURES FOR MAGTAPE USERS:

The following are the procedures for an RF DECdisk system having only one (1) platter and MAGTAPE:

1. Load the System Software (following the DOSSAV Operating Instructions).

Software Product	Version	
DOS-15	V1A	
Component	Version	Edit #
CHECKOUT PACKAGE	N/A	N/A
Subprogram or Additional Information	Sequence #	PAGE
	1	3 OF 5
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date

SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Description (Cont'd)

2. When the system monitor announces itself, type in the current date: ex: 11/29/71
3. Mount a scratch magtape on MAGTAPE UNIT #1 (have it write enabled)
4. Type the underlined commands which follow:

\$ LOGIN PER)

\$ A MTF 11)

\$ PIP)

> T MT1 (A)+DK DOSBCD 003)

> T MT1 (A)+DK CD.DOS 012)

> T MT1 (A)+DK FNEW 004)

> T MT1 (A)+DK LPA.15 042)

> T MT1 (B)+DK DYLDL BIN)

> T MT1 (B)+DK TRACK BIN)

> T MT1 (B)+DK VTPRIM BIN)

> T MT1 (B)+DK ROTATE BIN)

> T MT1 (B)+DK NUVAL BIN)

> T MT1 (B)+DK FORT BIN)

> T MT1 (B)+DK VECTOR BIN)

> T MT1 (B)+DK CIRCLE BIN)

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
CHECKOUT PACKAGE		N/A	N/A
Subprogram or Additional Information		Sequence #	PAGE
		1	4 OF 5
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

functional Description (Cont'd)

> T MT1 (B) +DK LPA.Ø9 BIN

> T MT1 (B) +DK F4X9 BIN

> T MT1 (B) +DK VPA.S BIN

> T MT1 (B) +DK LP.647 BIN

> T MT1 (B) +DK I.TORPB BIN

> N DK

> ↑C

5. Now again read in the RF Bootstrap, and enter the date which the monitor requests.
6. Take the ASCII paper tape labeled RF.CHK and place it in the high speed papertape reader, then type:

\$BATCH PR

The Batch Commands will then run the Checkout Package to completion and will so indicate on the teleprinter - before leaving Batch Mode.

Software Product DOS-15		Version V1A	
Component CHECKOUT PACKAGE		Version N/A	Edit # N/A
Subprogram or Additional Information		Sequence # 1	PAGE 5 OF 5
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	



SOFTWARE DISPATCH

DOS-15

PRE-1973

DDT V9A (EDIT #010)

Programming Notes

DDT identifies itself as DDT Vnn for page mode loads, and BDDT Vnn for bank mode loads.

DDT allows breakpoints on floating point instructions.

After nonrecoverable IOPS errors, DDT awaits a CTRL T before continuing.

DDT uses the tabbing mechanism in the teleprinter handler, instead of multiple spaces, for output. This makes DDT smaller and when using Model 35 teletypes faster on tabbing output.

The routine to print octal numbers has been shortened, and a problem with zero suppression has been corrected.

DDT had a problem in setting .SCOM+2 incorrectly, so that about 500 registers were unusable. This problem has been fixed in version V9A.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
DDT		V9A	10
Subprogram or Additional Information		Sequence #	PAGE
		1	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

Pre-1973

DTA. (EDIT #020)

Functional Change

The DTA handler has been modified to use dynamic buffer allocation. The new size is approximately 2750g--this is smaller than the old DTB version. For this reason, DTB has been deleted from the system. DTA. still has only three file capacity. If a user attempts to use more than three files at once on DECTape, an IOPS 17 error will result.

The last block of a file on DECTape has a forward data link of 777777. If the user tries to read past this block DTA will return the end-of-file sequence (001005,776773) in the user's buffer. Subsequent .READ's will continue to pass back the same two words. This corrects a problem that occurred in PIP when reading in dump mode and when the 001005, 776773 sequence was part of the data being transferred, with still more data following it.

NOTE:

None of the above changes has been made to the DTC., DTD., DTE., or DTF., DECTape Handlers.

Software Product	Version	
DOS-15	V1A	
Component	Version	Edit #
DECTAPE HANDLERS	N/A	20
Subprogram or Additional Information	Sequence #	PAGE
DTA.	1	1 OF 1
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date



SOFTWARE DISPATCH

DOS-15

PRE-1973

DTA. (EDIT #021)

Source Change to prevent .WAIT X from getting a buffer

Problem:

In Edit #020 of the DTA. handler, when a .WAIT X is issued after a .CLOSE X the handler gets a buffer. As a result when there are "B" buffers in a system and when B+1 files are accessed sequentially on B+1 DAT slots (B assigned to DT's and 1 assigned to some other device) the message -

"IOPS 55" (NO BUFFERS AVAILABLE)

is printed.

If all the B+1 slots are assigned to DT's the message

"IOPS 17" (TOO MANY FILES FOR HANDLER)

results.

Solution:

The above restriction is removed by preventing .WAIT from getting a buffer.

Below are the changes in the source code for DTA 020.

Software Product DOS-15	Version V2A	
Component DECTAPE HANDLERS	Version N/A	Edit # 21
Subprogram or Additional Information DTA.	Sequence # 2	PAGE 1 OF 2
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date

SOFTWARE DISPATCH

DOS-15

PRE-1973

Source Change to prevent .WAIT X from getting a buffer (Cont'd)

<u>LOC</u>	<u>OCTAL</u>	<u>LABEL</u>	<u>INST</u>	<u>COMMENT</u>
Ø	Ø42644	DTA.	DAC CALP	/CAL POINTER
			-	
15	Ø42646		DAC TEMP2	/T STORE DATA MODE OR
				/SUBFUNCTION
16	222642		LAC* ARGP	/CHECK IF
17	5Ø27ØØ		AND (77	/FUN. IS
2Ø	5427Ø1		SAD (12	/.WAIT/.WAITR?
21	6ØØ177		JMP DISPCH	/YES GO TO DISPCH,
				/DO NOT GET BUFFER
22	222644		LAC* CALP	/NO, GET DAT SLOT
				/(9-17)
			-	
			-	

This problem will be corrected in version DTA Edit #Ø21.

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
DECTAPE HANDLERS		N/A	21
Subprogram or Additional Information		Sequence #	PAGE
DTA.		2	2 OF 2
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

Nov. 1972

DECTAPE HANDLERS

Support of .TRAN Function on PDP-8/10/11 Tapes

The DECTape handlers in the system (except for DTF.) can be utilized to transfer data from PDP-8/10/11 using the .TRAN function.

In order to realize the above a minor source modification is needed to the handlers that support the .TRAN function. The instruction,

AND (7777 /clear possible erroneous data

must be inserted after the location DTSRCK+2, i.e., after the instruction,

LAC DTBCA

in DTA. , DTD. & DTE.

This is necessary because these tapes have 12 bit block numbers with erroneous data in the most significant bits.

Note that since the file structure on these tapes are different from the DOS-15 file structure, only the .TRAN function will work.

This information is provided for user's convenience only and should not be misconstrued as a feature that will be supported by DEC.

Software Product	Version	
DOS-15	V2A	
Component	Version	Edit #
DECTAPE HANDLERS	N/A	
Subprogram or Additional Information	Sequence #	PAGE
DTA. , DTD. , DTE.	3	1 OF 1
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date



SOFTWARE DISPATCH

DOS-15

PRE-1973

DISK HANDLERS

Programming Note on Use of .USER Macro

The Disk Handlers retain the UIC from the .UFDT in the Busy Table entry for each particular .DAT slot. Thus, changes made in the .UFDT via .USER macros will not become effective until a new Busy Table is established for the affected .UFDT slots.

Since the I/O macros to the disk handlers may or may not establish a new Busy Table entry, depending on a variety of conditions, this article will only give one example of incorrect usage, and then give a recommended procedure.

The following sequence:

```
.USER 1,ABC  
  
.INIT 1  
  
.USER 1,CDE  
  
.SEEK 1,FILE
```

will cause a .SEEK for FILE under the UFD called ABC. If FILE is really under the UFD called CDE, the programmer should have written

```
.USER 1,CDE  
  
.INIT 1  
  
.SEEK 1,FILE
```

Programmers should ensure that all .USER macros are immediately preceded by any one of the following macros:

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
DISK HANDLERS		N/A	
Subprogram or Additional Information		Sequence #	PAGE
		1	1 OF 2
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	

SOFTWARE DISPATCH

DOS-15

PRE-1973

Programming Note on Use of .USER Macro (Cont'd)

.CLOSE

.RENAM

.MTAPE (rewind)

.DELETE

or immediately followed by a .INIT.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
DISK HANDLERS		N/A	
Subprogram or Additional Information		Sequence #	PAGE
		1	2 OF 2
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

DOSSAV V2A (Edit #043)

Operating Instructions

DOSSAV is the system save/restore program. It resides on a paper tape, which must be HRM loaded at 37720 (restart at 34500).

It saves and restores to/from DECdisk, Disk Packs, DECTape and Magtape. A DECdisk system can be saved on and restored from DECTape, Magtape and Disk Pack. A Disk Pack system can use DECTape and Magtape.

Once loaded, it asks for all necessary information, such as input and output devices, unit numbers and, in the case of Magtape - parity and density.

GENERAL INSTRUCTION:

The user must type Carriage Return after all entries, including the character typed to restart after errors.

A. Restoring Systems

The following examples illustrate how to put the systems distributed by Digital on DECTape or Magtape onto a DECdisk or Disk Pack. The user responses are underlined.

1. To restore a DECdisk system from DECTape (on Unit 1)

```
DOSSAV V2A
INPUT DEVICE? DT
UNIT NO? 1
OUTPUT DEVICE? DK
DATE CREATED: 28-SEP-71
TAPE DONE. MOUNT ANOTHER
```

At this point, mount tape 2 and type any character on the keyboard followed by a Carriage Return.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
DOSSAV		V2A	43
Subprogram or Additional Information		Sequence #	PAGE
		1	1 OF 6
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	

SOFTWARE DISPATCH

DOS-15

PRE-1973

Operating Instructions (Cont'd)

NOTE: If DK is typed, no unit # is requested.

II. To restore a DECdisk system from Magtape (on Unit 0)

DOSSAV V2A
INPUT DEVICE? MT
UNIT NO? 0
TRACK (7 OR 9)? 7
DENSITY (2,5,8)? 8
PARITY (E OR O)? O
OUTPUT DEVICE: DK
DATE CREATED: 28-SEP-71

NOTE: ALL SYSTEM RESTORE MAGTAPES DISTRIBUTED BY DIGITAL
ARE 800 BPI, ODD PARITY.

III. To restore a Disk Pack system from DECTape (on Unit 1)

DOSSAV V2A
INPUT DEVICE? DT
UNIT NO? 1
OUTPUT DEVICE? DP
UNIT NO? 0
DATE CREATED: 28-SEP-71
TAPE DONE, MOUNT ANOTHER

At this point, mount Tape
2 and type any character
on the teleprinter follow-
ed by a Carriage Return.

Software Product	Version	
DOS-15	V1A	
Component	Version	Edit #
DOSSAV	V2A	43
Subprogram or Additional Information	Sequence #	PAGE
	1	2 OF 6
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date

SOFTWARE DISPATCH

DOS-15

PRE-1973

Operating Instructions (Cont'd)

IV. To restore a Disk Pack

DOSSAV V2A
INPUT DEVICE? MT)
UNIT NO? 1)
TRACK (7 OR 9)? 7)
DENSITY (2,5,8)? 8)
PARITY (E OR O)? O)
OUTPUT DEVICE? DP)
UNIT NO? Ø)
DATE CREATED: 28-SEP-71

It is possible to restore a software system to the DECdisk which was created for a machine smaller (different # of DECdisk platters) than the one being restored to. DOSSAV does all the necessary adjustments of the SAT's¹. Therefore, the restore tapes issued by Digital for a 1 platter system can be restored to any system. Note that this should only be done with the Master tape(s), which have block 1775_g free. That block may be needed during the restore for 5 or more DECdisk platters. Note that it is not possible to restore a software system which is larger than the hardware. (e.g., no restore of a 3-platter to one-platter configuration.)

B. Saving Systems

Once the user has tailored the system to his specific configuration, he will want to save that system for future restorations. To do that, simply reverse the procedure above. To illustrate, consider example 1 above and the changes necessary to it to create a restore tape.

To save a DECdisk system to DECTape (on Unit 1):

¹SAT's: Storage Allocation Tables - i.e., bit maps.

Software Product	Version	
DOS-15	V1A	
Component	Version	Edit #
DOSSAV	V2A	43
Subprogram or Additional Information	Sequence #	PAGE
	1	3 OF 6
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date

SOFTWARE DISPATCH

DOS-15

PRE-1973

Operating Instruction (Cont'd)

DOSSAV V2A
INPUT DEVICE? DK
OUTPUT DEVICE? DT
UNIT NO.? 1
TAPE DONE. MOUNT ANOTHER

At this point, mount another tape and type any character on the keyboard followed by a Carriage Return.

Note that DOSSAV allows for as many DECTapes and Magtapes as are necessary to hold the system.

C. Error Conditions and Messages

Recoverable errors during command string decoding: If a question is answered incorrectly, DOSSAV outputs an appropriate error message and then repeats the question. These error messages are:

ILLEGAL DEVICE	An illegal device mnemonic was typed (something other than DP, DK, DT and MT) or an illegal combination of devices was typed (i.e., input = DT and output = MT).
BAD TRACK	Something other than 7 or 9 was typed.
BAD DENSITY	Something other than 2(200) , 5(556) or 8(800) was typed.

Software Product DOS-15	Version V1A	
Component DOSSAV	Version V2A	Edit # 43
Subprogram or Additional Information	Sequence # 1	PAGE 4 OF 6
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date

SOFTWARE DISPATCH

DOS-15

PRE-1973

Operating Instructions (Cont'd)

BAD PARITY

Something other than E(even) or O(odd) was typed.

Recoverable errors during operation: If it is possible to recover from an error, DOSSAV will attempt to do it. The error message will be output to the console. After the problem has been corrected, any character on the keyboard followed by a Carriage Return will resume operation.

TAPE NOT READY

The DECTape or Magtape unit is off line or not write enabled.

DISK NOT READY

DECdisk is write locked.

DISK PACK NOT READY

The disk pack unit is not ready.

Unrecoverable errors¹: Primarily hardware errors, from which DOSSAV cannot recover. After the error message has been output, DOSSAV restarts.

DECTAPE ERROR

MAGTAPE ERROR

DISK ERROR

DISK PACK ERROR

ATTEMPT TO RESTORE
SYSTEM TO WRONG DISK

To protect users who have access to both a DECdisk and a disk pack and who may have several sets of restore tapes, all restore tapes are created with the mnemonic of the disk type in the first SAT. DOSSAV then checks this code against the output device code. If they differ, this message is output.

¹DOSSAV retries five times on a parity error before issuing an unrecoverable error message.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
DOSSAV		V2A	43
Subprogram or Additional Information		Sequence #	PAGE
		1	5 OF 6
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Operating Instructions (Cont'd)

BLK 1775 OCCUPIED. NO 2ND SAT CREATED

A DECdisk system created for 4 or fewer platters is restored to a machine with 5 or more platters and block 1775 is already used. Therefore, no second SAT is created. A Master Tape was not used to make the restore.

D. Tape Structure

The restore tapes are structured as follows: The first SAT of the system is the first block put on the tape. This SAT, which is never restored to the disk, has 2 words modified: word 2 contains the creation date (taken from .SCOM+47) and word 376 contains the device mnemonic (.SIXBT, right justified). All the occupied blocks referenced by this SAT are then put sequentially on the tape. The second SAT, if there is one, is then put on, and so on. This structure enables use of Magtape, which is a sequential only device.

E. DOSSAV Restrictions

1. It is not possible to save or restore Magtapes with even parity.
2. DOSSAV fails when two DECTapes are on line with the same unit number. It is necessary to restart under such circumstances.
3. Error checking and recovery is minimal.

Software Product	Version	
DOS-15	V1A	
Component	Version	Edit #
DOSSAV	V2A	43
Subprogram or Additional Information	Sequence #	PAGE
	1	6 OF 6
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date

SOFTWARE DISPATCH

DOS-15

Pre-1973

DUMP V9A (EDIT #009)

Information on .DAT slot Assignments

The command string will be output onto whatever device is assigned to .DAT -12.

If .DAT -14 is assigned to any device other than DECTape, Disk Pack or DECdisk, DUMP will print the following message:

.DAT -14 IS NOT ASSIGNED TO DISK OR DECTAPE
and then DUMP will exit to the Nonresident Monitor.

If .DAT -12 is assigned to a mass storage device, DUMP will not require an ALT MODE after an ALL command in order to create a file memory dump, called "MEMORY└DMP".

DUMP V9A will output only one form feed, instead of two, when the line printer is assigned to .DAT -12.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
DUMP		V9A	9
Subprogram or Additional Information		Sequence #	PAGE
		1	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

PRE-1973

DUMP V9A (Edit #009)

Some Information on QAREA's

DUMP will check the device assigned to .DAT -14, in order to determine the first block of the QAREA. If DECTape, the first block is always 1011. If Disk Pack, the first block is always 117030. The QAREA on DECdisk will be in different positions (space allocated during system generation), depending on the contents of .SCOM+66.

In the special case when the system device is Disk Pack, and .DAT -14 is assigned to a DECdisk, DUMP will print the following whenever the user attempts to dump the QAREA.

TYPE 1ST BLOCK # OF QAREA

In such a case, the user should type:

NNNN#<CR> or ALT MODE

and then repeat the ALL command. This special case is made because .SCOM+66 contains Disk Pack information.

If the user wishes to dump a QAREA that has a size different from the core size current to the system, he should type:

>ALL_(nn)<CR> or ALT MODE

where nn may be 8, 12, 16, 20, 24, 28 or 32 (The space after the ALL and the right parentheses are optional.)

Note:

The first block number and size of the CTRL Q area can be determined by listing SYSBLK with PIP:

L←TT DK (L)

Software Product	Version	
DOS-15	V1A	
Component	Version	Edit #
DUMP	V9A	9
Subprogram or Additional Information	Sequence #	PAGE
	2	1 OF 1
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date



SOFTWARE DISPATCH

DOS-15

PRE-1973

DUMP V9B (EDIT #009)

Patch to correct problem with selective dumps

PROBLEM:

DUMP V9A outputs incorrect information on selective dumps.

SOLUTION:

Make the following binary corrections to DUMP using the PATCH program.

<u>LOCATION</u>	<u>OLD CONTENTS</u>	<u>NEW CONTENTS</u>	<u>NEW SYMBOLIC</u>	<u>COMMENTS</u>
16256	217406	617472	JMP PATCH	/Patch area
17472	-	116034	JMS DEVICE	/Device check
17473	-	217406	LAC (-1)	/Restore inst.
17474	-	616257	JMP BACK	/Return
17224	106400	206400		/V9B

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
DUMP		V9B	9
Subprogram or Additional Information		Sequence #	PAGE
		3	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

PRE-1973

DUMP V9C (EDIT #009)

Patch to correct looping problem

PROBLEM:

DUMP V9B gets into an endless loop on the command "TYPE
1ST BLOCK OF ↑QAREA".

SOLUTION:

Using PATCH, make the following binary corrections to DUMP.

<u>LOCATION</u>	<u>OLD CONTENTS</u>	<u>NEW CONTENTS</u>	<u>NEW SYMBOLIC</u>
16123	615516	617475	JMP PATCH AREA
17475	-	217402	LAC (NOP
17476	-	055735	DAC CONTAL
17477	-	615516	JMP TR6
17224	206400	306400	V9C

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
DUMP		V9C	9
Subprogram or Additional Information		Sequence #	PAGE
		4	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

December, 1972

DUMP V9C (EDIT #009)

DUMP described in DOS Keyboard Command Guide

There is no utility manual for the DUMP utility program. This information is instead included as a Chapter in the DOS Keyboard Command Guide (DEC-15-NGKA-D).

Software Product	Version	
DOS-15	V1A	
Component	Version	Edit #
DUMP	V9C	9
Subprogram or Additional Information	Sequence #	PAGE
DOCUMENTATION	5	1 OF 1
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date



SOFTWARE DISPATCH

DOS-15

PRE-1973

FNEW (EDIT #004)

The Random Number Generator

The DOS version of FOCAL has a random number generator (FRND) included in FNEW (user-defined FOCAL functions). This routine is an improvement over the FRAN function in FOCAL.

FRND generates real, floating point numbers in the range of $-1.\emptyset$ less than or equal N less than or equal $+1.\emptyset$. The function can be called in the following ways.

FRND() --- Generate a random number based upon the last number generated.¹

FRND(\emptyset) --- Same as above.¹

FRND(X) --- Start a new sequence of random numbers based on the value of X. FRND will always generate the same number for the same value of X. X can be any valid arithmetic expression.

¹If this is the first call for the generator, FRND initializes itself. Under the standard output format of FOCAL, this produces a value of $1.\emptyset\emptyset\emptyset\emptyset$.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
FOCAL		N/A	4
Subprogram or Additional Information		Sequence #	PAGE
FNEW		1	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

MARCH 1973

FORTRAN, Object Time FORMAT Specification

Usage restriction and precaution

PROBLEM:

Section 6.1.3 of the FORTRAN IV Language Manual (DEC-15-GFWA-D) describes the usage of object time FORMAT specifications. It is not allowed, however, to use the name of an array that appears in a SUBROUTINE statement parameter list as an array name that is referenced by an I/O statement. That is, in the following program, the construction is correct.

```
          DIMENSION IBUF(10),FORM(10)
          DATA FORM(1) /5H(4I10/
          DATA FORM(2) /5H      /
10      DO 10 I = 1,10
          IBUF(I) = I
          NSZ=4
          WRITE (6,FORM) (IBUF(I),I=1,NSZ)
          CALL PRINT (IBUF,NSZ,FORM)
          PAUSE
          END
```

The first four elements of IBUF will be printed according to the format specified in the array FORM. If this is attempted in the subroutine PRINT, shown below, an OTS 12 will occur.

```
          SUBROUTINE PRINT (IBUF,NSZ,FORM)
          DIMENSION IBUF(1), FORM(10)
          WRITE (6,3) (FORM(I),I=1,10)
3      FORMAT(1X,10A5)
          WRITE (6,FORM) (IBUF(I),I=1,NSZ)
          RETURN
          END
```

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
FORTRAN		N/A	N/A
Subprogram or Additional Information		Sequence #	PAGE
		1	1 OF 2
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

MARCH 1973

Usage restriction and precaution (Cont'd)

RESTRICTION AND PRECAUTION:

To avoid this problem, it would be necessary to create some array in PRINT and to copy FORM into it. The former array could then be specified in the WRITE statement. Actually, the difficulty described here should be flagged as an error when compiling. The restriction will be relieved in the next release of the compiler.

As a further precaution, always enclose your FORMAT specification in parentheses when using this technique.

Note that this was done in the DATA statement of the main program above.

Software Product	Version	
DOS-15	V2A	
Component	Version	Edit #
FORTRAN	N/A	N/A
Subprogram or Additional Information	Sequence #	PAGE
	1	2 OF 2
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date

SOFTWARE DISPATCH

DOS-15

Pre-1973

FORTRAN

Usage of ADSS versus DOS Magtape handler MTF

PROBLEM:

1. The MTF. handler released with ADSS-15 V5A does not calculate checksums for IOPS binary records. MTF. 006 released with DOS does calculate checksums. Users attempting to read old data tapes under DOS FORTRAN may run into problems.
2. MTF. 006 has a default buffer size of 255 (10). The ADSS version has a fixed buffer size of 56 (10).
3. The buffer size in MTF. 006 may be changed under program control by referencing the global "MTBSIZ". (See DOS Users Manual).
4. MTF. 006 checks for record length errors prior to calculating checksums, and, if the record length is less than 255 (i.e., 56), MTF. 006 returns to the user without calculating a checksum.

The above inconsistencies create the following possibilities when reading old data tapes under DOS FORTRAN and MTF. 006.

	MTBSIZ	OTS Error	Data Read In
One physical record per logical record	255 ₁₀	None	Good
	56 ₁₀	11	----
More than one physical record per logical record	255	None	Bad
	56	11	---

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
FORTRAN		N/A	N/A
Subprogram or Additional Information		Sequence #	PAGE
MTF.		2	1 OF 3
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	

SOFTWARE DISPATCH

DOS-15

Pre-1973

Usage of ADSS versus DOS Magtape handler MTF (Cont'd)

In order to avoid OTS or data errors when reading old tapes under DOS FORTRAN/MTF. 006, the user must follow this procedure:

1. Call loader with \$LOAD (not GLOAD)
2. Load program using P option to get core map
3. When loader types ↑S, depress stop button
4. Deposit 740000 in MTF. + 423 (8) where MTF. = load map address for MTF.
5. Deposit 000070 in MTF. + 1201 (8)
6. Press continue and type ↑S to start program

Another alternative would be to change the source of MTF. 006 so that it never calculates checksums and then under program control change the contents of "MTBSIZ" with a GLOBAL subroutine.

As a final possibility, the user may copy his old data tapes using the following program.

```
10 CALL SET56
   READ (1, END = 11) LIST
   CALL SET255
   WRITE (2) LIST
   GO TO 10

11 CALL SET255
   WRITE (2) LIST
   CALL CLOSE (1)
   CALL CLOSE (2)
   STOP
   END
```

Software Product		Version	
DOS-15		V1A	
Component	Version	Edit #	
FORTTRAN	N/A	N/A	
Subprogram or Additional Information	Sequence #	PAGE	
MTF.	2	2 OF 3	
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	

SOFTWARE DISPATCH

DOS-15

Pre-1973

Usage of ADSS versus DOS Magtape handler MTF. (Cont'd)

SET56 and SET255 are two macro subroutines:

```
.GLOBL SET56,MTBSIZ,.FM

SET56      Ø
           LAC  (7Ø)
           DAC* MTBSIZ
           DAC* .FM
           JMP* SET56
           .END

.GLOBL SET255,MTBSIZ,.FM

SET255     Ø
           LAC  (377)
           DAC* MTBSIZ
           DAC* .FM
           JMP* SET255
           .END
```

* Do not modify these programs.
Insure that tapes are at load point before starting.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
FORTRAN		N/A	N/A
Subprogram or Additional Information		Sequence #	PAGE
MTF.		2	3 OF 3
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

MARCH 1973

FORTRAN IV OPERATING ENVIRONMENT MANUAL (DEC-15-GFZA-D)

Corrected version of ADJ to remove incompatibility with
FORTRAN Object Time System

PROBLEM:

The ADJ subroutine published in DEC-15-GFZA-D, 'FORTRAN IV Operating Environment', Appendix C, is not compatible with FORTRAN OTS libraries using .SS 008. (.SS 008 is edit #8 of .SS, the array element address calculation routine).

Errors will occur for the following case

1. A calling program DIMENSIONS a single subscripted array, e.g., A(100). This array is passed as a subroutine call parameter, e.g., CALL Z (A).
2. The subroutine adjusts this array to be used as a two dimensional array, e.g.

```
SUBROUTINE Z (A)
  DIMENSION A(10,10)
  CALL ADJ (A,A(1,1),10,10,0)
```

What happens is that .SS 008 is used to calculate the address of A(1,1). This causes a fatal error, since .SS 008 is being used on an array (A(100) in the main program) that is still single dimensioned until the ADJ call is complete. .SS 008 is not usable for single dimensioned arrays, and will not make a proper return.

SOLUTION:

The following changed ADJ circumvents this problem by re-entering the latter parts of .SS 008 at such a location that the address computed is returned directly to ADJ. This change is compatible only with .SS 008 as assembled without any conditional parameters. The changed version replaces the published version in the aforementioned document.

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
FORTRAN		N/A	1
Subprogram or Additional Information		Sequence #	PAGE
ADJ		3	1 OF 4
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

MARCH 1973

Corrected version of ADJ to remove incompatibility with
FORTRAN Object Time System (Cont'd)

It should be kept in mind that once an array is adjusted in a program this constitutes a change on the array's array descriptor block which remains in effect until another ADJ call is made. Thus, for an array that is adjusted in some program, the adjusted values pertain on return to a calling program from which the array name is passed, or in any called program to which the array name is passed.

```
/ ADJ - FORTRAN ARRAY DESCRIPTOR BLOCK DIMENSION ADJUSTMENT
/
/ EDIT #1 (TAM)
/
/COMPATIBLE ONLY WITH UNCONDITIONALIZED VERSION OF .SS 008
/
/COPYRIGHT 1973, DIGITAL EQUIPMENT CORPORATION, MAYNARD, MASS.
/
/CALLING SEQUENCE
/   JMS* ADJ
/   JMP .+6
/   .DSA ADBWD4      /ADDRESS OF WD4 OF ARRAY DESCRIPTOR BLOCK
/                   /OF ARRAY PASSED AS A DUMMY PARAMETER
/   .DSA B           /ADDRESS OF LOCATION IN THE ABOVE ARRAY AT
/                   /WHICH THE ADJUSTED ARRAY IS TO BEGIN
/   .DSA K1         /ADDRESS OF NEW MAXIMUM FIRST SUBSCRIPT
/   .DSA K2         /ADDRESS OF NEW MAXIMUM SECOND SUBSCRIPT
/   .DSA K3         /ADDRESS OF NEW MAXIMUM THIRD SUBSCRIPT
/
.GLOBL ADJ,.DA,.AD,.SS
ADJ 0
JMS* .DA           /GET ARGUMENT ADDRESS
JMP  .+6          /JUMP AROUND PARAMETER LIST

ARRAY 0
B      0
K1     0
K2     0
K3     0
```

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
FORTRAN		N/A	1
Subprogram or Additional Information		Sequence #	PAGE
ADJ		3	2 OF 4
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

MARCH 1973

Corrected version of ADJ to remove incompatibility with
FORTRAN Object Time System (Cont'd)

```

LAC* K2          /SPECIAL CONSIDERATION IS MADE FOR CASE OF
SNA              /ADJUSTING A SINGLE DIMENSIONED ARRAY TO 2 OR
JMP F+1          /MORE , SINCE .SS 008 WILL THEN FAIL IN COMPUTING
LAC .SS          /B. IF K2 IS ZERO, WE'RE OK, AS THERE IS ONLY
TAD (34         /ONE DIMENSION TO ADJUST. ELSE THE LAST PART OF
DAC B           /SS IS REDONE. B IS USED TEMPORARILY TO STORE
LAC (F          /ADDRESS AT WHICH TO ENTER .SS. AND F IS SET
DAC* .SS        /AS THE ADDRESS .SS WILL RETURN TO.
JMP* B          /THUS THIS JMP* IS TO .SS+34. RETURNED IN THE
DAC B           /AC IS THE CORRECT ADDRESS OF THE NEW LOCATION.

F
/

LAC (LAC* B     /INITIALIZE SUBSCRIPT POINTERS
DAC C
LAC B           /SET NEW STARTING ADDRESS
DAC* ARRAY
LAW -3
DAC CTR#        /COUNT FOR 3 SUBSCRIPTS
TAD ARRAY       /COMPUTE ADDRESS TO FIRST WORD OF ARRAY DESCRIPTOR
DAC ARRAY       /BLOCK IN THE PROGRAM IN WHICH THE ARRAY IS
DAC ARRAYP#     /DEFINED. THE ARRAY TYPE IS IN BITS 3 & 4 OF THIS
LAC* ARRAY      /WORD.
AND (60000      /ZERO OUT THE ARRAY SIZE
DAC* ARRAY      /SAVE CLEAN ARRAY TYPE
LRSS 15        /RIGHT JUSTIFY THE MODE, AND DETERMINE LENGTH
TAD (1          /OF THE VARIABLE TYPE. LENGTH = MODE + 1, EXCEPT
AND (3          /FOR DOUBLE INTEGER
SNA
LAC (2
LOOP ISZ C       /BUMPS TO LAC* K1, THEN K2, THEN K3
C   JMS* .AD     /MULTIPLY INTEGERS - CURRENT AC CONTENTS TIMES
XX           /K1, K2, OR K3, WHERE LAC* B WAS DAC'D, THEN
SNA          /ISZ'D ABOVE. WHEN THE RESULT IS ZERO, HAVE
JMP D        /RUN OUT OF SUBSCRIPTS.
DAC SIZE#    /UPDATE CUMULATIVE SIZE.
ISZ CTR      /ARE 3 SUBSCRIPTS YET TREATED?
SKP         /NO - GO STORE SUCCESSIVE SIZES
JMP E       /YES - GO CLEANUP
    
```

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
FORTRAN		N/A	1
Subprogram or Additional Information		Sequence #	PAGE
ADJ		3	3 OF 4
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

MARCH 1973

Corrected version of ADJ to remove incompatibility with
FORTRAN Object Time System (Cont'd)

```
/      ISZ ARRAYP      /STORE SUCCESSIVE SIZES INTO APPROPRIATE WORDS OF
DAC* ARRAYP          /ARRAY DESCRIPTOR BLOCK
JMP LOOP

/
D      DZM* ARRAYP     /WHEN HAVE RUN OUT OF SUBSCRIPTS, ZERO THE
ISZ ARRAYP           /REMAINING WORDS OF THE ADB.
ISZ CTR               /CHECK FOR FINISH
JMP LOOP

/
E      LAC SIZE        /CLEANUP - PACK THE SIZE AND THE MODE BITS INTO
AND (17777           /THE FIRST WORD OF THE ADB.
XOR* ARRAY
DAC* ARRAY
JMP* ADJ
.END
```

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
FORTRAN		N/A	1
Subprogram or Additional Information		Sequence #	PAGE
ADJ		3	4 OF 4
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

August, 1972

FORTRAN COMPILER (EDIT #36) F4X V36B, FPF4X V36B AND F4X9 V36B

Patch to correct improper imbedded subscript calculation

PROBLEM:

F4 036 generates improper subscript calculating code for A(J(I)) with a non-integer array.

SOLUTION:

The following patches, one for each of the three compilers, correct this problem. Use the "LR" command when patching FORTRAN or any relocatable file.

	<u>LOCATION</u>	<u>OLD CONTENTS</u>	<u>NEW CONTENTS</u>	<u>SYMBOLIC</u>
F4X	6546	106400	206400	'V36B' 15
	7736	207724	#+615435	JMP PATCH
	7737	112754	#+210231	LAC TSI
	7740	113247	#+055443	DAC TSITMP
	7741	040007	#+215443	LAC TSITMP
	7742	110100	#+050231	DAC TSI
	7747	607743	#+607741	JMP .-6
	15435	0	#+207724	LAC EXSBMD
	15436	0	#+112754	JMS SETN
	15437	0	#+113247	JMS TWOCMA
	15440	0	#+040007	DAC SSCTR
	15441	0	#+110100	JMS FPPOUT
	15442	0	#+607737	JMP BACK
	15443	0	0	-

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
FORTRAN COMPILER		V36B	36
Subprogram or Additional Information		Sequence #	PAGE
F4X, FPF4X, F4X9		1	1 OF 2
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

August, 1972

Patch to correct improper imbedded subscript calculation (Cont'd)

	<u>LOCATION</u>	<u>OLD CONTENTS</u>	<u>NEW CONTENTS</u>	<u>SYMBOLIC</u>
FPF4X	66Ø7	333202	3332Ø4	'V36B' 15
	1ØØØ4	2Ø7772	#+615714	JMP PATCH
	1ØØØ5	113Ø72	#+21Ø344	LAC TSI
	1ØØØ6	113365	#+Ø55722	DAC TSITMP
	1ØØØ7	Ø4ØØØ7	#+215722	LAC TSITMP
	1ØØ1Ø	11Ø213	#+Ø5Ø344	DAC TSI
	1ØØ15	61ØØ11	#+61ØØØ7	JMP .-6
	15714	Ø	#+2Ø7772	LAC EXSBMD
	15715	Ø	#+113Ø72	JMS SETN
	15716	Ø	#+113365	JMS TWOCMA
	15717	Ø	#+Ø4ØØØ7	DAC SSCTR
	1572Ø	Ø	#+11Ø213	JMS FPPOUT
	15721	Ø	#+61ØØØ5	JMP BACK
	15722	Ø	Ø	-
	F4X9	6533	64Ø432	641Ø32
7716		2Ø77Ø4	#+615412	JMP PATCH
7717		112742	#+21Ø211	LAC TSI
772Ø		113235	#+Ø5542Ø	DAC TSITMP
7721		Ø4ØØØ7	#+21542Ø	LAC TSITMP
7722		11ØØ6Ø	#+Ø5Ø211	DAC TSI
7727		6Ø7723	#+6Ø7721	JMP .-6
15412		Ø	#+2Ø77Ø4	LAC EXSBMD
15413		Ø	#+112742	JMS SETN
15414		Ø	#+113235	JMS TWOCMA
15415		Ø	#+Ø4ØØØ7	DAC SSCTR
15416		Ø	#+11ØØ6Ø	JMS FPPOUT
15417		Ø	#+6Ø7717	JMP BACK
1542Ø		Ø	Ø	-

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
FORTRAN COMPILER		V36B	36
Subprogram or Additional Information		Sequence #	PAGE
F4X, FPF4X, F4X9		1	2 OF 2
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

MARCH 1973

FORTRAN COMPILER (EDIT #36) F4X V36B, F4X9 V36B, FPF4X V36B

Errors not detected during compilation

PROBLEM:

The following errors have been found to occur during compilation using either the F4X V36B, F4X9 V36B, or FPF4X V36B compiler. These will be corrected in subsequent releases of the compiler.

1. Unbalanced parentheses in subroutine calls of the form

CALL LINE ((-MX(I),Ø,1)

are not trapped as an error, and bad object code is generated.

2. IMPLICIT mode declarations of variables appearing in a Statement Function definition fails, i.e., these variables will assume default mode.

SOLUTION:

1. Solution not yet available.
2. To cure problem 2, use an explicit mode declaration for these variables.

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
FORTRAN COMPILER		V36B	36
Subprogram or Additional Information		Sequence #	PAGE
F4X, F4X9, FPF4X		2	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

APRIL 1973

FORTRAN COMPILER (EDIT #36) F4X V36B, FPF4X V36B, F4X9 V36B

Programming to avoid incorrect mode typing of Functions
declared EXTERNAL

PROBLEM:

The compiler is presently typing as Integer any Function named in an External statement. This has bad effects only in the case where a call to such a Function is generated in the same program in which it is declared External, and where the Function should not normally generate an Integer result. No correction is published presently, although a rectification to this will be included in the next compiler release.

RESTRICTION:

For now, restrict your use of the External statement to naming Functions that are used only as Subroutine or other Function parameters; despite the fact that they are thought to be Integer by the main program, the correct address of the Function will be passed. However, if a Function is invoked in some program, do not declare it in an EXTERNAL statement in this same program. The Function will then retain its External characteristic (a fact that is determined by the compiler by the context in which it is used), will not lose its mode, and can be passed as a Subroutine parameter.

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
FORTRAN COMPILER		V36B	36
Subprogram or Additional Information		Sequence #	PAGE
F4X, FPF4X, F4X9		3	1 OF 1
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	



SOFTWARE DISPATCH

DOS-15

December, 1972

FORTRAN COMPILER (EDIT #36) F4X V36B, FPF4X V36B, F4X9 V36B

Incomplete DO Statement difficulties

PROBLEM:

Statements of the form

DO 2Ø I = 1

which are in fact an error, the DO statement not being complete, are not flagged by the compiler properly. When the total number of non-blank characters between column 7 and the equal sign does not exceed 6, no error is noted. The compiler, in fact, codes the assignment statement DO2ØI=1, due to its eliminating of all blanks before processing statements.

It also occurs that when the total number of non-blank characters between column 7 and the equal sign exceeds 6, the error indicating a string of more than six characters occurs. For example, the compiler tries to interpret

DO 2ØØØ I = 1

as DO2ØØØI = 1, which is an invalid assignment statement.

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
FORTRAN COMPILER		V36B	36
Subprogram or Additional Information		Sequence #	PAGE
F4X, FPF4X, F4X9		4	1 OF 1
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	



SOFTWARE DISPATCH

DOS-15

July, 1972

FORTRAN OTS

Programming note to eliminate carriage return

There is a FORTRAN level trick to eliminate the carriage return following a WRITE to the teletype. Follow the query line with an integer (using A1 format) which is initialized with an altmode (in 7 bit ASCII). If a READ is desired at the end of the line, it must be through a .DAT slot differing from that on which the WRITE was issued (which avoids a re-init by FIOPS). Also, the read .DAT slot must have been previously INITed (done for example a REWIND).

Example:

```
DATA IALT/#764000/  
REWIND 3  
WRITE (4,400) IALT  
400 FORMAT (1X, "NUMBER PLEASE:", A1)  
READ (3,) N  
.  
.  
.  
END
```

This results in a FOCAL type read, viz, ENTER NUMBER PLEASE: _____ response

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
FORTRAN OTS		N/A	N/A
Subprogram or Additional Information		Sequence #	PAGE
		1	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

July, 1972

FORTRAN OTS ROUTINE .DA (EDIT #011)

Programming note

Because of the multiple entry feature in F4X, the argument address fetch subroutine .DA does double ended double in-direction when fetching and storing addresses passed from a main program to a subroutine. Users should be aware that if bit zero in the storage address cell of the subroutine is set, another level of indirection is performed. Thus, MACRO subroutines using the argument address cells as scratch cells may suddenly cease to function under F4X.

Software Product	Version	
DOS-15	V2A	
Component	Version	Edit #
FORTRAN OTS	N/A	11
Subprogram or Additional Information	Sequence #	PAGE
.DA	2	1 OF 1
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date



SOFTWARE DISPATCH

DOS-15

December, 1972

FORTRAN OTS ROUTINES AMOD AND DMOD

Numerical Restrictions

In the existing FORTRAN documentation there is not stated a restriction on the range of values that AMOD and DMOD can accommodate. In either of these, for a call of the form AMOD (ARG1, ARG2), one of the internal operations is computing the result of ARG1/ARG2, and then converting this result to a single precision integer. This latter operation limits the useful range of ARG1/ARG2 to less than 2¹⁷, i.e., less than 131072. When this condition is not met, an OTS 11 error occurs, the program continues, and the results of AMOD or DMOD are not generally predictable.

This restriction can be relieved somewhat by the following example. (The following is not to be construed to be a supported software feature of the FORTRAN Object time system). Considering the case of DMOD, code and compile:

```
DOUBLE PRECISION FUNCTION DMOD (ARG1,ARG2)
DOUBLE PRECISION ARG1,ARG2, D
DOUBLE INTEGER J
J = ARG1/ARG2
D = J
DMOD = ARG1 - D*ARG2
RETURN
END
```

Explicitly state this program's file name in the loader command string, and it will be loaded instead of the FORTRAN Library routine DMOD. It extends the largest useful value of ARG1/ARG2 to be less than 34,359,738,368.

An equivalent routine may be written to replace AMOD, by replacing "DOUBLE PRECISION" with "REAL" and "DMOD" with "AMOD", at all locations in which each appears.

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
FORTRAN OTS		N/A	
Subprogram or Additional Information		Sequence #	PAGE
AMOD, DMOD		3	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

MARCH 1973

FORTRAN OTS ROUTINE DDIO (Edit #14), FPP VERSION

Reading INTEGER variables causing IOPS Ø

PROBLEM:

The following error has been found to occur during the execution of FORTRAN compiled programs using the FPP4B V36B compiler. Corrections will appear in subsequent releases of this compiler.

1. Reading in INTEGER variables (not arrays) using DDIO, Edit #14 may cause an IOPS Ø, although it cannot in general be predicted when this situation will arise. To avoid the problem, read the element into a DOUBLE INTEGER variable, then convert it to an INTEGER by an assignment statement or use of the ISNGL function. This problem could conceivably show up when using non-FPP versions, but has not been found to occur in test situations.

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
FORTRAN OTS		N/A	14
Subprogram or Additional Information		Sequence #	PAGE
DDIO		4	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

PRE-1973

LPA.15 (Edit #044)

Source Change to Prevent Return to Mainstream, at API Level 4 on .WAIT

PROBLEM:

The current LPA.15 handler does not do a DBR on return from a successful .WAIT system MACRO. Therefore, the calling program is entered at API level 4.

SOLUTION:

The problem is corrected by editing the source (LPA.15 Edit #043) as indicated below.

<u>Location</u>	<u>Old Contents</u>	<u>New Contents</u>
LPWAT1+1	JMP* LPARGP	JMP LPNEXT

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
LINE PRINTER HANDLERS		N/A	44
Subprogram or Additional Information		Sequence #	PAGE
LPA.15		1	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

PRE-1973

LINKING LOADER V12A (Edit #023)

Features of this Version

The Linking Loader will load programs in whatever addressing mode is current to the system. The BANK and PAGE Nonresident Monitor commands set the addressing mode. This loader identifies itself as LOADER V12A for page mode loads, and BLOADER V12A for bank mode loads.

There is a new Linking Loader code, CODE=33, which indicates the extension of the source file used to create the binary file via MACRO-15. When the "P" switch is used with the Linking Loader, the loader will print both the Object File's name, and the Source file's extension, for each file loaded. This allows programmers to identify different versions of their binary files.

The loader has been modified to allow arbitrary numbers of positive .DAT slots (as determined at system generation, up to 77 octal), and it will compute the position of .DAT from .SCOM+23.

The Linking Loader searches the 'IOS' UIC, the user's library, if one is present, and the system library as many times as is necessary to resolve .GLOBL's.¹ If a complete pass through them yields no new resolution, the Loader tries to match the missing .GLOBL's to Common Blocks. If some missing .GLOBL's still remain, a LOAD 3 is generated. These searches terminate early, if all .GLOBL's are resolved. The effect of this change is to allow backward references in user libraries, and to allow user files to reference the IOS and the system library.

¹ IOS, User Library, System Library, IOS;
(Test for resolution on last pass)
User Library, System Library, IOS;
(Test) etc.

Software Product	Version	
DOS-15	V2A	
Component	Version	Edit #
LINKING LOADER	V12A	23
Subprogram or Additional Information	Sequence #	PAGE
	1	1 OF 1
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date



SOFTWARE DISPATCH

DOS-15

PRE-1973

LKA. (EDIT #000)Functional Description1. Overall Description

The LK35 Keyboard Device Handler provides an interface between the user and the hardware. In general, it conforms to the conventions of the Disk Operating System, as described in DEC manual, DOS-15 User's Manual, DEC-15-ODUMA-A-D. Since the LK35 keyboard is a send only device, this handler will only handle input functions. The input functions are initiated by standard user program commands and all interrupt management is done automatically by the handler. The handler does not make the LK35 a console control keyboard; it is only an input device.

The primary goals of the handler are to relieve the user from writing his own device-handling subprograms and to centralize all direct communication between the PDP-15 and the LK35 keyboard. This handler will only input IOPS ASCII or IMAGE ASCII into a user's designated buffer. It is up to the user to display the text on the VT04, or write the text on any other device. The LK35 will be connected to the LT15 or the LT19D. Only one LK35 under DOS is supported.

Equipment required includes a PDP-15/20 with a

VT15
VT04 or VT07
LK35
LT19D or LT15

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
LK35 KEYBOARD HANDLER		N/A	0
Subprogram or Additional Information		Sequence #	PAGE
LKA.		1	1 OF 6
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	

SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Description (Cont'd)

Legal System Macros

.INIT
.READ
.WAIT
.WAITR
.CLOSE
.FSTAT

Illegal Functions

.WRITE
.DELETE
.RENAM
.ENTER
.CLEAR
.MTAPE
.TRAN

Ignored Functions

.SEEK

2. Legal Functions

2.1 .INIT (initialize) Macro

The .INIT causes the keyboard to be initialized and must be called before any other I/O Macro to this device is issued.

a. Form .INIT [-]ds,dd,restrt

b. Variables

ds = .DAT slot number

dd = ignored - may be any number between 0 and 3

restrt = CTRL P address

c. Expansion

LOC+0 CAL+10000*dd [-]ds&777

LOC+1 1

LOC+2 restrt

LOC+3 000000 /standard size of buffer (34₁₀) will be
/returned

d. Description

1. Handler will return standard line buffer size (34₁₀)
2. .INIT will abort a .READ

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
LK35 KEYBOARD HANDLER		N/A	0
Subprogram or Additional Information		Sequence #	PAGE
LKA.		1	2 OF 6
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Description (Cont'd)

2.2 .READ Macro

The .READ macro is used to transfer data from the LK35 to core memory.

a. Form .READ [-]ds,m,bufadd,wc

b. Variables

ds = .DAT slot number

m = Data mode

2 = IOPS ASCII

3 = IMAGE ASCII

bufadd = Line buffer address

wc = Line buffer word count, including the two-word header.

c. Expansion

LOC+0 CAL+10000*m [-]ds&777

LOC+1 10

LOC+2 bufadd

LOC+3 -wc

d. Description: .READ will

1. Allow previous input to terminate.
2. Set input underway indicator.
3. Set up to accept characters from keyboard.
4. Accept data control characters in IOPS ASCII.
 - a) Rubout - delete previous character typed.
 - b) ↑U - delete entire line typed so far.
5. Carriage Return or ALT MODE terminates an IOPS ASCII read.
6. The word count terminates an IMAGE ASCII read.

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
LK35 KEYBOARD HANDLER		N/A	0
Subprogram or Additional Information		Sequence #	PAGE
LKA.		1	3 OF 6
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Description (Cont'd)

2.3 .WAIT Macro

The .WAIT macro is used to detect the availability of the user's line buffer.

a. Form .WAIT [-]ds

b. Variable

ds = .DAT slot number

c. Expansion

```
LOC+0  CAL   [-]ds&777
LOC+1  12
```

d. Description

1. Control is returned to the user immediately after the expansion, if the line buffer is available.
2. If transfer of data has not been completed, control loops on the .WAIT macro.

2.4 .WAITR Macro

The .WAITR macro allows the user program to proceed in line if the previous .READ is complete. If the previous .READ is not complete control is given to the location in the user program specified by the .WAITR call. This allows the user to branch to some other part of his program while waiting for the .READ to finish. The user must continue to check for completion by periodically issuing .WAITR's or by using a .WAIT.

a. Form .WAITR [-]ds,waitad

b. Variables

ds = .DAT slot number

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
LK35 KEYBOARD HANDLER		N/A	Ø
Subprogram or Additional Information		Sequence #	PAGE
LKA.		1	4 OF 6
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Description (Cont'd)

waitad = location in the user program to branch to if input is not completed.

c. Expansion

LOC+0 CAL+1000 [-] ds&777
LOC+1 12
LOC+2 waitad

2.5 .CLOSE Macro

a. Form .CLOSE [-] ds

b. Variables

ds = .DAT slot number

c. Expansion

LOC+0 CAL [-] ds&777
LOC+1 6

d. Description

Same as .WAIT

2.6 .FSTAT Macro

a. Form .FSTAT [-] ds, address

b. Variables

ds = .DAT slot number
address = ignored

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
LK35 KEYBOARD HANDLER		N/A	Ø
Subprogram or Additional Information		Sequence #	PAGE
LKA.		1	5 OF 6
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Description (Cont'd)

c. Expansion

LOC+0 CAL+30000[-]ds&777
LOC+1 2
LOC+2 address

d. Description

1. Will return a zero in the AC, since this since this device is non-file oriented.

3. Legal Control Characters

- a. Control C (↑C) does a .EXIT to the Monitor.
- b. Control P (↑P) transfers control to the address given in the .INIT CAL.
- c. Control D (↑D) gives an End-of Medium Header Word Pair to the user.

Software Product	Version	
DOS-15	V2A	
Component	Version	Edit #
LK35 KEYBOARD HANDLER	N/A	0
Subprogram or Additional Information	Sequence #	PAGE
LKA.	1	6 OF 6
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date

SOFTWARE DISPATCH

DOS-15

PRE-1973

MACRO-15 V7A (EDIT #082)

New Switches in this Version

The Omit (O) switch

The O switch will cause MACRO-15 to omit the source extension and the new Linking Loader code (code=33) from the binary file. This should be used when assembling programs to be run on other PDP-15 systems, in particular, BACKGROUND/BACKGROUND, and ADVANCED SOFTWARE SYSTEM.

The Error (E) switch

The E switch allows programmers to have any assembly errors printed on the console teleprinter, in addition to the device assigned to .DAT-12. The E switch is useful only if the L or N switches are also used.

This will help programmers who assign DECTape or Disk to .DAT-12, but want to know where any error lines are. Previously, such a situation would require two assemblies: One to find any errors (e.g.:+FIL), that is, no switches), and one other if no errors occurred, this time using the N or L switches.

The Table of Contents (T) switch

If "T" is typed in the command string, a table will be generated during Pass one with the page number and the text of all assembled .TITLE statements in the program. This file will be generated with the program listing name on .DAT-12. Note that it is still necessary to type N, L, etc. if other listing output is required.

An assumption about switches:

If the L and X options are typed, MACRO-15 will assume that the N-option was typed also. This will help the user who typically forgets to type "N" and gets a cross reference that is effectively useless, because the source lines of the listing are not numbered.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
MACRO-15		V7A	82
Subprogram or Additional Information		Sequence #	PAGE
		1	1 OF 1
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	



SOFTWARE DISPATCH

DOS-15

PRE-1973

MACRO-15 V7A (EDIT #082)

Macros Implemented Specifically for DOS-15

MACRO-15 for DOS implements .RAND, .RTRAN, .USER, .OVRLA, .GTBUF and .GVBUF, as per Appendix B-1 and B-2 of the DOS PRELIMINARY MANUAL (DEC-15-MZDA-D). MACRO accepts .ENTER macros with file protect codes. MACRO-15 has not implemented Macro calls for .GET and .PUT.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
MACRO-15		V7A	82
Subprogram or Additional Information		Sequence #	PAGE
		2	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

PRE-1973

MACRO-15 V7A (EDIT #082)

Pseudo-op, .CBD

The Macro Assembler pseudo-op .CBD (Common Block Definition) allows the assembly language programmer to declare a COMMON of an indicated name and size, and to specify a word to be set to its base address.

The .CBD pseudo-op takes a COMMON name and its size as arguments, reserves one word of core, and outputs loader codes and parameters to direct the Linking Loader or CHAIN to set a vector to the first element of the indicated COMMON in the reserved word. For example, the statement

```
BASE .CBD ABCD 6
```

will provide the base address of COMMON/ABCD/ in the word labelled BASE.

Attached is a sample subroutine and an expansion of its assembled output. The 07, 10, 14, 15, 16 (octal) loader code sequence is the result of the .CBD pseudo-op. The 07-10-14 codes declare a COMMON named ABCD, and the 15-16 codes indicate that a vector to location 0000 in the COMMON is to be set in location 0012 of the routine being relocated.

NOTE: The .CBD pseudo-op must not be the first line of code.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
MACRO-15		V7A	82
Subprogram or Additional Information		Sequence #	PAGE
		3	1 OF 3
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Pseudo-op, .CDB (Cont'd)

PAGE 1 SIGMA SPC

```

/SIGMA -- FORTRAN CALLABLE SUBROUTINE
/
      .GLOBL  SIGMA
/
00000 R 000000 A  SIGMA  0
00001 R 200013 R      LAC   (5)
00002 R 722000 A      PAL
00003 R 735000 A      CLX
00004 R 750000 A      CLA
/
00005 R 370012 R  LOOP  TAD*  BASE,X
00006 R 725001 A      AXS   +1
00007 R 600005 R      JMP   LOOP
/
00010 R 070012 R      DAC*  BASE,X
00011 R 620000 R      JMP*  SIGMA
/
00012 R 000000 A  BASE  .CBD ABCD 6  /BASE OF COMMON BLOCK "
/
      000000 A      .END
00013 R 000005 A *L
SIZE=00014      NO ERROR LINES
    
```

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
MACRO-15		V7A	82
Subprogram or Additional Information		Sequence #	PAGE
		3	2 OF 3
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Pseudo-op, .CDB (Cont'd)

NAME = SIGMA
BIAS =

01	000014			
07	474057		SIG	
10	050550		MA@	
12	000000		SIGMA@=00000	
07	474057		SIG	
10	050550		MA@	
33	074623		SRC	
23	400000		SIGMA@=00000	
02	000000			
04	000000	00000	CAL	00000
03	200013	00001	LAC	00013
04	722000	00002	IOT	02000
04	735000	00003	IOT	15000
04	750000	00004	OPR	10000
03	370012	00005	TAD*	10012
04	725001	00006	IOT	05001
03	600005	00007	JMP	00005
03	070012	00010	DAC*	10012
03	620000	00011	JMP*	00000
07	403223		ABC	
10	014400		D@@	
14	000006			
15	000000			
16	000012			
04	000000	00012	CAL	00000
02	000013			
04	000005	00013	CAL	00005
? 07	406273		BAS	
10	017500		E@@	
23	000012		BASE@@=00012	
07	446547		LOO	
10	062000		P@@	
23	000005		LOOP@@=00005	
07	474057		SIG	
10	050550		MA@	
23	000000		SIGMA@=00000	
27	000000		.END	0000

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
MACRO-15		V7A	82
Subprogram or Additional Information		Sequence #	PAGE
		3	3 OF 3
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

PRE-1973

MACRO-15 V7A (EDIT #082)

Note on Binary Output File Extensions

MACRO-15 will include the extension of the source file in the binary output file. This means that programmers may use a numeric source file extension and increment it with each edit. (Other extensions are also legal, of course.) Then the P switch in the Linking Loader will produce the edit number of the current core load -- an invaluable identification tool in development programming. UPDATE's L command will also list the extension of the source file for each program in a library.

MACRO-15 accomplishes this by using a new Linking Loader code, code=33, as shown in the example on the next page.

Other PDP-15 systems, in particular, the ADVANCED SOFTWARE SYSTEM and BACKGROUND/FOREGROUND, will not work with the 33 Loader code. If programmers wish to assemble source files for such systems with this version of MACRO-15, they should use the "O" (omit) switch, which will omit the source file extension and the 33 Linking Loader code from the binary file.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
MACRO-15		V7A	82
Subprogram or Additional Information		Sequence #	PAGE
		4	1 OF 3
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Note on Binary Output File Extensions (Cont'd)

EXAMPLE:

PROGRAM LISTING

PAGE 1

J.BOND 007

/SHOW NEW LINK LOADER CODE
/AND WHERE IT IS PLACED
/

/EDIT* 007 9.28.71
/

00000 R 200001 R
00001 R 740000 A
000000 A

LAC A
A NOP
.END

SIZE=00002

NO ERROR LINES

DIRECTORY LISTING

>L TT ← DK

28-SEP-71
DIRECTORY LISTING
767 FREE BLKS
1 USER FILES
110 SYSTEM BLKS
J.BOND BIN 1 1

Software Product	Version	
DOS-15	V1A	
Component	Version	Edit #
MACRO-15	V7A	82
Subprogram or Additional Information	Sequence #	PAGE
	4	2 OF 3
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date

SOFTWARE DISPATCH

DOS-15

PRE-1973

Note on Binary Output File Extensions (Cont'd)

BINARY FILE DUMP

WORD	CONTENT	
0	010710	3 LINK LOADER CODES (SIX BITS EACH)
1	000002	PROGRAM SIZE
2	441342	J.B = FIRST SIX CHARACTERS OF
3	057764	OND = NAME IN RADIX 50
4	332302	3 LINK LOADER CODES
5	226067	EXTENSION NAME IN RADIX 50
6	400000	
7	000000	
10	030407	
11	200001	FIRST INSTRUCTION
12	740000	SECOND INSTRUCTION
13	003100	

(REST OF GENERATED CODE NOT SHOWN)

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
MACRO-15		V7A	82
Subprogram or Additional Information		Sequence #	PAGE
		4	3 OF 3
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

PRE-1973

Problems corrected (Cont'd)

6. MACRO-15 lost some literals during PASS one in a 28K environment. This caused internal pointers to be out of phase. When these pointers were passed on to CREF (Pass three), CREF would wipe out part of lower core.
7. The .EBREL and .DBREL pseudo-op now change addressing modes in .ABS(P) and .FULL(P) programs.
8. The following sequence assembled correctly, but caused E errors. The error message is no longer produced.

e.g.,

```
.LOC 600000  
LAW -1  
.LOC 700000  
LAW -1
```

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
MACRO-15		V7A	82
Subprogram or Additional Information		Sequence #	PAGE
		5	2 OF 2
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

MACRO-15 V7A (EDIT #082)

Programming Note on Usage of 'T' Switch

PROBLEM:

When using the T-switch, a discrepancy in the page count may occur where the user has a .LTORG in his program with many forward referencing literals. The forward referencing literals waste space, and should be removed--one location is reserved per forward reference. The page count discrepancy occurs because the page count is adjusted during pass one to reflect the total literal count. If the count is smaller after pass two (forward references have been defined), the page count is likely to be inaccurate.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
MACRO-15		V7A	82
Subprogram or Additional Information		Sequence #	PAGE
		6	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

PRE-1973

MACRO-15 V7B (EDIT #082)Patch to Expand .RTRAN Correctly**PROBLEM:**

MACRO-15 V7A expands the .RTRAN system macro with a positive rather than negative word count.

SOLUTION:

The following patch to MACRO corrects this error. The source code notation to the right need not be keyed in; it is shown only for information purposes.

<u>LOCATION</u>	<u>OLD CONTENTS</u>	<u>NEW CONTENTS</u>	<u>SYMBOLIC</u>
3272	426061	426061	.ASCII /EC/<15>
3273	504402	504532	<11>/-/
3274	024337	004121	.ASCII <001><005>
3275	700000	577400	<15><177>
7461	106400	206400	V7B

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
MACRO-15		V7B	82
Subprogram or Additional Information		Sequence #	PAGE
		7	1 OF 1
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	



SOFTWARE DISPATCH

DOS-15

October, 1973

CREF V7C (EDIT #016)

Patch to correct printing of erroneous message

PROBLEM:

When the command string to MACRO ends with a carriage return, CREF prints out the message: "PROGRAM NOT IN COMBLK".

SOLUTION:

The following patch to CREF corrects this problem.

<u>LOCATION</u>	<u>OLD CONTENTS</u>	<u>NEW CONTENTS</u>	<u>NEW SYMBOLIC</u>
17136	17140	17137	.+1

To change the version number patch the following location in MACRO:

<u>LOCATION</u>	<u>OLD CONTENTS</u>	<u>NEW CONTENTS</u>	<u>NEW SYMBOLIC</u>
7461	206400	306400	V7C

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
MACRO-15		V7C	16
Subprogram or Additional Information		Sequence #	PAGE
CREF		8	1 OF 1
New	Replacement Article	Original Date	
<input type="checkbox"/>	<input type="checkbox"/> 1	Pre-1973	



SOFTWARE DISPATCH

DOS-15

PRE-1973

CREF (EDIT #018)

Solutions to miscellaneous problems

1. Problem - Outputs one line too many for the VP15 storage scope.

Correction - Output one line less on each page.

2. Problem - Does not detect symbols occurring after an operator in an expression. This was because CREF as soon as it saw a number after the equal sign in an expression terminated processing of current line.

Correction - Check and make sure that the operand after the operator is a number before processing the next line; in the event the operand is a symbol, update the symbol table.

3. Problem - Did not handle line numbers beyond 9999₁₀. They were converted modulo 10000₁₀.

Correction - Handles line numbers beyond 9999₁₀.

Attached is a copy of the modified portions of the SRC listing. Changes are indicated by underscored and enclosed instructions.

Users have to make note that in order to patch the new CREF (edit #018) into the system, MACRO-15 V7A, edit #082 has to be modified as follows:

change P3ARGS=17610 on p. 5 of the SRC listing to
P3ARGS=17620

MACRO has then to be reassembled and patched into the system.

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
MACRO-15		N/A	18
Subprogram or Additional Information		Sequence #	PAGE
CREF		9	1 OF 5
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

October, 1973

Solutions to miscellaneous problems (Cont'd)

The above becomes necessary due to the increase in size of CREF. If the above is not done, users are assured that CREF will not run.

NOTE WELL

The following source code modifications do not encompass the program correction to CREF described as a binary patch in the preceding article. Also, subsequent CREF articles with patches will show corrections to the original version of CREF (edit #016) rather than to this one.

PAGE 11	CREF	018	CREF
406		017642	LSTLIN=EXPAGE+1
407		017643	LSTPGE=LSTLIN+1
408		017844	MULTIN=LSTPGE+1
409	16236	000000	OVRL1 0
410	16237	777713	LINCNT =65
411			/
412			/CHARACTER CONSTANTS
413			/ .OCT
414	16240	000040	SPACE 40

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
MACRO-15		N/A	18
Subprogram or Additional Information		Sequence #	PAGE
CREF		9	2 OF 5
New	Replacement Article	Original Date	
<input type="checkbox"/>	<input type="checkbox"/> 1	Pre-1973	

SOFTWARE DISPATCH

DOS-15

PRE-1973

Solutions to miscellaneous problems (Cont'd)

PAGE 15	CREF	Ø18	CREF
558			/SUBROUTINE TAGPRO
559			/
56Ø			/TAGPRO RECEIVES CONTROL IF THE FIRST
561			/OF A STATEMENT IS AN ALPHA OR DOT
562			/DIRECT ASSIGNMENTS ARE ALSO HANDLED HERE
563			/
564	16426	ØØØØØØ	TAGPRO Ø /
588	16456	116746	JMS FALPHA /IS IT AL
589	16457	1175Ø3	JMS ADRPRO /YES, TRE
59Ø	1646Ø	116764	JMS NUMERC /NO, CHECK IF IT
591	16461	616463	JMP CHKSYM /YES, NOW CHECK IT
592	16462	616154	JMP NXTLIN /NO
593			/
594			/
595	16463	1166Ø7	CHKSYM JMS GETCHR
596	16464	116764	JMS NUMERC /CHECK IF CHARACTE
597	16465	616463	JMP CHKSYM /YES, LOOP
598	16466	1167Ø2	JMS ADRDEL /NO, CHECK IF NEXT
599	16467	616455	JMP TAGDIR+1 /YES, CHECK FOR S
6ØØ	1647Ø	616154	JMP NXTLIN /NO, GO TO NEXT L
6Ø1			/
6Ø2			/
6Ø3	16471	1166Ø7	TAGEND JMS GETCHR /EDIT #16
6Ø4		1166Ø7	/

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
MACRO-15		N/A	18
Subprogram or Additional Information		Sequence #	PAGE
CREF		9	3 OF 5
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Solutions to miscellaneous problems (Cont'd)

PAGE 26	CREF	Ø18	CREF	
1Ø18			/	
1Ø19	17174	ØØØØØØ	UNDEC	Ø
1Ø2Ø	17175	157313		DZM OINIT /FLAG LEAD
1Ø21				.IFUND DOS15
1Ø22				DAC OVRL1
1Ø23				JMS DIVIDE
1Ø24				LAC OVRL1
1Ø25				LAC DTENTH
1Ø26				.ENDC
1Ø27				.IFDEF DOS15
1Ø28	17176	673323		IDIV!SHAL
1Ø29	17177	Ø2342Ø	DTENTH	2342Ø /1ØØØØ DEC.
1Ø3Ø	172ØØ	Ø56236		DAC OVRL1
1Ø31	172Ø1	641ØØ2		LACQ
1Ø32				.ENDC
1Ø33	172Ø2	11723Ø		JMS UNSEND
1Ø34				.IFUND DOS15
1Ø35				DAC OVRL1 /

PAGE 27	CREF	Ø18	CREF	
1Ø4Ø				.IFDEF DOS15
1Ø41	172Ø3	216236		LAC OVRL1
1Ø42	172Ø4	673323		IDIV!SHAL
1Ø43	172Ø5	ØØ175Ø		175Ø /1ØØØØ DEC
1Ø44	172Ø6	Ø56236		DAC OVRL1

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
MACRO-15		N/A	18
Subprogram or Additional Information		Sequence #	PAGE
CREF		9	4 OF 5
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Solutions to miscellaneous problems (Cont'd)

PAGE 28	CREF	Ø18	CREF		
1Ø93	17253	516312		AND	L77777
1Ø94	17254	Ø57174		DAC	UNDEC
1113	17276	2173Ø3	MACRO	LAC	MACR /PRINT 'MACRO' IN
1114	17277	117151		JMS	UNSIX /OCTAL VA
1115	173ØØ	2173Ø4		LAC	MACR+1
1116	173Ø1	117151		JMS	UNSIX
1117	173Ø2	617273		JMP	MACRO-3
1118	173Ø3	4Ø15Ø1	MACR	.SIXBT	' MACRO'
	173Ø4	Ø32217			-
1122	173Ø5	ØØØØØØ	OINIT	Ø	
1123	173Ø6	777773		LAW	-5
1124	173Ø7	Ø56633		DAC	GETPTR
1125	1731Ø	216272		LAC	I8 /REINITIALIZE POINTER
1126	17311	Ø57321		DAC	OPACK+2
1127	17312	216317		LAC	LINBF%
1128	17313	Ø56367		DAC	CHRCNT
1129	17314	77777Ø		LAW	-1Ø /8 LINE NUMBERS P
113Ø	17315	Ø5755Ø		DAC	OFLAG
1131	17316	6373Ø5		JMP*	OINIT

PAGE 3Ø	CREF	Ø18	CREF		
1198	17411	637365		JMP*	OWRITE
1199	17412	637365		JMP*	OWRITE /RETURN
1212	17421	117174		JMS	UNDEC
1213	17422	777775		LAW	-3
1214	17423	Ø56746		DAC	ALPHA
1215	17424	21624Ø		LAC	SPACE
1236	17451	ØØØ766		CAL+766	
1237	17452	ØØØØ12		12	
1238	17453	777713		LAW	-65
1239	17454	Ø56237		DAC	LINCNT
124Ø	17455	637413		JMP*	LINHDR

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
MACRO-15		N/A	18
Subprogram or Additional Information		Sequence #	PAGE
CREF		9	5 OF 5
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

October, 1973

MACRO-15 V7D (EDIT #082)

Leading commas in command string foiled BOSS-15 operation

PROBLEM:

In MACRO V7C, leading commas are not ignored in the input command string. This prevents successful operation under BOSS-15.

SOLUTION:

Using PATCH, make the following binary corrections to MACRO:

<u>LOCATION</u>	<u>OLD CONTENTS</u>	<u>NEW CONTENTS</u>	<u>NEW SYMBOLIC</u>	<u>COMMENTS</u>
7247	154431	JMP 17566	JMP PATCH	/PATCH AREA
17566	Ø	SAD 17572	SAD COMMA	/IS IT A COMMA?
17567	Ø	JMP 7244	JMP CMDSUB-5	/YES-GET CHAR.
1757Ø	Ø	DZM 14431	DZM PRVCHR	/NO, RESTORE
17571	Ø	JMP 725Ø	JMP CMDSUB-1	/AND CONTINUE
17572	Ø	54		/.ASCII FOR COMMA
7461	3Ø64ØØ	4Ø64ØØ		/V7D

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
MACRO-15		V7D	82
Subprogram or Additional Information		Sequence #	PAGE
		1Ø	1 OF 1
New	Replacement Article	Original Date	
<input type="checkbox"/>	<input type="checkbox"/> 1	Pre-1973	



SOFTWARE DISPATCH

DOS-15

October, 1973

MACRO-15 V7E (EDIT #082)

Problem with parameter file name being assigned to listing file

PROBLEM:

MACRO-15 assigns the parameter file name (when present on a file-oriented device) to the listing file on the file-oriented device assigned to DAT-12.

SOLUTION:

Use PATCH to make the following binary corrections to MACRO. Note that the source code notation on the right need not be keyed in. It is shown only for information purposes.

```
PATCH Vxx
>MACRO
>L 17114
>17114/207010>207021      LAC  OUTNAM
>17115/057101>
>17116/207011>207022<ALT> LAC  OUTNAM+1
>L 7461
>07461/406400>506400<ALT> V7E
>EXIT
```

Software Product	Version	
DOS-15	V2A	
Component	Version	Edit #
MACRO-15	V7E	82
Subprogram or Additional Information	Sequence #	PAGE
	11	1 OF 1
New <input type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date
	1	August, 1973



SOFTWARE DISPATCH

DOS-15

October, 1973

CREF V7F (EDIT #016)

Patch to prevent NEXM system crash in an X4K environment

PROBLEM:

When the X-switch option (cross-reference) is used in the MACRO-15 command string input, CREF crashes the system through a NEXM (non-existent memory) reference in systems using 20K or 28K of memory.

SOLUTION:

Use PATCH to make the following binary corrections to CREF and to MACRO. The source code notation to the right need not be keyed in; it is shown for the purpose of illustration.

```
PATCH Vxx
>CREF
>L 15667
>15667/356470>740000<ALT>      NOP
>MACRO
>L 7461
>07461/506400>606400<ALT>     V7F
>EXIT
```

Software Product	Version	
DOS-15	V2A	
Component	Version	Edit #
MACRO-15	V7F	16
Subprogram or Additional Information	Sequence #	PAGE
CREF	12	1 OF 1
<input type="checkbox"/> New	Replacement Article	Original Date
<input type="checkbox"/>	<input type="checkbox"/> 1	August, 1973



SOFTWARE DISPATCH

DOS-15

PRE-1973

MTF. (EDIT #006)

Functional Changes

MTF has been greatly modified. Details are on subsequent sheets. Standard buffer size is 377₈, as returned on .INIT. The user may dynamically change this size by the following instructions:

```
.GLOBL MTBSIZ
.
.
.
LAC      BUFSIZ  /(any desired buffer size)
DAC*    MTBSIZ
.
.
.
.WRITE
.
.READ
```

Thus, since FIOPS re-.INIT's a handler every time I/O transfer direction is changed, one can input from magtape drive N with one record size¹, and output to drive M with another record size, bearing in mind that MTBSIZ must be called before transfer direction is changed.

¹ Record size must be less than or equal 256₁₀ words for FORTRAN .READ's and .WRITE's. Larger record sizes are possible via MACRO routines.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
MAGTAPE HANDLERS		N/A	6
Subprogram or Additional Information		Sequence #	PAGE
MTF.		1	1 OF 7
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	

SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Changes (Cont'd)

.INIT

- A. Return standard buffer size of 255 words. Buffer size can be changed by modifying the .GLOBL MTBSIZ through a call MACRO subroutine.
- B. Call .SETUP - API channel register 48(8).
- C. Setup transfer direction (input or output).
- D. If first .INIT to this device, the assigned default values will be odd parity and 800 BPI. Track count will be specified by bit 6 of SCOM+4 register. (0=7 channel, 1=9 channel).
- E. Update the reference drive table that this unit is open for I/O transfers.

.OPER

- A. .FSTAT is allowed and implemented AC=0 on return.

.SEEK

- A. Undefined. Error return IOPS6.

.ENTER

- A. Undefined. Error return IOPS6.

.CLEAR

- A. Undefined. Error return IOPS6.

.CLOSE

- A. Checks transfer direction. If not output an error return IOPS 6 is issued.
- B. Writes an end-of-file mark and returns to caller.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
MAGTAPE HANDLERS		N/A	6
Subprogram or Additional Information		Sequence #	PAGE
MTF.		1	2 OF 7
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	

SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Changes (Cont'd)

.MTAPE

- A. Honors the subfunction specification as follows:
- ØØ) Rewind: A rewind is issued to the specified drive and control returned to caller.
 - Ø1) Undefined: Error return IOPS6.
 - Ø2) Backspace: A backspace is issued to backspace one physical record.
 - Ø3) Backspace file: Issue backspace until two end-of-file marks have been passed over, then space forward over the last end-of-file mark. If beginning of tape is sensed during the backspacing, the function is terminated and control returned to the caller.
 - Ø4) Write EOF: Issue a write end-of-file mark.
 - Ø5) Forward space: A space forward is issued to forward space one physical record. If the end-of-tape is sensed an error return IOPS65 is issued.
 - Ø6) Forward space file: A space forward is issued to forward space until an end-of-file is sensed. If the end-of-tape is sensed a IOPS65 is issued.
 - Ø7) Space to logical EOT: A space forward is issued until two consecutive

Software Product	Version	
DOS-15	V1A	
Component	Version	Edit #
MAGTAPE HANDLERS	N/A	6
Subprogram or Additional Information	Sequence #	PAGE
MTF.	1	3 OF 7
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date

SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Changes (Cont'd)

end-of-file marks are passed, then a back-space one physical record is issued. If the end-of-tape is sensed a IOPS65 is issued.

- 10→17) Describe the tape configuration. The reference drive table will be updated for the unit referenced. Subsequent I/O transfers will be performed in the density, parity and channel count given below:

<u>Subfunction</u>	<u>Channel Count</u>	<u>Parity</u>	<u>Density</u>
10	7	Even	200 BPI
11	7	Even	556
12	7	Even	800
13	9	Even	800
14	7	Odd	200
15	7	Odd	556
16	7	Odd	800
17	9	Odd	800

.READ

- A. Check if referenced unit is input. Error return IOPS6 issued if not.
- B. Check if data mode is legal. Modes 0 or 2; any other mode is illegal. Error return IOPS7 is issued.
- C. Initiate data transfer.
- D. Read errors:
 1. Parity, checksum and record length incorrect. The appropriate header bits are set and returned to the data buffer.
 2. Bad tape or data late. These are considered unrecoverable tape errors and an error return IOPS65 is issued.
 3. End-of-file. The appropriate header bits are set to a 5 and returned to the data buffer.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
MAGTAPE HANDLERS		N/A	6
Subprogram or Additional Information		Sequence #	PAGE
MTF.		1	4 OF 7
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Changes (Cont'd)

4. End-of-tape. The appropriate header bits are set to a 6 and returned to the data buffer.
5. Any real read error (parity, data late or bad tape) is given 25 rereads before error action is taken.

.WRITE

- A. Check if referenced unit is output. Error return IOPS6 issued if not.
- B. Check if data mode is legal. Modes \emptyset or 2; any other mode is illegal. Error return IOPS7 is issued.
- C. Initiate data transfer.
- D. Write errors:
 1. Any write error is given 25 rewrites. If unsuccessful, six inches of tape are skipped and record rewritten.
 2. End-of-tape. The appropriate leader bits are set to 6 and returned to the data buffer.

.WAIT, .WAITR

- A. Check I/O underway.
 1. Busy: Return to CAL or to address in CAL+2 (.WAITR).
 2. Non-busy: Return to CAL+2 or to CAL+3 (.WAITR).

.TRAN

Allows standard core dump mode (both 7 and 9-track look like 7-track), and true 9-track mode. Bit 9 of LOC+ \emptyset =1 yields true 9-track.

Software Product		Version	
DOS-15		VIA	
Component		Version	Edit #
MAGTAPE HANDLERS		N/A	6
Subprogram or Additional Information		Sequence #	PAGE
MTF.		1	5 OF 7
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	


SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Changes (Cont'd)

9-track data arrives in core with parity bits in bits 0 and 1, and two 8-bit bytes in low-order 16 bits. Thus:



Legal Data Modes

OUTPUT

- A. IOPS BINARY (0). The checksum is completed and stored in the second word of the line in the IOPS buffer area. Bits 12-13 of the first header word are set to zero. The count of words to write is taken from the word pair count in the header and transfer from the IOPS area is initiated.
- IOPS ASCII (2).

INPUT

- A. IOPS BINARY (0). The count of words to transfer is taken from the CAL sequence and input is initiated from the next physical block on tape directly into the IOPS buffer area. When the read is complete, the line validity bits are modified under the following conditions: bits 12-13 of header word 0 are set if buffer overflow occurred. A checksum is calculated and compared with the checksum read. If they differ, bits 12-13 are set to 10. Finally, a check is made to assure that the line was transferred without hardware-detected error. If an error occurred, bits 12-13 are set to 01.
- IOPS ASCII (2).

Software Product	Version	
DOS-15	V1A	
Component	Version	Edit #
MAGTAPE HANDLERS	N/A	6
Subprogram or Additional Information	Sequence #	PAGE
MTF.	1	6 OF 7
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date

SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Changes (Cont'd)

Recoverable Errors

- A. Transport not ready. IOPS4
- Results from:
1. Write request with write lock.
 2. 9-channel I/O request to 7-channel transport, and vice-versa.
 3. Transport off line or otherwise not ready.

Remedy:

1. Ready the device.
2. Type control R on the teletype.

Unrecoverable Errors

- A. Illegal function. IOPS6.
- B. Illegal data mode. IOPS7.
- C. End-of-tape encountered on a file spacing command. IOPS44.
- D. Unrecoverable mag tape error (data late or bad tape). IOPS65.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
MAGTAPE HANDLERS		N/A	6
Subprogram or Additional Information		Sequence #	PAGE
MTF.		1	7 OF 7
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

PRE-1973

MTF. (EDIT #007)Returning status on a .WAIT**PROBLEM:**

Magnetic Tape (MT) handlers which support .WAIT are expected to return MT status in the AC. System programs like MTDUMP utilize this information for proper operation. MTF. 006 did not return the status on a .WAIT.

SOLUTION:

The following SRC modification to MTF. edit #006 corrects this problem.

Page 18

MTF. 007 .WAIT

```
          /COME HERE ON IO COMPLETE.  RETURN TO CAL+2 IF WAIT, TO CAL.
J1000 R 400773 R  MTDONE XCT MTWTSW      /IO FINISHED.  SKIP IF WAIT, NOP IF
01001 R 441232 R          ISZ MTARGP      /WAITR, BUMP TO NON-BUSY RETURN.
01002 R 200051 R          LAC MTSTAT
01003 R 600107 R  MTJDBR  JMP MTDBR      /THEN RETURN THRU MTARGP.
          /
01004 R 741000 A  MTSKIP  SKP
```

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
MAGTAPE HANDLER		N/A	7
Subprogram or Additional Information		Sequence #	PAGE
MTF.		2	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

PRE-1973

RESMON V1A (EDIT #057)

Operational Note: IOPS 77 After Control Q

The SGEN program (DOSGEN) allows users with an RF15 system device to change the CTRL QAREA. Should the user delete the QAREA, any CTRL Q dump would produce disastrous results, by overwriting the disk. The Resident Monitor therefore checks the size of the QAREA before it allows any dumps. If the QAREA is too small for the current core size, the Resident Monitor will give IOPS 77 after any of the following:

A program issues a .GET or .PUT macro

The user tries a manual (CTRL Q) dump

The user tries to restore core, using .SCOM+64

The Resident Monitor will print a number after the IOPS 77. Bits 3-17 of this number will be the desired restart address after the dump or restore which could not be processed.

Software Product	Version	
DOS-15	V1A	
Component	Version	Edit #
MONITOR	V1A	57
Subprogram or Additional Information	Sequence #	PAGE
RESMON	1	1 OF 1
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date



SOFTWARE DISPATCH

DOS-15

PRE-1973

TELEPRINTER HANDLER VIA (EDIT #057)

Operational Note on Overprinting

The teleprinter handler will support double spacing at the FORTRAN level. When FORTRAN outputs a line with its first character equal to zero, the FORTRAN OTS replaces it with a 21 code, which requests a double space. If the FORTRAN output line has a first character equal to +, the OTS routines output a 20 which requests an overprint (no advance).

The teleprinter handler has been modified such that, if the first character in an IOPS ASCII record is an octal 20, the handler will do an overprint (carriage return, with no line feed). If the first character is octal 21, the handler will do a carriage return and two line feeds.

Software Product	Version	
DOS-15	V1A	
Component	Version	Edit #
MONITOR	V1A	57
Subprogram or Additional Information	Sequence #	PAGE
TELEPRINTER HANDLER	2	1 OF 1
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date



SOFTWARE DISPATCH

DOS-15

PRE-1973

DOSNRM V2B (EDIT #060)

Problem in restoring UIC's to DAT slots on LOGOUT

Note: The V2A version of DOS-15 was provided as a tape update rather than as an entirely new system. This is described in document DEC-15-QUDA-D, "DOS-15 V1A UPDATE PROCEDURES".

PROBLEM:

The DOS-15 system provides the user with the capability of assigning UIC's to DAT slots at SGEN time. The system will restore the UFDT to the UIC's assigned at the last system generation in the absence of "KEEP ON" commands.

The above capability was not realizable due to a bug in DOSNRM V2A (edit #061).

SOLUTION:

The following patch corrects this problem.

Software Product	Version	
DOS-15	V2B	
Component	Version	Edit #
MONITOR	V2B	60
Subprogram or Additional Information	Sequence #	PAGE
DOSNRM	3	1 OF 3
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date

SOFTWARE DISPATCH

DOS-15

PRE-1973

Problem in restoring UIC's to DAT slots on LOGOUT (Cont'd)

DOS-15 V2A
\$PATCH

PATCH V10A

>DOS15

>NB

>00236/000033>34

>L 6774

>06774/076004>616035

LOC1

JMP PATCH1

>L 6777

06777/235567>616044

LOC2

JMP PATCH2

>L 7007

07007/060013>616050

LOC3

JMP PATCH3

>L 7012

07012/235567>616053

LOC4

JMP PATCH4

>L 7020

07020/060013>616057

LOC5

JMP PATCH5

>L 7023

07023/235567>616063

LOC6

JMP PATCH6

>L 16024

>16024/000000>14

L14

14

16025/000000>251103

LUIC

251103

16026/000000>141

L141

141

16027/000000>

UFDUP1

0

16030/000000>220014

LAC* 14

16031/000000>556025

SAD (251103

16032/000000>236026

LAC* (141

16033/000000>060013

DAC* 13

16034/000000>636027

JMP* UFDUP1

16035/000000>076004

PATCH1

DAC* (13

16036/000000>217102

LAC NODAT

16037/000000>744020

CLL!RAR

16040/000000>357101

TAD NOPAR

16041/000000>350002

TAD .SGNBLK

16042/000000>076024

DAC* (14

16043/000000>606775

JMP LOC1+1

Software Product		Version	
DOS-15		V2B	
Component		Version	Edit #
MONITOR		V2B	60
Subprogram or Additional Information		Sequence #	PAGE
DOSNRM		3	2 OF 3
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Problem in restoring UIC's to DAT slots on LOGOUT (Cont'd)

```

16044/0000000>116027          PATCH2      JMS UFDUP1
16045/0000000>446770          ISZ  CT1
16046/0000000>616044          JMP  PATCH2
16047/0000000>607003          JMP  LOC2+4
16050/0000000>060013          PATCH3      DAC*  13
16051/0000000>476024          ISZ* (14
16052/0000000>607010          JMP  LOC3+1
16053/0000000>116027          PATCH4      JMS UFDUP1
16054/0000000>446770          ISZ  CT1
16055/0000000>616053          JMP  PATCH4
16056/0000000>607016          JMP  LOC4+4
16057/0000000>060013          PATCH5      DAC*  13
16060/0000000>476024          ISZ* (14
16061/0000000>476024          ISZ* (14
16062/0000000>607021          JMP  LOC5+1
16063/0000000>116027          PATCH6      JMS UFDUP1
16064/0000000>446770          ISZ  CT1
16065/0000000>616063          JMP  PATCH6
16066/0000000>626771          JMP* UFDUP1
> LR 1117
> 01117/631202>631204          V2B
> EXIT
    
```

Software Product		Version	
DOS-15		V2B	
Component		Version	Edit #
MONITOR		V2B	60
Subprogram or Additional Information		Sequence #	PAGE
DOSNRM		3	3 OF 3
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	



SOFTWARE DISPATCH

DOS-15

August, 1973

TELEPRINTER HANDLER V2C (EDIT #064)

Patch to support LA30 at 300 baud

This patch to support LA30 at 300 baud has been revised to suppress echoing of the ALT-MODE (ASCII code 175). The following changes are made by using the "L" command under PATCH.

<u>LOCATION</u>	<u>OLD CONTENTS</u>	<u>NEW CONTENTS</u>		<u>SYMBOLIC</u>
0571	100722	102615		JMS PATCH4
1633	760015	760212	TTLFO	LAW 212
1635	760212	102605	TTOCRT	JMS PATCH
1636	102452	740000		NOP
2252	601635	602577	TTALFO	JMP PATCH2
2451	741000	602602		JMP PATCH3
2504	760015	601635		JMP TTOCRT
2505	601636	740000		NOP
2577	-	760212	PATCH2	LAW 212
2600	-	102452		JMS TTOSVC
2601	-	601637		JMP TTLNFN
2602	-	542547	PATCH3	SAD TTY015
2603	-	602627		JMP PATCH5+1
2604	-	602453		JMP TTYVT3
2605	-	000000	PATCH	0
2606	-	777770		LAW -10
2607	-	042625		DAC TTFLCT
2610	-	760015	TTFLP	LAW 15
2611	-	102452		JMS TTOSVC
2612	-	442625		ISZ TTFLCT
2613	-	602610		JMP TTFLP
2614	-	622605		JMP* PATCH

Software Product		Version	
DOS-15		V2C	
Component		Version	Edit #
MONITOR		V2C	64
Subprogram or Additional Information		Sequence #	PAGE
TELEPRINTER HANDLER		4	1 OF 2
New	Replacement Article	Original Date	
<input type="checkbox"/>	<input type="checkbox"/> 4	Pre-1973	

SOFTWARE DISPATCH

DOS-15

August, 1973

Patch to support LA3Ø at 3ØØ baud (Cont'd)

<u>LOCATION</u>	<u>OLD CONTENTS</u>	<u>NEW CONTENTS</u>		<u>SYMBOLIC</u>
2615	-	ØØØØØØ	PATCH4	Ø
2616	-	77777Ø		LAW -1Ø
2617	-	Ø42625		DAC TTFLCT
262f	-	76ØØ15		LAW 15
2621	-	1ØØ722		JMS TOUT
2622	-	442625		ISZ TTFLCT
2623	-	6Ø262Ø		JMP PATCH4+3
2624	-	622615		JMP* PATCH4
2625	-	ØØØØØØ	TTFLCT	Ø
2626	-	ØØØØØØ	PATCH5	Ø
2627	-	2Ø2452		LAC TTOSVC
263Ø	-	Ø42626		DAC PATCH5
2631	-	1Ø26Ø5		JMS PATCH
2632	-	2Ø2626		LAC PATCH5
2633	-	Ø42452		DAC TTOSVC
2634	-	622452		JMP* TTOSVC
24Ø6	6Ø2441	6Ø2435		JMP TTLNFA-1
1Ø1	-	2635		

The version number is changed from V2B to V2C by making the following changes to the non-resident monitor (DOS-15). Use "LR" command.

1117	6312Ø4	6312Ø6	V2C
------	--------	--------	-----

Bootstrap to refresh core.

Software Product		Version	
DOS-15		V2C	
Component		Version	Edit #
MONITOR		V2C	64
Subprogram or Additional Information		Sequence #	PAGE
TELEPRINTER HANDLER		4	2 OF 2
New	Replacement Article	Original Date	
<input type="checkbox"/>	<input type="checkbox"/> 4	Pre-1973	

SOFTWARE DISPATCH

DOS-15

October, 1973

RESMON V2D (EDIT #064)

Patch to restore system configuration on "LOGOUT"

PROBLEM:

In the current version of the DOS monitor 'V2C' on issuing a "LOGOUT" monitor command the system is not restored to the default (as specified in SGEN) configuration, as stated in the DOS systems manual.

SOLUTION:

The above problem is corrected by the following patch:

```
PATCH V10A
>DOS15 )
>LR 5571
>06720/235601<14452>616020 (ALT)      LOC      JMP      PATCH
>LR 14671 )
>16020/000000>217105 )                PATCH  LAC  SGNBLK+5
>16021/000000>075563 )                DAC* (.SCOM+4
>16022/000000>235601 )                LAC* (152
>16023/000000>606721 (ALT)           JMP  LOC+1
>PS )
>00240/015362>15366 (ALT)
>EXIT )
```

Bootstrap to refresh core. The version number is changed from 'V2C' to 'V2D' by modifying 'location 1117' from '631206' to '631210', before exiting from PATCH. Use 'LR' command.

Software Product		Version	
DOS-15		V2D	
Component		Version	Edit #
MONITOR		V2D	64
Subprogram or Additional Information		Sequence #	PAGE
RESMON		5	1 OF 1
New <input type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	
	1	Pre-1973	



SOFTWARE DISPATCH

DOS-15

October, 1973

RESMON V2D (EDIT #064)

Teletype Handler .INIT function limitations

PROBLEM:

A .INIT issued to the Teletype handler will not cancel a .READ/.WRITE which is in progress.

The reason for this problem is that after the CAL pointer has been saved and the argument pointer bumped, the I/O underway switch (TTIOSW) is tested and, if set, the program loops back to the CAL.

SOLUTION:

.SCOM+35 contains the instruction "DZM TTIOSW". If a program desires to abort teletype I/O, it can merely issue the instruction "XCT* (.SCOM+35)", which will clear out the busy flag. The following is an alternate method for clearing the flag:

```
LAW    -3           /COMPUTE DAT -3
TAD*   (.SCOM+23
DAC    DATM3        /STORE IN TRANSFER VECTOR
LAW    -1           /C(.DAT -3) = TTA
TAD*   DATM3        /TTA. -1 = TTIOSW
DAC    TTIOSW       /STORE IN TV
DZM*   TTIOSW       /CLEAR TTIOSW
```

Software Product		Version	
DOS-15		V2D	
Component		Version	Edit #
MONITOR		V2D	64
Subprogram or Additional Information		Sequence #	PAGE
RESMON		6	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

October, 1973

DOS-15 USERS MANUAL (DEC-15-ODUMA-A-D)

Document Number Change Notice

New #: DEC-15-ODUMA-A-D

Old #: DEC-15-MRDA-D

There has been no change in the contents of the above manual except for a few corrections of minor typographical errors etc., in the manual as listed below:

<u>Page</u>	<u>Change</u>	<u>Comment</u>
1-5	add 'or LA30 DEC Writer' in the 5th line of Section 1.2.2	new console terminal supported by DEC.
2-10	delete 'manipulate and' from the 1st line of Section 2.11.	PIP has limited capabilities with MT.
	add 'DEC' in front of 'tape storage' in item 7 in the same section.	-"-
6-25	change all occurrences of 'wrdcnt' to 'wdc' on this page.	for sake of consistency
6-26	change 'nn' to 'ds' under FORMAT.	typographical error
7-5	change '3' to '1' under 'UNIT #?' in the printout depicted in Section 7.3.1.3.	typographical error

Software Product		Version	
DOS-15		V20	
Component		Version	Edit #
MONITOR		N/A	N/A
Subprogram or Additional Information		Sequence #	PAGE
DOCUMENT CORRECTION		7	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

AUGUST 1973

DOS-15 USER'S MANUAL (DEC-15-ODUMA-A-D)

Documentation error

PROBLEM:

In Section 6.7.11 on page 6-23 in the DOS-15 User's Manual it is claimed that "beg" and "wdc" are ignored by the disk pack handler in the .RTRAN system MACRO call. This is not correct. The "beg" and "wdc" are ignored only on output.

SOLUTION:

The manual should read:

ignored for output to disk pack

instead of reading:

ignored for disk pack

Software Product		Version	
DOS-15		V2D	
Component		Version	Edit #
MONITOR		N/A	N/A
Subprogram or Additional Information		Sequence #	PAGE
DOCUMENTATION CORRECTION		8	1 OF 1
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	



SOFTWARE DISPATCH

DOS-15

October, 1973

DOS-15 VIA UPDATE PROCEDURE (DEC-15-QUDA-D)

Typographical error in patch to PIP

In the patch published for DOSPIP V6B, the new contents of LOC 14744 should be

JMP #+1040

and not

JMP #1040

as stated in the published article.

Software Product	Version	
DOS-15	V2D	
Component	Version	Edit #
MONITOR	N/A	N/A
Subprogram or Additional Information	Sequence #	PAGE
DOCUMENTATION CORRECTION	9	1 OF 1
<input checked="" type="checkbox"/> New	<input type="checkbox"/> Replacement Article	Original Date



SOFTWARE DISPATCH

DOS-15

PRE-1973

PAPER TAPE PUNCH HANDLERS

Difference in End-of-File Code Between ADSS and DOS

The Paper Punch Handlers in the Advanced Software System output the following EOF header on a .CLOSE:

001505
776273

The Handlers for DOS all output the following EOF header:

001005
776773

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
PAPER TAPE PUNCH HANDLERS		N/A	
Subprogram or Additional Information		Sequence #	PAGE
PPA., PPB., PPC.		1	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

PRE-1973

PATCH V1ØA (EDIT #Ø16)

Operation under DOS-15

PATCH V1ØA for DOS release is functionally similar to earlier versions. For patching a disk, PATCH requires the operator to log in under the MIC. If the user fails to do so, PATCH will type:

.DAT-14 NOT PATCHABLE

When patching a disk, PATCH finds the system blocks (SYSBLK and COMBLK) from bits 3-17 of word 2 of the first MFD entry. SYSBLK and COMBLK occupy two contiguous blocks on the DOS-15 system device, and PATCH uses this information when reading or writing these two blocks.

Software Product		Version	
DOS-15		V1A	
Component	Version	Edit #	
PATCH	V1ØA	16	
Subprogram or Additional Information		Sequence #	PAGE
		1	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

PRE-1973

PIP V6A (EDIT #090)

Note on Implicit Data Modes

If implicit data modes are to be used in PIP command strings, certain rules must be followed.

1. It is not possible to mix data modes in one command.

a. T DP ,,+DK FILE1,FILE2,FILE3 (B)

All three files must be binary files with a BIN Extension.

b. T DP ,+DK FILE1 BIN,FILE2 SRC

This is not a legal command string.

2. Files with extensions used by PIP to determine data modes should not actually be of another data mode.

Example:

FILE1 BIN should be a file written in IOPS Binary mode (0 in bits 14-17 of the first header word). It should not, for example, have been written in IOPS ASCII (2 in bits 14-17 of the first header word) and then had its extension changed to BIN.

If such a file is transferred, PIP will put the correct data mode code in the header words. If, however, that file is being transferred in a multiple file string and another follows it, PIP cannot handle the next file correctly.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
PIP		V6A	90
Subprogram or Additional Information		Sequence #	PAGE
		1	1 OF 2
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Note on Implicit Data Modes (Cont'd)

PIP uses the following extensions as data mode indicators:

BIN - IOPS Binary

SRC - IOPS ASCII

ABS - Dump

A number in the third location of the extension (e.g., ABL FZ2) makes PIP assume the file is in IOPS ASCII.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
PIP		V6A	90
Subprogram or Additional Information		Sequence #	PAGE
		1	2 OF 2
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

PIP V6A (EDIT #090)

Restriction on Diskpack to Diskpack copies

PROBLEM:

One cannot use PIP to COPY the contents of a UFD on one pack to another if the UIC's are the same.

>C DP1←DP0 ↵

for example will not work.

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
PIP		V6A	90
Subprogram or Additional Information		Sequence #	PAGE
		2	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

October, 1973

PIP V6B (EDIT #090)

Segmenting files under BOSS-15

PROBLEM:

When using PIP V6A under BOSS-15 to segment files, it was not possible to key in CTRL P as needed. Also, in violation of system convention, PIP would restart itself following an (H) mode COPY command instead of exiting to the monitor.

SOLUTION:

Make the following patches to PIP using the "LR" command to list locations.

<u>LOCATION</u>	<u>OLD CONTENTS</u>	<u>NEW CONTENTS</u>	<u>NEW SYMBOLIC</u>	<u>COMMENTS</u>
1032	633202	633204	V6B	
1040	776	775	-3	/OUTPUT TO -3
1037	154473	JMP #+14736	JMP PATCH	/PATCH AREA
14736	0	DZM #+14473	DZM YEOF SW	/RESTORE INST.
14737	0	LAC* #+14527	LAC* (BOSS	/BOSS REGISTER
14740	0	XOR #+14644	XOR (20000	/IF BIT 4
14741	0	AND #+14644	AND (20000	/IS NOT SET.
14742	0	XOR* #+14527	XOR* (BOSS	/SET IT FOR ↑P
14743	0	DAC* #+14527	DAC* (BOSS	/SAVE IT
14744	0	JMP #+1040	JMP RESTRT+2	/RETURN
13537	776	775	-3	/OUTPUT TO -3
13535	741200	JMP #+14745	JMP PATCH	
14745	0	SNA	SNA	/RESTORE INST.
14746	0	JMP #+1036	JMP RESTRT	
14747	0	LAC* #+14527	LAC* (BOSS	/BOSS REGISTER

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
PIP		V6B	90
Subprogram or Additional Information		Sequence #	PAGE
		3	1 OF 2
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

October, 1973

Segmenting files under BOSS-15 (Cont'd)

<u>LOCATION</u>	<u>OLD CONTENTS</u>	<u>NEW CONTENTS</u>	<u>NEW SYMBOLIC</u>	<u>COMMENTS</u>
14750	Ø	XOR #+14644	XOR (200000	/SET BIT 4
14751	Ø	AND #+14644	AND (200000	/OF .SCOM+52
14752	Ø	XOR* #+14527	XOR* (BOSS	/FOR ↑P
14753	Ø	DAC* #+14527	DAC* (BOSS	/
14754	Ø	JMP #+13537	JMP NUORRE+4	/RETURN
13106	11352Ø	JMP #+14755	JMP PATCH	/PATCH
14755	Ø	JMS #+1352Ø	JMS ZCLOS	/RESTORE
14756	Ø	LAC #+14512	LAC XITFLG	/IS EXIT
14757	Ø	SZA		/FLAG SET?
14760	Ø	JMP #+13107	JMP PIP-3	/NO, RESTART
14761	Ø	JMP #+13571	JMP BOSEXT	/YES, EXIT

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
PIP		V6B	9Ø
Subprogram or Additional Information		Sequence #	PAGE
		3	2 OF 2
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

PIP V6C (EDIT #090)

Patch to Transfer All Files in a 'C' Function

PROBLEM:

In DOSPIP V6B if a COPY command with no switches is typed and there are seventy files to be transferred, only sixty-six files will be transferred.

SOLUTION:

Using the "LR" command to patch PIP, make the following binary corrections.

<u>LOCATION</u>	<u>OLD CONTENTS</u>	<u>NEW CONTENTS</u>	<u>NEW SYMBOLIC</u>
4747	354542	TAD #+7314	TAD LML
1032	633204	633206	V6C

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
PIP		V6C	90
Subprogram or Additional Information		Sequence #	PAGE
		4	1 OF 1
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	



SOFTWARE DISPATCH

DOS-15

PRE-1973

PIP V6D (EDIT #090)

Patch to correct problem in Transferring Multiple Files
from Card Readers

PROBLEM:

PIP V6C will cause the system to hang if an attempt is made to read more than 1 file from the card reader, using the "T" function.

The machine will be in a tight loop.

XXX JMP XXX

The above is due to the fact that the program on reaching an EOF thinks it is reading from a paper tape reader and it waits for the user to type ↑P (indicating presence of new medium) to continue.

SOLUTION:

Use PATCH to make the following binary corrections to PIP. The source code notation to the right is for information only and need not be keyed in.

```
$PATCH
PATCH V10A
>PIP
>LR 5574
>10421/610435<05610>610551 (ALT)    JMP ZEOF
>LR 1032
>03657/633206>633210 (ALT)            V6D
>EXIT
```

Bootstrap to refresh core.

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
PIP		V6D	90
Subprogram or Additional Information		Sequence #	PAGE
		5	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

October, 1973

PIP V6E (EDIT #090)

Patch to Correct Problem with 'N' Function when 'Snn'
Switch Option is Used

PROBLEM:

PIP V6D (Edit #090) does not handle the 'Snn' switch option in an 'N' function properly. This is due to a programming error in the ZS CODE section of the program.

SOLUTION:

The following patch corrects this problem. The source code notation to the right is for information only and need not be keyed in.

```
$PATCH
PATCH V10A
>PIP
>LR 7237
>12064/745200>SNA!CLL!CML
>LR 7243
>12070/612074<07247>JMP #+14762
>LR 14762
>17607/000000>LAC #+14556          LAC (100
>17610/000000>DAC #+14502          DAC DIRBLK
>17611/000000>JMP #+7247          JMP DTCLER
>LR 1032
>03657/633210>633212              V6E
>EXIT
```

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
PIP		V6E	90
Subprogram or Additional Information		Sequence #	PAGE
		6	1 OF 1
New	Replacement Article	Original Date	
<input type="checkbox"/>	<input type="checkbox"/> 1	February, 1973	



SOFTWARE DISPATCH

DOS-15

October, 1973

PIP V7A (EDIT #091)

Problem with 'C' switch option in a 'T' function

PROBLEM:

In DOSPIP the user can use the "C" switch option for a "T" function. This provides him with the capability of converting two or more spaces into tabs.

The above capability was not realizable due to improper handling of the "C" switch option, in DOSPIP V6A.

SOLUTION:

The following SRC level changes correct this problem. Changes are indicated by underscored and enclosed instructions. The print-out of an example which explains the operation of the "C" switch option for a "T" function is provided at the end. Note well that these changes do not encompass the corrections to PIP from the preceding articles and that those patches cannot be made as is to PIP V7A because of the shift in code position.

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
PIP		V7A	91
Subprogram or Additional Information		Sequence #	PAGE
		7	1 OF 3
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

October, 1973

Problem with 'C' switch option in a 'T' function (Cont'd)

PAGE 79

DOSPIP 091

CECHECK: C,E,T SWITCH PROCESSOR.

```

3502      06525 R 000000 A   R1      0
3503      06526 R 346620 R           TAD MQ2
3504      06527 R 054534 R           DAC TEMPQ      /SAVE TO BUMP (MAYBE)
3505      06530 R 741200 A           SNA
3506      06531 R 606542 R           JMP NOTABS      /Q1=Q2: NO T
3507      06532 R 106607 R           JMS OUTBUN     /OUTPUT Q2-Q
3508      006533 R
3509      06533 R 000011 A   LIT11=.
3510      06534 R 214534 R   HT      11
3511      06535 R 740001 A           LAC TEMPQ     /CONVERT # OF TABS
3512      06536 R 354555 R           CMA           /TO A POSITIVE
3513      06537 R 746010 A           TAD (1 /NUMBER
3514      06540 R 740010 A           CLL!RTL /MULTIPLY BY
3515      06541 R 054534 R           RAL           /EIGHT
3516      06542 R 211120 R           DAC TEMPQ     /SAVE TO BUMP TYPPOS
3517      06543 R 741200 A   NOTABS  LAC CNTSW
3518      06544 R 606547 R           SNA
3519      06545 R 206657 R           JMP .+3
3520      06546 R 606560 R           LAC CSET
3521      06547 R 146657 R           JMP TAG1
3522      06550 R 214534 R           DZM CSET     /ZERO, IN CASE WE SE
3523      06551 R 740200 A           LAC TEMPQ     /CHECK IF WE SENT AN
3524      06552 R 606563 R           SZA           /SKIP IF NO
3525      06553 R 206525 R           JMP NOSPC     /YES, DONT SEND ANY
3526      06554 R 740001 A           LAC R1
3527      06555 R 354656 R           CMA
3528      06556 R 046657 R           TAD (11
3529      06557 R 354621 R           DAC CSET
3530      06560 R 740001 A           TAD (-1
3531      06561 R 106607 R   TAG1    CMA
3532      06562 R 000040 A   ONESPI  JMS OUTBUN     /OUTPUT 8-R
3533      06563 R 206617 R   LIT40   40
           NOSPC  LAC TYPPOS
    
```

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
PIP		V7A	91
Subprogram or Additional Information		Sequence #	PAGE
		7	2 OF 3
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

October, 1973

Problem with 'C' switch option in a 'T' function (Cont'd)

```

PAGE 80      DOSPIP 091      CECHECK: C,E,T SWITCH PROCESSOR.

3534      06564 R 354534 R      TAD TEMPO
3535      06565 R 346657 R      TAD CSET
3536      06566 R 046617 R      DAC TYPPOS      /T=T+S (+1
3537      06567 R 146657 R      DZM CSET        /S=0.
3538      06570 R 606466 R      JMP TOUTCH      /GO OUTPUT
3539      06571 R 750001 A      TONESP         CLC
3540      06572 R 606561 R      JMP ONESP1      /OUTPUT ONLY
    
```

DOSPIP V7A

>T TT ←DK PIPTST SRC

```

1234567812345678123456781234567812345678123456781234567812345678
X X   XXX X X   X
      XXX X   X
X X   X   X
X     X     X
X     X     X
    
```

DOSPIP V7A

>T TT ←DK PIPTST (AC)

```

1234567812345678123456781234567812345678123456781234567812345678
X X   XXX X X X
      XXX X   X
X     X     X     X
X     X     X
X     X     X     X
    
```

DOSPIP V7A

>

Software Product DOS-15		Version V2A	
Component PIP		Version V7A	Edit # 91
Subprogram or Additional Information		Sequence # 7	PAGE 3 OF 3
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	



SOFTWARE DISPATCH

DOS-15

PRE-1973

SYSTEM

Conversion from ADSS-15: Programs may not fit

PROBLEM:

When updating ADSS systems to DOS-15 V1A, sometimes the user's programs do not fit. This symptom has several possible causes:

1. The FORTRAN OTS library has grown in average size of routine by about 10-15%.
2. There are a number of core-consuming monitor environmental considerations-
 - LP ON
 - VT ON
 - Size of monitor patch area
 - Size of buffer pool
 - Size of buffers
 - Size of .DAT table

which are not present in ADSS, but can help to exhaust core quickly if not handled properly.

3. The resident monitor itself (RESMON) has grown by approximately (20010) words.

Sometimes this size increase is just enough to force a device handler to be loaded in the second memory field (4K page) instead of the first, leaving a non-obvious hole in low core.

SOLUTION:

If this occurs, enable bank mode operation since it ignores 4K boundaries and loads to 8K bounds.

Software Product DOS-15		Version V1A	
Component SYSTEM		Version N/A	Edit # N/A
Subprogram or Additional Information		Sequence # 1	PAGE 1 OF 1
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	



SOFTWARE DISPATCH

DOS-15

PRE-1973

SYSTEM HARDWARE

Minimum and Optional Hardware for DOS-15 System

The equipment configuration for the utilization of the DOS-15 software facilities includes a PDP-15/20 computer with 16K of memory and at least one DECdisk or Disk Pack.

A. The minimum hardware required by DOS consists of:

PDP-15 with 16K, 18-bit, 800-NS core memory

+KSR-35 or KSR-33 Teleprinter

+PC15 High-Speed Paper Tape Reader and Punch

+KE15 Extended Arithmetic Element

+ TC15 DECTape Control with 1 TU56 Dual DECTape Transport or 2 TU55 DECTape transports

or

+ TC59 Magtape Control with 1 TU10, TU20, or TU30 Magtape Transport (7- or 9-track)

+ RF15 DECdisk control with 1 RS09 DECdisk Drive (262,144 words)

or

+ RP15 Disk Pack Control
1 RP02 Disk Pack Drive (10.24 million words)
1 RP02P Disk Pack

Software Product DOS-15	Version V1A	
Component SYSTEM	Version N/A	Edit # N/A
Subprogram or Additional Information HARDWARE	Sequence # 2	PAGE 1 OF 3
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date

SOFTWARE DISPATCH

DOS-15

PRE-1973

Minimum and Optional Hardware for DOS-15 System (Cont'd)

B. The optional hardware supported by DOS is as follows:

PDP-15 with 32K, 18-bit, core memory

KA15 Automatic Priority Interrupt

KW15 Real Time Clock

FP15 Floating Point Processor

KSR-33 Teleprinter

PC15 High Speed Paper Tape Reader and Punch

TC15 DEctape Control with up to 4 TU56
Dual DEctape Transports or 8 TU55 DEctape
Transports

RF15 DECdisk Control with up to 8 RS09 DECdisk
Drives (262,144 words per drive)

RP15 Disk Pack Control with up to 8 RP02
Disk Pack Drives (10,600,000 words per drive)

TC59 Magtape Control with up to 8 TU10, TU20,
or TU30 Magnetic Tape Transports (7- or 9-
track)

CR03B 200 cpm Reader and Control
or
CR15 1000 cpm Reader and Control

VP15 Point Plotting Display
or
VT15 Graphic Display Processor
with
VT04 Graphic Display Console

Software Product DOS-15	Version V1A	
Component SYSTEM	Version N/A	Edit # N/A
Subprogram or Additional Information HARDWARE	Sequence # 2	PAGE 2 OF 3
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date

SOFTWARE DISPATCH

DOS-15

PRE-1973

Minimum and Optional Hardware for DOS-15 System (Cont'd)

LK35 Keyboard

Line Printers*

LP15C - 1000 lpm, 132 column line

LP15F - 356 lpm, 80 column line

VWA Writing Tablet

*Other line printers supported are the LP15H, LP15J and LP15K, which operate from the LP15F Controller.

Software Product DOS-15	Version V1A	
Component SYSTEM	Version N/A	Edit # N/A
Subprogram or Additional Information HARDWARE	Sequence # 2	PAGE 3 OF 3
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date



SOFTWARE DISPATCH

DOS-15

October, 1973

Radix 50₈ Format

Programming Note

Radix 50₈ is a technique used by the MACRO Assembler and the FORTRAN Compiler to condense the binary representation of symbolic names in symbol tables. It is described in Appendix A of the Linking Loader Utility Manual. The following Radix 50₈ table should be added to the description in the Linking Loader Manual:

Software Product DOS-15	Version V2A	
Component SYSTEM	Version N/A	Edit # N/A
Subprogram or Additional Information	Sequence # 3	PAGE 1 OF 2
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date

SOFTWARE DISPATCH

DOS-15

October, 1973

RADIX 50₈ VALUES

X--		-X-		--X	
A	003100	A	000050	A	000001
B	006200	B	000120	B	000002
C	011300	C	000170	C	000003
D	014400	D	000240	D	000004
E	017500	E	000310	E	000005
F	022600	F	000360	F	000006
G	025700	G	000430	G	000007
H	031000	H	000500	H	000010
I	034100	I	000550	I	000011
J	037200	J	000620	J	000012
K	042300	K	000670	K	000013
L	045400	L	000740	L	000014
M	050500	M	001010	M	000015
N	053600	N	001060	N	000016
O	056700	O	001130	O	000017
P	062000	P	001200	P	000020
Q	065100	Q	001250	Q	000021
R	070200	R	001320	R	000022
S	073300	S	001370	S	000023
T	076400	T	001440	T	000024
U	101500	U	001510	U	000025
V	104600	V	001560	V	000026
W	107700	W	001630	W	000027
X	113000	X	001700	X	000030
Y	116100	Y	001750	Y	000031
Z	121200	Z	002020	Z	000032
%	124300	%	002070	%	000033
.	127400	.	002140	.	000034
0	132500	0	002210	0	000035
1	135600	1	002260	1	000036
2	140700	2	002330	2	000037
3	144000	3	002400	3	000040
4	147100	4	002450	4	000041
5	152200	5	002520	5	000042
6	155300	6	002570	6	000043
7	160400	7	002640	7	000044
8	163500	8	002710	8	000045
9	166600	9	002760	9	000046
#	171700	#	003030	#	000047

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
SYSTEM		N/A	N/A
Subprogram or Additional Information		Sequence #	PAGE
		3	2 OF 2
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

SGEN V1A (EDIT #036)

Relative Positions of the Clock and Line Printer Skip IOT's

PROBLEM:

Disk Pack systems have been supplied with the line printer skip before the clock skip. Under rare circumstances, this will cause the system to hang mysteriously.

SOLUTION:

During System Generation, therefore, the System Manager must ensure that the clock skip, "CLSF", comes before the line printer skip, "LSDF". The rest of the skip chain is in good order.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
SYSTEM GENERATOR		V1A	36
Subprogram or Additional Information		Sequence #	PAGE
		1	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

PRE-1973

UPDATE V1ØA (EDIT #ØØ1)

Note on Program File Extensions

The Linking Loader code (33₈) allows UPDATE to retrieve the extension of the source program for information purposes. UPDATE will print this information when the user specifies the LIST (L) option in the file specification command. If the Linking Loader code 33 is missing from a relocatable binary file, UPDATE will not insert a code 33 or extension.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
UPDATE		V1ØA	1
Subprogram or Additional Information		Sequence #	PAGE
		1	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

PRE-1973

UPDATE V1ØA (EDIT #ØØ1)

Note on G option and FREE Command

G-Option

The GET (G) option is the file specification command option that allows the free command to be legal. The G-option is legal only with the L and S options, and only the FREE (F), END (E) and CLOSE (C) commands are legal.

FREE (F) Command

Frees the named file from the library file, and makes it a separate file on the output device.

FORMAT:

FREE (F) FILENAME <CR> or ALT MODE

The FREE command can only be used with the G-option. If the user gives the FREE command without specifying the G-option, UPDATE will type:

VALID ONLY IN GET MODE

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
UPDATE		V1ØA	1
Subprogram or Additional Information		Sequence #	PAGE
		2	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

PRE-1973

UPDATE V1ØA (EDIT #ØØ1)

Note on Error Conditions

1. If, after a CLOSE command, the named library file is already on the output device, UPDATE will print the following:

NAMED FILE ALREADY ON OUTPUT DEVICE

DO YOU WISH TO CONTINUE (Y/N)

Any response to the above other than:

Y<CR> or YES<CR>

will be interpreted as a "no". If Y or YES, UPDATE will delete the old file and rename the WRK file with the old file's name. If not Y or YES, UPDATE will type:

COMMAND IGNORED

and the user may type in a new CLOSE command with a different file name, a normal close, or exit to the nonresident Monitor.

NOTE: If the user exits back to the monitor, the new or updated file will be present on the output device under a work extension (WRK). If the DOS-15 disk handlers are not being used (e.g., with DECTape), the A-version is required. This is because the new code uses the .FSTAT system macro. If only one file is to be open on DECTape, the "E" or "D" handlers could be used.

2. If, after an INSERT (I) or REPLACE (R) command, the file name (typed) and the program name (in the binary

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
UPDATE		V1ØA	1
Subprogram or Additional Information		Sequence #	PAGE
		3	1 OF 5
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Note on Error Conditions (Cont'd)

code) are not the same, and the device on .DAT-10 is a directoried (file-oriented) device, UPDATE will print the following:

```
PROGRAM NAME DISCREPANCY
FILE NAME -- (name)
PROGRAM NAME -- (name)
SOURCE EXT -- (extension)
DO YOU WISH TO ACCEPT COMMAND (Y/N)
```

Any response to the above, other than:

Y <CR> or YES <CR>

will be considered a "NO", and UPDATE will type:

COMMAND IGNORED

If Y or YES, UPDATE will type:

DO YOU WISH TO USE FILE NAME (Y/N)

In the user's response, UPDATE follows the same conventions in determining a YES or a NO. If NO, UPDATE will use the program's name. In either case, UPDATE will type:

SOURCE EXT WANTED

The user should then type zero-to-three characters, and terminate with a carriage return. If the user types a carriage return only, then the extension will be omitted from the program unit. The extension must be made up of legal RADIX 50 characters.

Software Product DOS-15		Version V1A	
Component UPDATE		Version V10A	Edit # 1
Subprogram or Additional Information		Sequence # 3	PAGE 2 OF 5
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	

SOFTWARE DISPATCH

DOS-15

PRE-1973

Note on Error Conditions (Cont'd)

- 2-b. After an INSERT (I) or REPLACE (R) command, if the file name (typed) and the program name (in the binary code) are not the same, and the device on .DAT-1Ø is not a directoried (i.e., non-file oriented) mass storage device, UPDATE will print:

```
PROGRAM NAME DISCREPANCY
FILE NAME -- (name)
PROGRAM NAME -- (name)
SOURCE EXT -- (extension)
DO YOU WISH TO CHANGE INPUT (Y/N)
```

The convention for yes and no answers is as above.

If yes, UPDATE will type:

```
CHANGE INPUT AND ↑P
```

If no, UPDATE will type:

```
DO YOU WISH TO USE FILE NAME (Y/N)
```

A yes reply will update the library with the file name; a no will cause UPDATE to use the program's name.

In either case, UPDATE will then type:

```
SOURCE EXT WANTED
```

The user should then type zero-to-three characters, and terminate with a carriage return. If the user types a carriage return only, the extension will be omitted from the program unit. The source extension must be made up of legal RADIX 5Ø characters.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
UPDATE		V1ØA	1
Subprogram or Additional Information		Sequence #	PAGE
		3	3 OF 5
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Note on Error Conditions (Cont'd)

NOTE: In the case of discrepancy between typed name and binary name, the sense of the questions for directoried devices (DEctape, disk and some Magtape) is opposite to that for non-directoried devices (paper tape reader, and some Magtape). Thus, a NO for a directoried device has the effect of a YES for the non-directoried devices. The user should therefore read the questions carefully.

2-c. More information on REPLACE and INSERT

If the secondary input device (.DAT-1Ø) is a directoried device (that is, file-oriented), UPDATE will now do a .FSTAT for the file name in the command string for REPLACE or INSERT. If the file is not found, UPDATE will type:

FILE NOT FOUND
COMMAND IGNORED

If the secondary input device is not a directoried device (non-file oriented), and the first buffer of the unit to be inserted contains an End-of-File or End-of-Medium header word pair, UPDATE will type:

PGM UNIT NOT FOUND
FILE POSITIONING COMPLETED
COMMAND IGNORED

3. If UPDATE discovers that the file named in a FREE command is already on the output device, it types the following message:

NAMED FILE ALREADY ON OUTPUT DEVICE
DO YOU WISH TO CONTINUE (Y/N)

Software Product DOS-15		Version V1A	
Component UPDATE		Version V1ØA	Edit # 1
Subprogram or Additional Information		Sequence # 3	PAGE 4 OF 5
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	

SOFTWARE DISPATCH

DOS-15

PRE-1973

Note on Error Conditions (Cont'd)

If the answer is Y or YES, UPDATE will delete the file already present on the output device, and write the one derived from the object library. The object library itself is not affected. If the answer is not Y or YES, UPDATE types:

COMMAND IGNORED

4. If, after a FREE command is made, UPDATE cannot find the named file in the library, UPDATE will type:

EOF REACHED BY SEARCH

5. If, after a FREE command is made, UPDATE finds the named file, but cannot find the .END Linking Loader code (27_g) within the named file, UPDATE will print:

END OF FILE FOUND

which indicates the library is no longer valid.

Software Product DOS-15	Version V1A	
Component UPDATE	Version V10A	Edit # 1
Subprogram or Additional Information	Sequence # 3	PAGE 5 OF 5
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date



SOFTWARE DISPATCH

DOS-15

October, 1973

UPDATE V10B (EDIT #002)

Why V10B and not V11A

PROBLEM:

A new source level version of UPDATE was distributed with the second of the updates to the DOS-15 system as described in DEC-15-ODUDA-B-D, "DOS-15 Update, Number 2". The source file name is UPDATE 002. According to the rules for assigning program version numbers a source file change should have caused the version number to go from V10A to V11A; instead, the source was edited to print V10B, which indicates erroneously that there has been a patch.

SOLUTION:

This discrepancy, which has no operational effect, will be corrected in the next release of the software.

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
UPDATE		V10B	2
Subprogram or Additional Information		Sequence #	PAGE
		4	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

February, 1973

UPDATE V10C (EDIT #002)

Patch to correctly read the EOF/EOM record

PROBLEM:

UPDATE V10B detects a record with linking loader code 27 as the last record, instead of the record with EOF/EOM. As a result when secondary input is from a papertape, the record with the EOF/EOM is not read.

SOLUTION:

The following patch to UPDATE corrects this problem.

```
DOS-15 V2A
$MICLOG SYS
$PATCH
PATCH V10A
>UPDATE
>L 16047
>16047/000770>114710      JMS READ      /READ. EOF/EOM?
>16050/000006>617573     JMP PATCH     /YES. CLOSE FILE & EXIT
>16051/152546>616000     JMP WRONGP    /NO. REPORT TO USER
>L 16421
>16421/410320>414320     /V10C
>L 17573
>17573/000000>770  PATCH CAL+770  /CLOSE INPUT
>17574/000000>6        6
>17575/000000>152546    DZM SRCEXT   /RESET FILE EXT
>17576/000000>635744    JMP* INSUNT  /DONE-EXIT
>EXIT
```

Software Product		Version	
DOS-15		V2A	
Component		Version	Edit #
UPDATE		V10C	2
Subprogram or Additional Information		Sequence #	PAGE
		5	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

PRE-1973

ROTATE (SRC)

Functional Description

The Linking Loader allows the VT handler to reside in IOS. There are two new calls to the graphics software: ROTATE and CIRCLE.

ROTATE modifies a user's array so that he may plot a three dimensional figure. A single call to ROTATE will effect a rotation about one or more of the X, Y or Z axes. A rotation about any other axis will require one or two more calls to rotate. Note that ROTATE uses the same left-handed system that the rest of the Graphics Software uses. That is, origin at the center of the screen, X horizontal, positive to the right, Y vertical, positive up, and Z = YxX (positive into the screen). Systems with a different origin will require a translation followed by the rotation(s) followed by a retranslation.

Programmers should use ROTATE carefully. A rotation of a large figure in the X-Y plane about the Z-axis, for example, may cause part or all of the figure to disappear. This will happen whenever one end-point of a line passes off the screen. The cautious programmer will save the original buffer before calling ROTATE, and be prepared to reduce the size of the figure, should a rotation destroy parts of the picture.

Software Product DOS-15	Version V1A	
Component VT15 GRAPHICS	Version N/A	Edit # SRC
Subprogram or Additional Information ROTATE	Sequence # 1	PAGE 1 OF 3
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date

SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Description (Cont'd)

Here are the FORTRAN and MACRO formats for calls to ROTATE:

FORTRAN:

```
CALL ROTATE(ISTR, IA, IB, IC, X, Y, Z, SINA, CSA)
```

MACRO:

```
.GLOBL    ROTATE
JMS*     ROTATE
JMP      .+12
.DSA     ISTR
.DSA     IA
.DSA     IB
.DSA     IC
.DSA     X
.DSA     Y
.DSA     Z
.DSA     SINA
.DSA     CSA
```

The input variables for ROTATE are as follows:

1. ISTR is the array length, in locations.
2. IA specifies whether rotation about the z axis is desired.
If IA=1, rotation will occur about the z-axis.
If IA=0, there will be no rotation about the X-axis.
3. IB specifies whether rotation about the Y-axis is desired.
IB=1 indicates rotation is desired, as with IA.
4. IC specifies whether rotation about the X-axis is desired.
IC=1 indicates rotation is desired, as with IA.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
VT15 GRAPHICS		N/A	SRC
Subprogram or Additional Information		Sequence #	PAGE
ROTATE		1	2 OF 3
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Description (Cont'd)

5. X is the name of the X array.
6. Y is the name of the Y array.
7. Z is the name of the Z array.
8. SINA is the sine of the angle of rotation.
9. CSA is the cosine of the angle of rotation.

Restrictions:

The values in the user's array must be in floating point format.

The user must calculate the sine and cosine of the angle of rotation before he calls ROTATE.

It is up to the user to change integers into floating point numbers and make the correct calls for displaying the rotated figure.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
VT15 GRAPHICS		N/A	SRC
Subprogram or Additional Information		Sequence #	PAGE
ROTATE		1	3 OF 3
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

DOS-15

PRE-1973

CIRCLE (SRC)

Functional Description

The CIRCLE subroutine will construct approximations of arcs and circles as subpictures. (The approximations are really a series of chords. The user may specify how long the chords should be.) The user may subsequently display such subpictures with the proper calls to the handler. The subpicture will be at the array named in the call.

Here is the form for calls to CIRCLE:

FORTTRAN:

```
CALL CIRCLE (R, THETA, GAMA, DEG, PNAME)
```

MACRO:

```
.GLOBL      CIRCLE
JMS*        CIRCLE
JMP          .+7
.DSA        R
.DSA        THETA
.DSA        GAMA
.DSA        DEG
.DSA        PNAME
```

The input variables for CIRCLE are as follows:

1. R is the radius of the circle, in Raster units.
2. THETA is the start of the arc in degrees from the X-axis, rotating counter clockwise about the center of the screen.
3. GAMA is the end of the arc in degrees from the X-axis, rotating counter clockwise about the center of the screen.

Software Product DOS-15		Version V1A	
Component VT15 GRAPHICS		Version N/A	Edit # SRC
Subprogram or Additional Information CIRCLE		Sequence # 2	PAGE 1 OF 2
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date	

SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Description (Cont'd)

4. DEG is the chord length, in degrees.
5. PNAME is the name of the location at which CIRCLE will start the new array.

NOTE:

1. Circles will only be produced if $GAMA-THETA=360^\circ$.
2. The array at PNAME will be as long as there are chords in the constructed arc. That is, the length at the array PNAME will equal the number of chords required to construct the arc--one chord per element.

Software Product	Version	
DOS-15	V1A	
Component	Version	Edit #
VT15 GRAPHICS	N/A	SRC
Subprogram or Additional Information	Sequence #	PAGE
CIRCLE	2	2 OF 2
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date

SOFTWARE DISPATCH

DOS-15

PRE-1973

VWA. (EDIT #0000)

Functional Description

The device handler for the VW01 Sonic Digitizer Writing Tablet provides an interface between the user and the hardware. In general it conforms to the conventions of the Disk Operating System* as described in Disk Operating System, DEC-15-MZDA-D (prelim). Initialize and input functions are initiated by standard user program commands (system macros). The primary goal of the device handler is to relieve the user from writing his own device handling subprograms.

1. .INIT (INITIALIZE) MACRO

The macro .INIT causes the Writing Tablet to be initialized and must be given prior to any other I/O command referencing this device.

The action taken by the .INIT software is the clearing of one software and two hardware flags. These flags are:

- 1) Handler busy flag /Software
- 2) Data Ready flag /Hardware
- 3) Pen Data flag /Hardware

The form is: .INIT [-]ds

where: ds = .DAT slot number

The expansion is:

LOC+0 CAL [-]ds&777
LOC+1 1 /Function code for .INIT
LOC+2 000000
LOC+3 000000

*VW01 will work in an Advanced Monitor Software System, as well.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
WRITING TABLET HANDLER		N/A	0
Subprogram or Additional Information		Sequence #	PAGE
VWA.		1	1 OF 5
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15


PRE-1973

Functional Description (Cont'd)

2. .READ MACRO

The .READ macro is used for input to the user from the Writing Tablet. The input always consists of one status word and two words containing the X and Y coordinates respectively.

The status word has the following format:



SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Description (Cont'd)

The expansion is:

```
LOC+0    CAL+10000*m1[-]ds&777
LOC+1    10 /Function code for .READ
LOC+2    bufadd
LOC+3    -w
```

3. .WAIT MACRO

The .WAIT macro is only used with respect to the .READ. If a .WAIT is given the user program waits until the .READ has completed--that is, when the line buffer is filled and again available for the user program. If the line buffer is available, control is returned to the user immediately after the .WAIT macro expansion (LOC+2). If the input of data has not yet been completed, control loops on the .WAIT macro.

The form is: .WAIT₁[-]ds

where ds = .DAT slot number

The expansion is:

```
LOC+0    CAL1[-]ds&777
LOC+1    12 /Function code for .WAIT
```

4. .WAITR MACRO

The .WAITR macro is only used with respect to the .READ. If the previous .READ is completed, control is returned to the user immediately after the .WAIT in order to proceed in line. If the input of data has not yet been completed, however, control is given to the location in the user program specified by the .WAITR call.

The form is: .WAITR₁[-]ds,waitad

Software Product		Version	
DOS-15		VIA	
Component		Version	Edit #
WRITING TABLET HANDLER		N/A	0
Subprogram or Additional Information		Sequence #	PAGE
VWA.		1	3 OF 5
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Description (Cont'd)

where: ds = .DAT slot number
waitad = location in the user program to
which control must be transferred
if input is not completed.

The expansion is:

LOC+0 CAL+1000▣[-]ds&777
LOC+1 12 /Function code for .WAITR
LOC+2 waitad

5. .FSTAT MACRO

The .FSTAT macro has meaning only for directoried (i.e., file oriented) devices. On return, the AC will contain zero and bits 0 - 2 of LOC+2 will also be zero, stating that the device was non-file oriented.

The form is: .FSTAT▣[-]ds,namptr

where: ds = .DAT slot number
namptr = address of the first of three words
containing the .SIXBT representation
of the name and extension of a file.

The expansion is:

LOC+0 CAL+3000▣[-]ds&777
LOC+1 2 /Function code for .FSTAT
LOC+2 namptr

6. .CLOSE MACRO

When action has been initiated (.INIT and .READ), it must be terminated via the .CLOSE macro. The hardware flags (Data, Ready and Pen Data) will be cleared and the writing tablet(s) will be disabled in order to prevent illegal interrupts.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
WRITING TABLET HANDLER		N/A	0
Subprogram or Additional Information		Sequence #	PAGE
VWA.		1	4 OF 5
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

DOS-15

PRE-1973

Functional Description (Cont'd)

The form is: .CLOSE [-]ds

where: ds = .DAT slot number

The expansion is:

LOC+0 CAL [-]ds&777
LOC+1 6 /Function code for .CLOSE

7. IGNORED FUNCTIONS

The following macros are ignored by the device handler for the VW01 Writing Tablet:

1. .SEEK
2. .ENTER
3. .CLEAR
4. .MTAPE
5. .WRITE
6. .TRAN
7. .DELETE
8. .RENAM

8. INTERACTIVE ROUTINES FOR VW01 AND VT15

In the Writing Tablet handler no tests are made on the incoming X and Y coordinates. All coordinates are directly transferred to the user. This means that if the pen stays on the same spot (Data Input mode) or is pushed on the same spot for more than once (Single point mode) the same X and Y coordinates are transferred to the user. He must not transfer these X and Y coordinates directly to the VT-handler because a hole could be burned in the display screen. For this reason, it is the user's responsibility to test for consecutive X and Y coordinates on one and the same spot. The number of times the same coordinates could be accepted depends on the intensity.

Software Product		Version	
DOS-15		V1A	
Component		Version	Edit #
WRITING TABLET HANDLER		N/A	Ø
Subprogram or Additional Information		Sequence #	PAGE
VWA.		1	5 OF 5
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		



SOFTWARE DISPATCH

BOSS-15

PRE-1973

NRBOSS V1B (EDIT #052)

Patch to correct problems in closing Run Time Files & MICLOG being active on exit from BOSS-15

PROBLEM:

On exit from BOSS via an EOF card the system was restored under the MICLOG regardless of the state of the system when BOSS was entered. As a result of this the system was unprotected (any user could modify the system, delete files, etc.).

A \$ card which was supposed to close all Run Time Files (RTF) did not do so. This was due to the mixup between the card image expected by the routine that decodes the card and the routine that reads the card in NRBOSS. A card with just the \$ sign in column 1 gets mapped into \$ sign followed by a "carriage return". The routine that decodes the card was erroneously expecting to see a card image of \$ sign followed by a "space".

SOLUTION:

Use PATCH as shown below to make binary corrections to BOSS-15. This ensures that the system is restored to the user mode under the UIC that was current when BOSS was entered. Hence, it is not necessary for users to logout on exit from BOSS in case they entered it under the MICLOG. Users have to make note that they have to do a fresh login on exit from BOSS if they want to do privileged operations.

Software Product BOSS-15	Version V1B	
Component MONITOR	Version V1B	Edit # 52
Subprogram or Additional Information NRBOSS	Sequence # 1	PAGE 1 OF 2
New <input checked="" type="checkbox"/>	Replacement Article <input type="checkbox"/>	Original Date

SOFTWARE DISPATCH

BOSS-15

PRE-1973

Patch to correct problems in closing Run Time Files & MICLOG being active on exit from BOSS-15 (Cont'd)

```
$PATCH )  
PATCH V10A  
>BOSS15 )  
>L 3273 )  
>03273/541043 > 541003 (ALT) PATCH2 SAD CR  
>L 5732 )  
>05732/777762 > 206271 (ALT) PATCH1 LAC PLIT1  
>L 6271 )  
>062710000000 > 377762 (ALT) PLIT1 377762  
>L 1703 )  
>01703/106400 206400 (ALT) V1B  
EXIT )
```

Bootstrap to refresh core.

Software Product	Version	
BOSS-15	V1B	
Component	Version	Edit #
MONITOR	V1B	52
Subprogram or Additional Information	Sequence #	PAGE
NRBOSS	1	2 OF 2
New	Replacement Article	Original Date
<input checked="" type="checkbox"/>	<input type="checkbox"/>	

SOFTWARE DISPATCH

BOSS-15

October, 1973

NRBOSS V1C (EDIT #052)

Patch to correct problem in assigning non-default file names in \$CRT and \$ADD procedure files

PROBLEM:

NRBOSS V1B does not permit usage of non-default file names in \$CRT and \$ADD procedure files.

SOLUTION:

The following patch corrects this problem:

\$PATCH

```
>BOSS15
>L 2602
>02602/200664>
  02603/741200>
  02604/602622>
  02605/777766>
  02606/040442>
  02607/200557>106035      JMS  GT.CHR
  02610/105740>501035      CR.LOP  AND  L77
  02611/541051>541003      SAD   CR
  02612/602624>
  02613/741200>541043      SAD   SPACE
  02614/102770>741000      SKP
  02615/105776>
  02616/105747>106035      JMS  GT.CHR
  02617/440442>
  02620/602611>602746<ALT>  JMP   CR.LOP
>L 2743
  02743/777766>
  02744/040442>
  02745/200557>106035      JMS  GT.CHR
```

Software Product		Version	
BOSS-15		V1C	
Component		Version	Edit #
MONITOR		V1C	52
Subprogram or Additional Information		Sequence #	PAGE
NRBOSS		2	1 OF 2
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

BOSS-15

October, 1973

Patch to correct problem in assigning non-default file names in \$CRT and \$ADD procedure files (Cont'd)

```
02746/105740>501035    EN.LOP    AND    L77
02747/541051>541003    SAD     CR
02750/602762>
02751/741200>541043    SAD     SPACE
02752/102770>741000    SKP
02753/105776>
02754/105747>106035    JMS     GT.CHR
02755/440442>
02756/602747>602746<ALT>    JMP     EN.LOP
>L 1703
>01703/206400>306400<ALT>    VLC
>EXIT
```

Software Product		Version	
BOSS-15		V1C	
Component		Version	Edit #
MONITOR		V1C	52
Subprogram or Additional Information		Sequence #	PAGE
NRBOSS		2	2 OF 2
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

BOSS-15

February, 1973

BOSS-15 VIA PROCEDURE FILES

Correction to FOR and ASM to permit usage of the default file name

PROBLEM:

BOSS-15 permits users to use the default file name 'FILTMP' in the \$FOR and \$ASM cards. This is not possible due to a bug in both these procedure files.

SOLUTION:

The following edit change corrects this problem.

```
$MICLOG SYS
$PIP
DOSPIP V6C
>T { DP } , { DP } <CTP> FOR PRC,ASM PRC (A)
   { DK } , { DK }
DOS-15 V2A
$EDIT
EDITOR V18A
>OPEN FOR PRC
EDIT
>L @A
@AØØ () @
>C / (/ (FILTMP
@AØØ (FILTMP) @
>C
EDITOR V18A
>OPEN ASM PRC
EDIT
>L @A
@AØØ () @
>C / (/FILTMP
@AØØFILTMP) @
>E
```

Software Product		Version	
BOSS-15		V1A	
Component		Version	Edit #
PROCEDURE FILES		N/A	
Subprogram or Additional Information		Sequence #	PAGE
FOR PRC, ASM PRC		1	1 OF 2
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		

SOFTWARE DISPATCH

BOSS-15

August, 1973

BOSS-15 VIA PROCEDURE FILES

Correction to JOB procedure file to permit usage of default UIC

PROBLEM:

BOSS-15 permits users to use the default 'SRC' UIC in the \$JOB command card. This is not possible due to an error in the \$JOB procedure file.

SOLUTION:

The following edit change corrects this problem.

```
$A { DK } <CTP> -14
    { DP }
$EDIT
EDITOR V18A
>OPEN JOB PRC
EDIT
>F N
N @D11()@ <SCR> @D14()@
>C /SCR/@AØ2(SRC)@
N @D11()@ <@AØ2(SRC)@>D14()@
>E
```

Software Product		Version	
BOSS-15		VIA	
Component		Version	Edit #
PROCEDURE FILES		N/A	
Subprogram or Additional Information		Sequence #	PAGE
JOB PRC		2	1 OF 1
New	Replacement Article	Original Date	
<input checked="" type="checkbox"/>	<input type="checkbox"/>		





