SERVICE MANUAL

Color Video Monitor

ZVM-130



585-121-2

The purpose of this page is to make sure that all service bulletins are entered in this manual. When a service bulletin is received, mark the manual and list the information in the record below.

Record of Field Service Bulletins

SERVICE BULLETIN NUMBER	DATE OF ISSUE	CHANGED PAGE(S)	PURPOSE OF SERVICE BULLETIN	INITIALS
			·	

LIMITED RIGHTS LEGEND

Contractor is Zenith Data Systems Corporation of St. Joseph, Michigan 49085. The entire document is subject to Limited Rights data provisions.

Copyright © 1986 by Zenith Data Systems Corporation Printed in the United States of America

Zenith Data Systems Corporation St. Joseph, Michigan 49085

WARNINGS and CAUTIONS

IMPORTANT SAFETY NOTICE: Under no circumstances should the original design be modified or altered without permission from Zenith Electronics Corporation. All components should be replaced only with types identical to those in the original circuit, and their physical location, wiring, and lead dress must conform to the original layout upon completion of repairs.

In some instances, redundant circuitry is used for additional circuit protection and X-radiation protection. Special circuits are also used to prevent shock and fire hazard. These special circuit components contain an X in their reference designator (CX501 is an example). They are to be replaced with identical components only.

WARNING: No work should be attempted on any part of the chassis by anyone not familiar with Zenith service procedures and precautions. Otherwise, personal injury may result.

WARNING: External isolation transformers should always be used when test equipment is connected to the monitor. This is to reduce a lethal shock hazard, monitor damage, and test equipment damage that could result from the monitor and/or test equipment chassis being connected to different sides of the AC line.

WARNING: Do not operate a monitor with excessive high voltage because the monitor will produce X-rays from the CRT when the high voltage is excessive. Always verify that the high voltage is at the normal level when servicing the unit.

WARNING: Discharge the high voltage at the anode lead of the CRT before attempting service on the high voltage supply or associated circuits. Refer to the servicing section of this manual for detailed instructions.

WARNING: The CRT and the attached CRT board loses support once the back cover is removed. Use extra care when repositioning the monitor. Turn the power off and disconnect the power cord before attempting to reposition the monitor.

WARNING: Handle the cathode-ray tube carefully when you hold, remove, or install it; otherwise implosion and/or personal injury may result.

WARNING: To prevent electrical shock after reassembly, perform an AC leakage test on all exposed metal parts of the monitor. Do not use a line isolation transformer to perform this test.

Any leakage voltage measurement that exceeds 0.75 volts rms (0.5 milliamperes AC) constitutes a potential shock hazard and must be corrected. These voltage and current values are based upon the following test meter circuit (Figure 1) and the following test instructions.

- 1. Connect the test circuit as shown in Figure 1.
- 2. With monitor power turned on, measure the leakage voltage between earth ground and an exposed monitor metal part.
- Repeat the measurement with the meter leads reversed.
- Repeat steps 2 and 3 until all exposed monitor metal parts are verified to have satisfactory AC leakage levels.




Figure 1
AC Leakage Voltmeter Circuit

WARNING: Unplug the monitor's power cable before cleaning; otherwise, electrical shock and/or personal injury may result.

WARNING: Removing or lifting the ground from the AC power source may present a lethal shock hazard.

CAUTION: The monitor must be located in an area that will provide proper ventilation. Inform the user that the air vents at the bottom, back, and top of the monitor must not be blocked.

CAUTION: Be sure the signal and power cables are unplugged from the computer or other signal and power sources before disassembling the monitor.

CAUTION: Some of the ICs (integrated circuits) used in this unit are electrostatic-sensitive devices. These devices can be damaged by static electricity. When handling any IC, be sure to equalize the static charge before touching the IC, by using a grounding strap.

Contents

Chapter 1: Characteristics	Video Output Module (70) 5-2
Description	Interface Module (85) 5-2
Controls, Indicators, and Connectors 1-1	Power Supply Board (65) 5-2
Specifications	Power Supply Assembly (65) 5-3 CRT (105)
Chapter 2: Installation 2-1	
Chanter C. Circuit Percuinting	Chapter 6: Parts List 6-1
Chapter 3: Circuit Description 3-1	
Power Supply Assembly	Flaures
AC Power	Figures
Degaussing Circuit	d.d. Manitan Frank Views
+150 VDC Supply	1-1: Monitor Front View
Sweep Module	1-2: Monitor Rear View
Power Supplies	44 40 1 1 2 2 1 1 1 2 2 2 2
Sweep Circuits	4-1: AC Leakage Voltmeter Circuit 4-1
Interface Module	4-2: Adjustments-Rear View 4-4
Video Signals	4-3: Interlace Display
Sync	4-4: Monitor Block Diagram (Fold Out) 4-7
Audio	4-5: Interface Module Component Location and
Video Output Board	Waveforms (Fold Out) 4-8
Circuit Board Pinouts 3-3	4-6: Interface Module Schematic (Fold Out) . 4-9
	4-7: Sweep Module Component Location (Fold Out)
Chapter 4: Servicing 4-1	
Safety and Service Guidelines	4-8: Sweep Module Waveforms (Fold Out) . 4-10
AC Leakage Test 4-1	4-9: Sweep Module Schematic (Fold Out) 4-11
Other Precautions	4-10: Power Supply Assembly Major Components
Suggested Equipment and Supplies 4-2	(Fold Out)
Tools and Supplies 4-2	4-11: Power Supply Module component Location
Test Equipment	4-12
Troubleshooting 4-2	4-12: Power Supply Assembly Schematic (Fold Out)
Adjustments	4-13
Interface Module 4-3	4-13: Video Output Module Component Location
Sweep Module	(Fold Out) 4-14
Fill the Screen Test 4-6	4-14: Video Output Module Waveforms (Fold Out)
Cleaning Procedure	4-14
Servicing Diagrams	4-15: Video Output Module Schematic 4-14
Waveform Photograph Explanations 4-7	4-16: Secondary Control Panel Component Location
	4-15
Chapter 5: Disassembly/Reassembly 5-1	4-17: Secondary Control Panel Schematic 4-15
Back Cover (10) 5-1	4-18: Primary Control Board Component Location
Top Cover (20) 5-1	4-16
Input Panel (40) 5-1	4-19: Primary Control Board Schematic 4-16
Cabinet Front (150) 5-1	4-20: Input Panel Component Location 4-17
Primary Control Panel (125) 5-1	4-21: Input Panel Schematic 4-17
Secondary Control Panel (135) 5-2	
Speaker (115)	6-1: Exploded View (Fold Out) 6-9
Sweep Module (77) 5-2	

Tables

3-1:	Interface Module Pinouts 3-	3 6-4:	9-155-25 Video Output Module	6-5
	Sweep Module Pinouts 3-4		9-391 Sweep Module	6-5
	Video Output Module Pinouts 3-4		A-13284 Heat Sync Assembly	6-8
	•		A-12842 Capacitor and Cable Assembly.	
4-1:	General Troubleshooting 4-3		9-293-03 Power Supply Module	
	3		A-9522-06 Secondary Control Panel	
6-1:	Monitor Major Assembly 6-		A-13042 Primary Control Board	
	Monitor Cables 6-2		A-13444 Input Panel	
	9-390 Interface Module 6-2		•	

Characteristics

Description

The Zenith ZVM-130 is a medium resolution color monitor with 25 lines and 40 characters per line. The ZVM-130 accepts composite video, chroma, and luma inputs. A green only switch is provided for reduced eye strain. The ZVM-130 features automatic color processing and stabilizing circuits which eliminate the need for vertical hold and horizontal hold panel controls.

Controls, Indicators, and Connectors

Refer to Figures 1-1, 1-2, and 4-2 for locations of the following controls, indicators, and connectors.

Front Panel

Power Switch

Color Level

Power Indicator

Green/White Switch

Volume

Tint

Display Drive Black Level Sharpness

Noise Processor Switch

Rear Panel

Focus Adjustment Hi-Z/75 Ohm Switch Luma In Connector Audio In Connector

Comp Video Out Connector Comp Video Chroma In

Connector

Internal

Interface

Width

Vertical Centering

G2

Vertical Hold

Red Background

Vertical Size

Green Background Blue Background

Horizontal Centering Horizontal Hold

3.58 MHz Trap

Linearity (Horizontal)




Figure 1-1
Monitor Front View




Figure 1-2
Monitor Rear View

Specifications

Text Capacity	13"(330 mm), 90 degree deflection, .63 mm pitch stripe mask. Negative matrix, P-22 pigmented phosphor. 25 lines of 40 characters. 250 lines horizontal × 240 lines vertical (non-interlaced). 480 lines (interlaced). Video (COMP/CHROMA In) 1 V (P-P) NTSC standard composite video. Luma 1 Volt (P-P) NTSC standard composite. Audio — 0.3 to 1.0 Volts RMS.
Bandwidth	2.5 MHz. 100 nanoseconds. Plus or minus 4 volts horizontal, Plus or minus 4 volts vertical. 15.734 kHz horizontal, 60 Hz vertical. Horizontal display 45 μs. Horizontal retrace 12 μs. Vertical display 15.3 ms. Vertical retrace 1 ms.
High Voltage High Voltage Shutdown Speaker Electrical Power Dimensions Weight	20 to 23 kV (at zero beam current). 22.5 to 25.5kV, maximum 31 kV. 2" × 3.25". 120 VAC, 1.23 A, 60 Hz. 13.75" H × 15.25" W × 15.25" D (350 × 390 × 390 mm). 38 pounds (17.2 kg).

Zenith Data Systems reserves the right to discontinue products and to change specifications at any time.

Installation

- 1. Connect the cables as shown in Figure 1-2, and supply a composite input.
- 2. Set the HI-Z/75 Ω switch for the input supplied.
- Set the BLACK LEVEL control to its midrange, detent position (see Figure 1-2). This will cause the areas of the display intended to be black to become black.
- 4. Set the COLOR LEVEL control to its midrange, detent position.
- Set the DISPLAY DRIVE control to its full clockwise position.
- 6. Select green or color:
 - If the monitor is to be used only for monochrome text display, select green by pushing in the GREEN/WHITE switch.

- If the monitor is to be used for graphics display or text and color display, select color by pulling out the GREEN/WHITE switch.
- 7. Turn on the computer and video monitor. The power indicator on the front of the video monitor should light.
- 8. After the monitor has warmed up, adjust the DISPLAY DRIVE control for the desired display brightness.
- If the dark areas, or color areas, or both, appear faded or washed out, turn the BLACK LEVEL control counterclockwise. If the light backgrounds or colors appear too dark, turn the BLACK LEVEL control clockwise.
- 10. Turn the Noise Processor switch on if the display appears noisy.
- 11. To tilt the screen downward, extend the bail (see Figure 1-2 inset) to its down position.

Circuit Description

Refer to the block diagram, schematics, and waveforms starting at Figure 4-3 in Chapter 4 Servicing.

Power Supply Assembly

The power supply assembly generates the +150 VDC supply, the regulated +120 VDC supply, the start-up pulse, and the degaussing current.

AC POWER

Line voltage is supplied to the power supply board through connector 3R8. The AC voltage is then routed through fuse FX3299 and an LCI (line conducted interference) choke. The LCI choke, in conjunction with capacitors CX3274 and CX3299 prevent noise generated within the monitor from being fed back into the AC line. The power switch is located across pins 1 and 2 of connector 3S8.

DEGAUSSING CIRCUIT

Since externally generated magnetic forces can cause the mask inside the CRT to become magnetized, the CRT is automatically degaussed each time the monitor is switched on.

Degaussing is accomplished by passing AC current through the degaussing coil wrapped around the CRT. The average value of the AC current is zero and therefore does not allow residual magnetism to remain on the mask of the CRT.

The degaussing coil is connected to the power supply board by connector 3T8. A positive temperature coefficient thermistor (RX3296) controls AC current flow through the degaussing coil. When monitor power is turned on, a high AC current will flow from one side of the AC line through the degaussing coil and thermistor RX3296 to the other side of the AC line. This high AC current demagnetizes the mask and then quickly drops to a value of near zero due to the heating and subsequent high resistance of RX3296.

+ 150 VDC SUPPLY

When monitor power is first turned on, the first power supply to develop output voltage is the +150 VDC supply. This is a bridge rectifier comprised of diodes CRX3271 – CRX3274. The output of this bridge rectifier circuit acts as a source for the other power supplies.

WARNING: The bridge rectifier circuit is referenced to chassis ground and is not isolated from the AC power with a built-in isolation transformer. Therefore, external isolation transwformers should always be used when test equipment is connected to the monitor. This is to prevent injury and damage to the monitor and/or test equipment.

This +150 VDC supply developes the start-up pulse which goes to the sweep module at pin 3 of connector 3B3. Also, the +150 VDC supplies the series regulator for the +120 VDC Horizontal Output Transistor (H.O.T.) power at connector 3U3 on the sweep module. The horizontal oscillator must be operating before additional power supplies will operate. For example, the horizontal oscillator must be operating and driving the H.O.T. before high voltage can be generated.

Sweep Module

The sweep module develops the horizontal and vertical deflection currents, CRT anode B+, CRT filament, G2, and various power supplies for itself and other modules.

POWER SUPPLIES

Regulated + 120 VDC is received from the power supply assembly at connector 3U3 to power the H.O.T. The start-up pulse which is received from the power supply assembly allows the horizontal oscillator, located in IC3401, to generate horizontal drive to the H.O.T. The resulting H.O.T. output supplies power at the various windings of TX3204 horizontal output transformer which is the source for the following power supplies:

- + 180 VDC (CR3210 half-wave rectifier)
- +26 VDC (CR3207 half-wave rectifier)
- + 12 VDC (divided down from + 26 VDC at Q3404 emitter)

CRT focus

CRT G2

CRT filament

CRT anode (B+) 22kV

60 V flyback

The +180 VDC, +26 VDC, and +12 VDC are supplied to the interface module at connector 2C5. The zener regulated ABL voltage is generated from the +180 VDC in the interface module and supplied to the sweep module at connector 5C2. Also, 60 V flyback is supplied to the interface module at pin 5 of connector 9E2.

SWEEP CIRCUITS

Horizontal and vertical sync signals are supplied to IC3401 horizontal and vertical scan processor from connector 9E2 on the interface module.

Vertical sweep (deflection) current is supplied to the yoke from connector 2A3, and horizontal sweep (deflection) current for the yoke comes from connector 3S3.

Interface Module

VIDEO SIGNALS

The interface module develops Red, Green, and Blue signals for the video output module and horizontal and

vertical sync signals for the sweep module. These signals are developed from a composite video input signal.

Additionally, ABL voltage is supplied from the sweep module, and G1 and base voltages are supplied to the video output module.

Audio signals supplied at the audio input connector are processed to drive a speaker.

The composite video signal at connector 9F2 pin 1 goes to chroma/luminance IC2376 where the Red, Green, and Blue signals are processed. These signals go through background controls R2405 (Red), R2406 (Green), R2407 (Blue), and through emitter followers before reaching output connector 2A5.

SYNC

Horizontal and vertical sync signals are processed in vertical and horizontal processor IC1301, amplified by transistors Q1217 (vertical) and Q1215 (horizontal) before reaching output connector 9E2.

AUDIO

Audio input at connector 9E4 pin 2 is processed by audio IC1415 with capacitor C1451 coupling the signal to speaker connector 4P4 pin 1.

Video Output Board

All outputs of this board go to the CRT socket which is on this board. The Red, Green, and Blue signals from the main board enter at connector 5A2 and go to transistors Q5102, Q5103, and Q5101 to drive the CRT. The following voltages are supplied from the sweep board:

- CRT filament voltage to connector 5H3.
- G2 voltage to connector 5X7.
- Focus voltage through a pigtail connector to the CRT.

The +180 VDC transistor supply voltage along with G1 and H.O.T. BASE DRIVE voltage are supplied by the interface module.

Circuit Board Pinouts

Refer to Figure 4-3 Block Diagram and schematics in Chapter 4.

Table 3-1 Interface Module

PIN NUMBER	SIGNAL NAME/DESCRIPTION
8E2 (To Swe	ep Module)
1	Ground
2	+ 26 VDC
3	+ 12 VDC
_	(connector key)
4	ABL (Automatic Brightness Level) voltage
5	No Connection
6	+ 180 VDC
9E2 (To Swe	ep Module)
1	Horizontal Sync
2	Vertical Sync
_	(connector key)
3	Ground
4	Horizontal Blanking
5	60 Volt Pulse
2B7 (To Sec	ondary Control Panel)
1	Color Level Control
2	Ground
_	(connector key)
3	Tint Control
4	No Connection
5	Green/White Switch
2A7 (To Sec	ondary Control Panel)
1	+ 12 VDC
2	Brightness Range Control
3	Display Drive Control
_	(connector key)
4	Sharpness Control
5	Noise Processor Switch
6	Black Level Control
TP7 (To Prim	nary Control Board)
1	Ground
_	

Table 3-1 (Continued) Interface Module

PIN NUMBER	SIGNAL NAME/DESCRIPTION
2A5 (To Vide	eo Output Module)
1	RED Signal
2	GREEN Signal
	(connector key)
3	BLUE Signal
4	Ground
2C5 (To Vide	o Output Module)
1	+ 180 VDC
2	No Connection
_	(connector key)
3	Drive
4	G1 (CRT Grid 1) Voltage
5	No Connection
9F2 (To Inpu	t Panel Assembly)
1 .	Composite Video Input
2	Ground
9G3 (To Inpu	t Panel Assembly)
1	Luma Input
2	Ground
9H4 (To Inpu	t Panel Assembly)
Center pin	• • • • • • • • • • • • • • • • • • • •
Shield	Ground
9E4 (To Inpu	t Panel Assembly)
1	Ground
2	Audio Input
4P4 (To Spea	ker)
1	Audio Signal
2	Ground

Volume Control

2

Table 3-2Sweep Module

PIN		
NUMBER	SIGNAL NAME/DESCRIPTION	
3S3 (To Yoke	-Horizontal Winding)	
1	Horizontal Sweep (Hi)	
2	Horizontal Sweep (Lo)	
2A3 (To Yoke	e-Vertical Winding)	
1	Vertical Sweep (Lo)	
2	Vertical Sweep (Hi)	
3B3 (To Powe	er Supply Module)	
1	Frame Ground	
2	Ground	
3	Start-up Pulse	
3U3 (To Powe	er Supply Module)	
1	+ 120 VDC	
CRT Anode (To CRT)	
•	+ 22 kV	
F (T- Vi-	deo Output Module)	
-	•	
Mid-air	Focus voltage	
Mid-air	•	
Mid-air	Focus voltage	
Mid-air 7X5 (To Video 1	Focus voltage D Output Module)	
Mid-air 7X5 (To Video 1	Focus voltage Doutput Module) G2 (CRT Grid 2) voltage	
Mid-air 7X5 (To Video 1 3B9 (To Video	Focus voltage D Output Module) G2 (CRT Grid 2) voltage D Output Module)	
Mid-air 7X5 (To Video 1 3B9 (To Video	Focus voltage D Output Module) G2 (CRT Grid 2) voltage D Output Module) CRT Filament (Heater) voltage CRT Filament (Heater) voltage	
Mid-air 7X5 (To Video 1 3B9 (To Video 1 2	Focus voltage D Output Module) G2 (CRT Grid 2) voltage D Output Module) CRT Filament (Heater) voltage CRT Filament (Heater) voltage	
Mid-air 7X5 (To Video 1 3B9 (To Video 1 2 2E8 (To Interf	Focus voltage D Output Module) G2 (CRT Grid 2) voltage D Output Module) CRT Filament (Heater) voltage CRT Filament (Heater) voltage	
Mid-air 7X5 (To Video 1 3B9 (To Video 1 2 2E8 (To Interi	Focus voltage D Output Module) G2 (CRT Grid 2) voltage D Output Module) CRT Filament (Heater) voltage CRT Filament (Heater) voltage Fiace Module) + 180 VDC	
Mid-air 7X5 (To Video 1 3B9 (To Video 1 2 2E8 (To Interi 1 2	Focus voltage D Output Module) G2 (CRT Grid 2) voltage D Output Module) CRT Filament (Heater) voltage CRT Filament (Heater) voltage Fiace Module) + 180 VDC No Connection	
Mid-air 7X5 (To Video 1 3B9 (To Video 1 2 2E8 (To Interi 1 2	Focus voltage O Output Module) G2 (CRT Grid 2) voltage O Output Module) CRT Filament (Heater) voltage CRT Filament (Heater) voltage Hace Module) + 180 VDC No Connection ABL (Automatic Brightness Level) voltage	
Mid-air 7X5 (To Video 1 3B9 (To Video 1 2 2E8 (To Interi 1 2 3 —	Focus voltage D Output Module) G2 (CRT Grid 2) voltage D Output Module) CRT Filament (Heater) voltage CRT Filament (Heater) voltage Fiace Module) + 180 VDC No Connection ABL (Automatic Brightness Level) voltage (connector key)	
Mid-air 7X5 (To Video 1 3B9 (To Video 1 2 2E8 (To Interi 1 2 3 4	Focus voltage D Output Module) G2 (CRT Grid 2) voltage D Output Module) CRT Filament (Heater) voltage CRT Filament (Heater) voltage Fiace Module) + 180 VDC No Connection ABL (Automatic Brightness Level) voltage (connector key) + 12 VDC	
Mid-air 7X5 (To Video 1 3B9 (To Video 1 2 2E8 (To Interi 1 2 3 4 5	Focus voltage D Output Module) G2 (CRT Grid 2) voltage D Output Module) CRT Filament (Heater) voltage CRT Filament (Heater) voltage Face Module) + 180 VDC No Connection ABL (Automatic Brightness Level) voltage (connector key) + 12 VDC + 26 VDC Ground	
Mid-air 7X5 (To Video 1 3B9 (To Video 1 2 2E8 (To Interi 1 2 3 4 5 6	Focus voltage D Output Module) G2 (CRT Grid 2) voltage D Output Module) CRT Filament (Heater) voltage CRT Filament (Heater) voltage Face Module) + 180 VDC No Connection ABL (Automatic Brightness Level) voltage (connector key) + 12 VDC + 26 VDC Ground	
Mid-air 7X5 (To Video 1 3B9 (To Video 1 2 2E8 (To Interi 2 3 4 5 6 2E9 (To Interi	Focus voltage D Output Module) G2 (CRT Grid 2) voltage D Output Module) CRT Filament (Heater) voltage CRT Filament (Heater) voltage GRT Filament (Heater) voltage Face Module) + 180 VDC No Connection ABL (Automatic Brightness Level) voltage (connector key) + 12 VDC + 26 VDC Ground Face Module)	
Mid-air 7X5 (To Video 1 3B9 (To Video 1 2 2E8 (To Interi 2 3 4 5 6 2E9 (To Interi 1	Focus voltage D Output Module) G2 (CRT Grid 2) voltage D Output Module) CRT Filament (Heater) voltage CRT Filament (Heater) voltage CRT Filament (Heater) voltage Face Module) + 180 VDC No Connection ABL (Automatic Brightness Level) voltage (connector key) + 12 VDC + 26 VDC Ground Face Module) 60 Volt Pulse	
Mid-air 7X5 (To Video 1 3B9 (To Video 1 2 2E8 (To Interi 2 3 4 5 6 2E9 (To Interi 1	Focus voltage D Output Module) G2 (CRT Grid 2) voltage D Output Module) CRT Filament (Heater) voltage CRT Filament (Heater) voltage face Module) + 180 VDC No Connection ABL (Automatic Brightness Level) voltage (connector key) + 12 VDC + 26 VDC Ground face Module) 60 Volt Pulse Horizontal Blanking (connector key) Ground	
Mid-air 7X5 (To Video 1 3B9 (To Video 1 2 2E8 (To Interial 3 4 5 6 2E9 (To Interial 2 —	Focus voltage D Output Module) G2 (CRT Grid 2) voltage D Output Module) CRT Filament (Heater) voltage CRT Filament (Heater) voltage face Module) + 180 VDC No Connection ABL (Automatic Brightness Level) voltage (connector key) + 12 VDC + 26 VDC Ground face Module) 60 Volt Pulse Horizontal Blanking (connector key)	

Table 3-3 *Video Output Module*

PIN NUMBER	SIGNAL NAME/DESCRIPTION		
5A2 (To Interfa	5A2 (To Interface Module)		
1	RED Signal		
2	GREEN Signal		
_	(connector key)		
3	RED Signal		
4	Ground		
5C2 (To Interfa	ce Module)		
1	+ 180 VDC		
2	No Connection		
_	(connector key)		
3	Drive		
4	G1 (CRT Grid 1) voltage		
5	No Connection		
DAG (To CRT (Ground Contact)		
1	DAG (Ground)		
5H3 (To Sweep Module)			
5H3 (To Sweep	Module)		
5H3 (To Sweep	Module) CRT Filament (Heater) voltage		
•			
1	CRT Filament (Heater) voltage CRT Filament (Heater) voltage		
1 2	CRT Filament (Heater) voltage CRT Filament (Heater) voltage		
1 2 5X7 (To Sweep	CRT Filament (Heater) voltage CRT Filament (Heater) voltage Module) G2 (CRT Grid 2) voltage		
1 2 5X7 (To Sweep 1	CRT Filament (Heater) voltage CRT Filament (Heater) voltage Module) G2 (CRT Grid 2) voltage		
5X7 (To Sweep 1	CRT Filament (Heater) voltage CRT Filament (Heater) voltage Module) G2 (CRT Grid 2) voltage rep Module) Focus voltage		
5X7 (To Sweep 1 Focus (To Swe Mid-air	CRT Filament (Heater) voltage CRT Filament (Heater) voltage Module) G2 (CRT Grid 2) voltage rep Module) Focus voltage CRT)		
5X7 (To Sweep 1 Focus (To Swe Mid-air CRT Socket (To 1, 2, and 3 are of	CRT Filament (Heater) voltage CRT Filament (Heater) voltage Module) G2 (CRT Grid 2) voltage sep Module) Focus voltage CRT) common No connection		
5X7 (To Sweep 1 Focus (To Swe Mid-air CRT Socket (To 1, 2, and 3 are of 4	CRT Filament (Heater) voltage CRT Filament (Heater) voltage Module) G2 (CRT Grid 2) voltage Pep Module) Focus voltage CRT) COMMON No connection G1 (CRT Grid 1) voltage		
5X7 (To Sweep 1 Focus (To Swe Mid-air CRT Socket (To 1, 2, and 3 are of 4 5 6	CRT Filament (Heater) voltage CRT Filament (Heater) voltage Module) G2 (CRT Grid 2) voltage Pep Module) Focus voltage CRT) COMMON No connection G1 (CRT Grid 1) voltage GREEN Cathode signal		
5X7 (To Sweep 1 Focus (To Swee Mid-air CRT Socket (To 1, 2, and 3 are of 4 5 6 7	CRT Filament (Heater) voltage CRT Filament (Heater) voltage Module) G2 (CRT Grid 2) voltage Pep Module) Focus voltage CRT) COMMON No connection G1 (CRT Grid 1) voltage GREEN Cathode signal G2 (CRT Grid 2) voltage		
5X7 (To Sweep 1 Focus (To Sweep Mid-air CRT Socket (To 1, 2, and 3 are of 4 5 6 7 8	CRT Filament (Heater) voltage CRT Filament (Heater) voltage Module) G2 (CRT Grid 2) voltage Pep Module) Focus voltage CRT) COMMON No connection G1 (CRT Grid 1) voltage GREEN Cathode signal G2 (CRT Grid 2) voltage RED Cathode signal		
5X7 (To Sweep 1 Focus (To Swee Mid-air CRT Socket (To 1, 2, and 3 are of 4 5 6 7 8 9	CRT Filament (Heater) voltage CRT Filament (Heater) voltage Module) G2 (CRT Grid 2) voltage Pep Module) Focus voltage CRT) COMMON No connection G1 (CRT Grid 1) voltage GREEN Cathode signal G2 (CRT Grid 2) voltage RED Cathode signal Filament (Heater) voltage		
1 2 5X7 (To Sweep 1 Focus (To Sweep 1 Mid-air CRT Socket (To 1, 2, and 3 are of 4 5 6 7 8 9 10	CRT Filament (Heater) voltage CRT Filament (Heater) voltage Module) G2 (CRT Grid 2) voltage Pep Module) Focus voltage CRT) COMMON No connection G1 (CRT Grid 1) voltage GREEN Cathode signal G2 (CRT Grid 2) voltage RED Cathode signal Filament (Heater) voltage Filament (Heater) voltage		
5X7 (To Sweep 1 Focus (To Swee Mid-air CRT Socket (To 1, 2, and 3 are of 4 5 6 7 8 9	CRT Filament (Heater) voltage CRT Filament (Heater) voltage Module) G2 (CRT Grid 2) voltage Pep Module) Focus voltage CRT) COMMON No connection G1 (CRT Grid 1) voltage GREEN Cathode signal G2 (CRT Grid 2) voltage RED Cathode signal Filament (Heater) voltage		

Servicing

Safety and Service Guidelines

WARNING: No work should be attempted on any part of the chassis by anyone not familiar with Zenith service procedures and precautions; otherwise, personal injury may result.

WARNING: External Isolation transformers should always be used when test equipment is connected to the monitor. This is to prevent injury and damage to the monitor and or test equipment.

WARNING: With the monitor power turned off and disconnected, discharge the high voltage anode lead at the CRT, using a jumper lead connected between the chassis and a screwdriver (see Figure 6.1). Failure to comply could result in severe shock and/or personal injury.

WARNING: Do not operate the monitor with excessive high voltage any longer than necessary or the monitor may produce X-rays from the CRT.

Excessive high voltage will produce X-rays from the CRT; always verify that the voltage is at normal levels when servicing the monitor.

WARNING: Carefully handle the cathode-ray tube when you hold, remove, or install it; otherwise, implosion and/or injury may result.

NOTE: Under no circumstances should the original design be modified or altered without permission from Zenith Electronics Corporation.

AC LEAKAGE TEST

To prevent electrical shock after reassembly, perform an AC leakage test on all exposed metal parts of the monitor. Do not use an isolation transformer to perform this test.

1. Connect the test circuit as shown in Figure 4.1.

- With the monitor turned on, measure the leakage voltage between earth ground and an exposed monitor metal part.
- Repeat the measurement with the meter leads reversed.
- Repeat steps 2 and 3 until all exposed metal parts are verified to have satisfactory AC leakage levels.

WARNING: Any leakage voltage measurement that exceeds 0.75 volts rms (0.5 milliamperes AC) constitutes a potential shock hazard and must be corrected.

CAUTION: Some of the ICs (integrated circuits) used in the monitor are electrostatic-sensitive devices. These circuits can be damaged by static electricity. When handling any IC, use a wrist grounding strap or be sure to equalize the static charge before touching the IC.




Figure 4-1
AC Leakage Voltmeter Circuit

OTHER PRECAUTIONS

- Be sure that all components are positioned in such a manner as to avoid the possibility of short circuits.
- Inspect and correct all soldered connections for cold solder joints, frayed leads, damaged insulation, splashed solder, or sharp points.
- Never release a repaired product to a customer unless all protective devices, such as insulators, barriers, cover shields, strain reliefs, etc., have been installed.
- Remove all loose material from inside the monitor after servicing.
- Follow the original lead layout, dress, lengths, and tension.
- Replace all components with exact Zenith replacement parts.

Suggested Equipment and Supplies

TOOLS AND SUPPLIES

- 1/4-inch nut driver
- Flat-bladed screwdriver, 1/4-inch blade
- Phillips screwdriver, No. 1 tip
- Phillips screwdriver, No. 2 tip
- Diagonal cutters
- Wire strippers
- Long-nose pliers
- Desoldering tool
- Soldering iron, 25 to 40 watts
- Solder, 60/40, HE-331-59
- Desoldering braid, HE-490-185
- Cable ties, HE-354-59
- Lint-free cloths

TEST EQUIPMENT

- Oscilloscope DC to 100 MHz, dual trace, triggered sweep. Tektronix Model 465, or equivalent.
- Logic probe Capable of detecting 10 nanoseconds single pulses, and indicating logic one, logic zero, and high impedance states. Heath Model IT-7410, or equivalent.
- Digital voltmeter High impedance input, 0 to 1000 volts, 0 to 1 M Ω . Heath Model SM-2215, or equivalent.
- Variable power supply 0 to 120 VAC rms, 3 amps. Heath Model IM-5210, or equivalent.
- Low capacitance oscilloscope probe Input capacitance adjustable from 15 pF to 50 pF, 4 ns rise time. Heath Model PKW-105, or equivalent.
- High voltage probe 0 to 40 kV. Heath Model IM-5210, or equivalent.
- Isolation transformer

Troubleshooting

Use the following inspection to determine possible causes of monitor failures.

- Verify proper computer operation.
- Check monitor controls for proper response and settings.
- Unplug the signal and power cables from the monitor and check for burnt insulation, broken wires, or loose prongs on plugs.
- Check the AC receptacle (wall outlet) for proper supply voltage.

- Check all cabling and internal circuit board plugs for proper electrical connections. Refer to the applicable block diagram and component location illustrations for cable connector assignments.
- Check monitor adjustments as explained at the end of this chapter.
- Check all circuit boards for broken or burnt components or for darkened areas or other signs of component overheating.
- Verify that the Green/White switch is in the correct position.
- When power is applied, check the CRT for a glowing filament.
- When power is applied, check for high voltage by placing the back of the hand near the face of the CRT.

Table 4-1:General Troubleshooting

PROBLEM	POSSIBLE CAUSE
Dead monitor	 No power at source. Power cord. Fuse. Connector 3R8. Connector 3S8. Power switch.
No display	Composite video cable. Composite video source.
No color	 Green/White switch. Software produces monochrome display.
Green color only	Green/White switch. Software produces green display.
Out of focus	Focus control.
Raster displayed	G2 control.
Display does not fit on CRT	 Vertical size (R2172). Width adjust (LX3261).

Adjustments

INTERFACE MODULE

Background (Red, Green, and Blue) and G2 Adjustments

These adjustments are to be made in a darkened room.

- Locate connector 9C1 on the interface module and move the jumper connector to the set-up position (installed in the slot away from connector 2C5, see Figure 4-4).
- 2. Turn each control (R2405 Red, R2406 Green, and R2407 Blue) fully counterclockwise and allow a minimum of ten minutes warm-up.
- 3. Adjust G2 on the sweep module until the raster just appears.
- 4. Adjust each control until a gray raster appears.
- 5. Readjust G2 until the raster just disappears.
- Return the jumper connector to the normal position in 9C1 connector (installed in the slot near connector 2C5).

Interlace Adjustment

The monitor must exhibit acceptable convergence before you can check or make this adjustment.

The following interlace adjustment procedure requires an interlace signal and is based on the composite interlaced video signal generated by the Z-319 video card and the CB-5063-28 Diagnostic package software.

 Connect the monitor Composite Video Chroma input to the Composite video output of an operating Z-319 video card. Note that this will produce a monochrome display only.

IMPORTANT NOTICE

FOR X-RADIATION, FIRE OR SHOCK HAZARD PREVENTION, CERTAIN SPECIAL OR REDUNDANT PARTS ARE USED. USE ONLY EXACT REPLACEMENTS, DO NOT ALTER THE CIRCUIT OR DEFEAT THE FUSE. FAILURE TO COMPLY MAY BE UNLAWFUL.




Figure 4-2
Adjustments-Rear View

Page 4-4 Servicing

- Use a CB-5063-28 Diagnostic package to display an interlaced pattern as shown in Figure 4-3 below. This display is the second pattern of the sixth series of displays using the Video Controller Test.
- Adjust the Interlace control R3438 (See Figure 4-2), for the largest and most even opening in the vertical lines as indicated in Figure 4-3. This will provide stable display when the monitor is operated with an interlaced video signal.

SWEEP MODULE

Vertical Size and Vertical Center Adjustments

These controls (R2172 size and R2125 vertical centering) are to be adjusted under low-light conditions.

- 1. Turn the G2 control clockwise until a raster appears.
- 2. Adjust the two controls so that the top and bottom of the raster are 1/2 inch from the edge of the CRT.
- 3. Turn the G2 control counterclockwise until the raster just disappears.




Figure 4-3
Interlace Display

Width and Horizontal Center Adjustments

Horizontal centering control R3425 and width LX3261 are to be adjusted under low light conditions (see Figure 4-2).

- 1. Turn the G2 control clockwise until a raster appears.
- 2. Adjust these two controls so that the raster is 1/4 inch from the left and 3/8 inch from the right CRT edges.
- 3. Turn the G2 control counterclockwise until the raster just disappears.

Focus

With a video source connected to the monitor, adjust the focus control for the clearest (sharpest) display (see Figures 1-2 and 4-2).

Fill the Screen Test

A Z-100 Series, Z-100 PC Series, or equivalent computer is required for these tests.

The screen can be filled by using the Monitor ROM.

- 1. Turn on the computer.
- 2. Z-100:

When the hand prompt appears (you may have to defeat the autoboot by pressing the ESC key during the autoboot sequence to get this), press the T key to obtain the test menu from the Monitor ROM. If the test menu does not appear and the computer beeps, then the Monitor ROM is an early version and does not contain the test routines. In this situation, use the BASIC program.

Z-100 PC:

Press the CTRL, ALT, and INS keys and then enter TEST and press RETURN.

3. Select the Keyboard Test by pressing the 2 key.

- 4. Choose any character to fill the screen by pressing it. The capital Z is recommended.
- Check to see if the screen is filled with the test character and if the width and height of the display are correct.
- 6. Make any necessary adjustments (see Monitor Alignments and Adjustments in this chapter).
- 7. When you are finished using the display, press the DELETE key to return to the test menu.
- 8. Press the 5 key to return to the hand prompt.

Cleaning Procedure

WARNING: Be sure that the monitor's power cable is unplugged before cleaning.

- Clean the cabinet with a lint-free cloth, lightly dampened and with a mild cleaning solution; do not spray liquids directly on the monitor or use a wet, saturated cloth.
- Clean the monitor's screen with a good quality glass cleaner.
- Be sure that the monitor is completely dry before applying electrical power.

Servicing Diagrams

Use the following block diagrams to locate schematics while tracing signal and power circuits during trouble-shooting.

Waveform representations are provided with adjacent schematic and component location drawings. The source location of waveforms are shown on both schematic and component location drawing.

A Z-160 PC Series computer was used to supply the composite signals for generating the waveforms.

NOTE: Some input and output waveforms for some boards are taken from the adjacent boards because test points having the same signal are more accessible there.

Page 4-6 Servicing

WAVEFORM PHOTOGRAPH EXPLANATIONS

The waveforms in this manual are photographs taken on a DC-coupled Tektronix 2445, 4 channel, 150 MHz oscilloscope through a 10X probe with $10M\Omega$ impedance. The oscilloscope automatically compensates for the 10x probe, so the display shows the probe input.

NOTE: The waveforms on your oscilloscope may vary slightly from those in this manual due to bandwidth, input impedance, and other oscilloscope differences, as well as the monitor being examined.

A — The letter (A or B) is the oscilloscope trigger that is controlling the display. The trigger source is the second character (Channel 1, 2, 3, or 4).

B — The voltage level at which the scan is triggered, measured in volts (V) or millivolts (mV).

C — One of four possible values: sweep delay time, delta voltage, delta time, or inverse delta time (1/delta time). Delta values are established between the variable reference curosr (dotted line O) and the variable data cursor (dotted line N). The symbol to the left of the value type indicates delta or delay, while the symbol to the right indicates unit of measurment, based upon either the sweep scale factor (see K and M) or the scale factor (see D, G, I, and J).

D — The channel 1 scale factor in volts (V) or millivolts (mV).

E — Indicates two signals summed togeter (+).


F — Indicates inverted display (down arrow).

G — The channel 2 scale factor in volts (V) or millivolts (mV).

H — Bandwidth limitation (20 MHz) indicator (BWL).

I — Channel 3 scale factor in volts (V) or millivolts (mV).

J — Channel 4 scale factor in volts (V) or millivolts (mV).



OSCILLOSCOPE DISPLAY

K — A sweep time base in seconds (s), milliseconds (ms), microseconds (us), or nanoseconds (ns).

L — Holdoff indicator (HO). Holdoff is the amount of time between the end of the sweep and the time that a triggering signal can initiate the next sweep).

M — B-sweep time base in seconds (s), milliseconds (ms), microseconds (us), or nanoseconds (ns).

N — Data cursor which may be varied either on the vertical axis (illustrated) to measure delta voltage or on the horizontal axis (not illustrated) to measure delta time.

O — Reference cursor which may be varied either on the vertical axis (illustrated) or the horizontal axis (not illustrated). Unless otherwise indicated, this cursor is used to show ground reference when in the vertical axis.




Figure 4-4 Part 1
Monitor Block Diagram

CABLE PIN ASSIGNMEN	Т
8E2 (INTERFACE MODULE) TO	
1	 6
3	5 4
4	4 3
5 ——————————	2
6	1
9E2 (INTERFACE) 1 ———————————————————————————————————	2E9 (SWEEP) 5
2	5 4
3 —	7 3
4	2
5	1
2A5 (INTERFACE MODULE)	5C2 (VIDEO OUTPUT)
1 ————————————————————————————————————	— 1
2	2
3	3
4	 4
2C5 (INTERFACE MODULE)	5C2 (VIDEO OUTPUT)
1	1
2 ————	2
3	3
4	4
1 ————————————————————————————————————	2
9C1 (INTERFACE MODEL) JUMPER IN	NORMAL (OPERATING) POSITIO
1 1	*****
2 2	
3	7
	-
5 ——— 5 ——	
6	
7 8	
9	
9C1 (INTERFACE MODULE) JUMPER I	N SET-UP POSITION
2	
3	
4 1	
5 2	
6 3	n
7 ——— 4 ——	-
8 — 5 —	
9 ——— 6 ——	

Figure 4-4 Part 2
Cable Pin Assignment




Figure 4-5
Interface Module Component Location and
Waveforms







Figure 4-6
Interface Module Schematic










Figure 4-7
Sweep Module Component Location

Figure 4-8 Sweep Module Waveforms




Figure 4-9 Sweep Module Schematic




Figure 4-11
Power Supply Module Component Locations

Page 4-12 Servicing





Figure 4-10
Power Supply Assembly Major Components



SCHEMATIC FOR 9-293 & 9-293-01 & 9-293-02 SERIES PASS POWER SUPPLY

Figure 4-12
Power Supply Assembly Schematic




Figure 4-15
Video Output Module Schematic

Page 4-14 Servicing




Figure 4-13
Video Output Module Component Location




Figure 4-14
Video Output Module Waveforms




Figure 4-16
Secondary Control Panel Component Location






Figure 4-17
Secondary Control Panel Schematic



SCREW, THD FORM 4-24x0.25 TYPE B CADMIUM 0.187A HEX HD, SLOTTED	2	114-584	8
LABEL DATE CODE	1	101-6239-11	7
SWITCH PUSH BUTTON, LOCKING	1	85-1559-9-02	6
CONTROL ROTARY, SINGLE	1	63-10772-04	5
CABLE RETAINER STRAP CABLE TIE	1	19-733-06	4
METAL STAMPING BRACKET, VOLUME CONTROL MTG	1	12-7926-01	3
CABLE AND HSNG ASSY 0.312P, 1UP, TWIN LEAD 3S8	1	A-10150-05	2
CABLE AND HSNG ASSY 0.156P, 1P, TP7	1	A-9911-79	1
DESCRIPTION	QTY.	PART NUMBER	ITEM

Figure 4-18
Primary Control Board Component Location



Page **4-16**





Figure 4-20
Input Panel Component Location



Disassembly/ Reassembly

This section along with Figure 6-1, provides instruction for both disassembling and reassembling the monitor. The step-by-step instructions are written for disassembly. For reassembly, perform the steps in the reverse order except when instructed to do otherwise.

WARNING: Be sure that the monitor power and signal cables are unplugged before attempting disassembly of the monitor.

NOTE: Some connectors are very tight and may require careful prying with a screwdriver in order to free them.

Back Cover (10)

- Disconnect the power and signal cables from the rear of the monitor.
- 2. Remove the four screws (05) from the back cover (10) and pull the cover back and away from the monitor.

Top Cover (20)

Remove the two screws (15) from the bottom of the cabinet and lift the top cover (20) up and toward the rear of the monitor.

Input Panel (40)

- 1. Remove the back cover (10).
- 2. Remove the top cover (20).
- 3. Remove the two screws (35) that secure the input panel to the right chassis CRT mounting plate (151).

4. Disconnect the input panel cable connectors from the interface board and remove the panel from the monitor.

Cabinet Front (150)

- 1. Remove the back cover (10).
- 2. Remove the top cover(20).
- 3. Disconnect the primary control cables from the power supply and interface boards.
- 4. Disconnect the degaussing cable connector from the power supply board.
- Disconnect the secondary control cable connectors from the interface board.
- 6. Disconnect the speaker cable connector from the interface board.
- 7. Remove the four screws (74) that secure the cabinet front (150) and bring the cabinet front forward and away from the monitor.

Primary Control Panel (125)

- 1. Remove the cabinet front (150).
- 2. Cut the cable tie that holds the power LED cable to the volume control cable.
- 3. Remove the two screws (120) that secure the primary control to the cabinet front.

Secondary Control Panel (135)

- 1. Remove the cabinet front (150).
- Disconnect the connector from the power LED cable.
- 3. Remove the two screws (130) that secure the secondary control to the cabinet front.

Speaker (115)

- 1. Remove the cabinet front (150).
- 2. Remove the four screws (110) that secure the speaker to the cabinet front.

Sweep Module (77)

- 1. Remove the cabinet back (10).
- 2. Remove the cabinet top (20).
- Discharge the high voltage and disconnect the high voltage lead from the CRT.

WARNING: Discharge the high voltage at the anode lead to the CRT using a jumper lead connected between the chassis and a screwdriver. Otherwise, shock or injury may result. Refer to the inset of Figure 6-1.

- 4. Remove the two screws (25) and remove the cross brace (30).
- 5. Disconnect the focus wire at the mid-air connector.
- 6. Remove the five screws (78) that secure the sweep module to the left chassis CRT mounting plate (152).
- 7. Disconnect interface module connectors to allow access to screw (73).
- 8. Loosen screw (73) and lift the sweep module up and toward the rear of the monitor.

Video Output Module (70)

- 1. Remove the cabinet back (10).
- 2. Remove the cabinet top (20).
- 3. Carefully unplug the video output module from the CRT.
- 4. Disconnect the focus wire at the mid-air connector.
- 5. Disconnect the ground connection from the CRT ground contact (100).
- 6. Disconnect the remaining cable connectors from the video output module.

Interface Module (85)

- 1. Remove the cabinet back (10).
- 2. Remove the cabinet top (20).
- 3. Unplug the video output module from the CRT.
- 4. Disconnect all cable connectors from the interface module.
- 5. Remove the two screws (22) that secure the rear of the interface module to the chassis.
- 6. Slide the interface module to the rear and out of the guides that secure the front of the interface module.

Power Supply Board (65)

- 1. Remove the cabinet back (10).
- 2. Remove the cabinet top (20).
- 3. Remove the two screws (26) that secure the top of the board to the bracket of the power supply assembly.

- 4. Lift the power supply board up and out of the two guides that secure the bottom of the board.
- Disconnect all cable connectors from the power supply board.
- 6. Remove the power supply board from the monitor

Power Supply Assembly (65)

- 1. Remove the cabinet back (10).
- 2. Remove the cabinet top (20).
- 3. Remove the screws (23) that secure the power supply assembly to the right chassis CRT mounting plate (151).
- 4. Remove the two screws (35) that secure the input panel (40) to the right chassis CRT mounting plate.
- Remove the two screws (27) that secure the bottom of the power supply to the chassis and lift the assembly up and away from the monitor.

CRT (105)

- 1. Remove the cabinet back (10).
- 2. Remove the cabinet top (20).

3. Discharge the high voltage and disconnect the high voltage lead from the CRT.

WARNING: Discharge the high voltage at the anode lead to the CRT using a jumper lead connected between the chassis and a screwdriver. Otherwise, shock or injury may result. Refer to the inset of Figure 6-1.

- Disconnect the video output module from the CRT.
- 5. Disconnect the video output module ground wire from the CRT ground contact.
- 6. Disconnect the yoke cable connectors from the sweep module.
- 7. Place the monitor with its CRT face down on a soft horizontal surface, allowing access to screws (104).
- 8. Cut the ties that secure the degaussing coil at the four corners of the CRT.
- Remove the four screws (104), flat washers (102), and star washers (103) that secure the CRT to the right and left chassis CRT mounting plates.
- 10. Lift the monitor up and away from the CRT.

Chapter 6

Parts List

All part numbers in this manual are identified in the following tables of parts lists Table 6-1 Monitor Major Assemblies, Table 6-2 Cable Assemblies, and Table 6-3 through Table 6-10 board and assembly components.

CAUTION: Some of the ICs used in this unit are electrostatic-sensitive devices. These devices can be damaged by static electricity. When handling any IC, use a wrist ground strap or be sure to equalize the static charge before touching the IC.

IMPORTANT SAFETY NOTICE: Under no circumstances should the original design be modified or altered without permission from Zenith Electronics Corporation. All components should be replaced only with types identical to those in the original circuit, and their physical location, wiring, and lead dress must conform to the original layout upon completion of repairs.

In some instances, redundant circuits are incorporated for additional protection and X-radiation protection. Special circuits are also used to prevent shock and fire hazard. These special circuit components, which contain X in their reference designator, are to be replaced with identical components only.

NOTE: Unless otherwise specified, all resistors are 1/4-watt, 5% tolerance.

In the following parts list, N/A refers to "Not Assigned" parts for which there is no replacement part number assigned.

Assemblies identified by part numbers that start with the letter **F** are not available at this assembly level.

Table 6-1 *Monitor Major Assembly (see Figure 6-1)*

REFERENCE	ZDS PART	
DESIGNATOR	NUMBER	DESCRIPTION
05	114-1207	Screw, back cover, 8-18 × .625
03	114-1207	hex head
10	14-11514-03	Back cover
11	14-11515-01	Cabinet bottom, rectangular
15	112-2262-05	Screw, cover glue block, 8-18 ×
13	112-2202-03	1.250 phillips
20	14-11649	Top cover
20	14 11040	1 op 60 v c.
21	114-00802-01	Screw, CRT bracket to channel
		bracket
22	114-01121	Screw, Interface board to channel
		bracket
23	114-01353-02	Screw, Power Supply to CRT
		bracket
24	114-01393	Screw, channel bracket mounting
25	114-802	Screw, cross brace, 8-18 $ imes$.375
		hex head
26	114-01393-01	Screw, power supply board to as-
		sembly bracket
27	N/A	Screw, power supply assembly
		bottom support
30	12-8298	Cross brace
35	114-00802-01	Screw to input panel
40	A-13444	Input panel assembly
40	7. 10-1-1	input purior adderniory
64	9-293-03	Power Supply Module
65	N/A	Power Supply Assembly
70	9-155-25	Video output module
73	N/A	Screw, sweep module bracket
74	114-01402	Screw, CRT bracket to front
77	0.201	Sugar madula
77	9-391	Sweep module
78	114-01121	Screw, sweep board mounting
85	9-390	Interface module
90	19-733-04	Cable tie
91	19-733-01	Cable tie
N/A	19-733-05	Cable tie
92	20-3918-09	Degaussing coil and cable as-
100	107-006-00	sembly
	127-226-03	Contact, CRT ground
102	N/A	Flat washer, CRT mounting
103	93-02076-01	Lock washer, see item 104
104	114-601	Screw, CRT mounting 10-16 × .500 hex w/washer

Table 6-1 (Continued)

Monitor Major Assembly (see Figure 6-1)

Table 6-2	(Continued)
Monitor Cables	(see Figure 4-3)

REFERENCE DESIGNATOR	ZDS PART NUMBER	DESCRIPTION
105	A-13649	CRT, yoke, and beam bender as sembly
110	114-1379	Screw speaker mounting
115	49-1332	Speaker
120	114-1402	Primary control board screws
125	A-10342	Primary control board and switch assembly
126	A-10675	LED cable and housing assembly
N/A	19-1000	Clip for A-10675
N/A	46-10335	Knob, on-off switch
N/A	A-08846	Knob assembly, volume control
130	114-1402	Secondary control board screws
135	A-9522-06	Secondary control board
140	N/A	Insulation sheet, Power Supply
141	N/A	Insulation sheet, Interface Module
145	N/A	Insulation sheet, Sweep Module
146	50-347-01	Power cable assembly
147	125-198-07	Power cable strain relief
148	114-1425-01	Screw, AC line, ground to frame
150	14-11516-08	Cabinet front
151	12-8720	Right chassis mounting plate
152	12-88720-01	Left CRT chassis mounting plate
153	12-08719	Channel support, front
154	12-08719-01	Channel support, rear

REFERENCE DESIGNATOR	ZDS PART NUMBER	DESCRIPTION
9E4	50-261-12	Connector and cable assembly
9F2	50-261-11	Connector and cable assembly
9G3	50-261-13	Connector and cable assembly
9H2	52-2571-19	Cable and plug
TP7	A-9911-79	Cable and housing assembly

Table 6-39-390 Interface Module (see Figure 4-4)

9-390 lineriace Module (See Figure 4-4)				
REFERENCE DESIGNATOR		DESCRIPTION		
Capacitors				
C1201	22-7407-01	1 μF electrolytic		
C1203	22-7633-29	68 pF disc		
C1204	22-7648-14	20 pF disc		
C1207	22-7775-22	.068 μF polyester		
04000				
C1302	22-7862-01	1 μF electrolytic		
C1303	22-7648-23	47 pF disc		
C1304	22-7774-08	.0047 μF polyester		
C1451	22-7860-09	100 μF electrolytic		
C1452	22-7862-01	1 μF electrolytic		
C1455	22-7742-02	220 pF tubular		
C1456	22-7774-28	.22 μF polyester		
C1457	22-7613-12	1000 pF disc		
C1459	22-7861-12	470 μF electrolytic		
C1460	22-7860-06	22 μF electrolytic		
C1462	22-7860-08	47 μF electrolytic		
C1463	22-7742-06	470 pF tubular		

Table 6-2 *Monitor Cables (see Figure 4-3)*

		.e (666 : 1941 e : 6)	C1460	22-7860-06	22 μF electrolytic	
REFERENCE	ZDS PART		C1462	22-7860-08	47 μF electrolytic	
DESIGNATOR	NUMBER	DESCRIPTION	04400			
DESIGNATOR	NUMBER	DESCRIPTION	C1463	22-7742-06	470 pF tubular	
			C1467	22-7774-26	.15 μF polyester	
2A5/5A2	50-933	Connector and cable assembly	C1468	22-7862-02	2.2 μF electrolytic	
2A7	A-9919-43	Cable and housing assembly			•	
2B7	A-9917-46	Cable and housing assembly	C1504	22-7774-08	.0047 μF polyester	
2C5/5C2	50-934	Connector and cable assembly	C1505	22-7774-08	.0047 μF polyester	
2E8/8E2	50-607-26	Connector and cable assembly	C2215	22-7742-05	390 pF tubular	
2E9/9E2	50-616-21	Connector and cable assembly	C2251	22-7862-01	1 μF electrolytic	
			C2253	22-7742-10	1000 pF tubular	
3B3/3B3	50-242-06	Connector and cable assembly	C2257	22-7742-10	1000 pF tubular	
3S8	A-10150-05	Cable and housing assembly			roop, tabala.	
3U3/3U3	50-238-28	Connector and cable assembly	C2281	22-7862-22	.33 μF electrolytic	
			C2282	22-7633-35	120 pF disc	
4P4	A-10039-03	Speaker cable assembly	C2283	22-7743-20	22 pF tubular	
5H3/3B9	50-229-01	Connector and cable assembly				
5X7/7X5	50-238-39	Connector and cable assembly				

Table 6-3 (Continued)9-390 Interface Module (see Figure 4-4)

Table 6-3 (Continued)9-390 Interface Module (see Figure 4-4)

REFERENCE	ZDS PART		REFERENCE	ZDS PART	
DESIGNATOR	NUMBER	DESCRIPTION	DESIGNATOR	NUMBER	DESCRIPTION
C2354	22-7742-10	1000 pF tubular	L2376	95-3080	Transformer
C2355	22-7621-27	51 pF disc	L2378	20-3887-20	Coil
C2356	22-7743-24	33 pF tubular			
C2358	22-7742-10	1000 pF tubular	Transistors		
C2359	22-7621-11	11 pF disc	Q1201	121-895	NPN
C2362	22-7862-24	1.5 μF electrolytic	Q1202	121-986	PNP
C2376	22-7747-33	75 pF tubular	Q1203		
2377	22-7749-32	68 pF tubular	through		
		·	Q1209	121-895	NPN
C2378	22-7613-12	1000 pF disc			
C2391	22-7742-10	1000 pF tubular	Q1210	121-1019	PNP
2384	22-7862	.47 μF electrolytic	Q1211	121-1019	PNP
2385	22-7613-12	1000 pF disc	Q1212	121-1019	PNP
			Q1213	121-895	NPN
2386	22-7749-32	68 pF tubular	-		
C2388	22-7742-10	1000 pF tubular	Q1214	121-895	NPN
2389	22-7748-25	36 pF tubular	Q1215	121-1096	NPN
2390	22-7859-08	47 μF electrolytic	Q1216	121-895	NPN
		p. 0.000.01y.10	Q1217	121-1096	NPN
2392	22-7503-01	820 pF trapezoidal		500	
2393	22-7775-24	.1 μF polyester	Q2215	121-699	PNP
2400	22-7407-01	1 μF electrolytic	Resistors		
C2401	22-7405-02	2.2 μF electrolytic	1100101010		
22.401	22 7400 02	2.2 pr electionytic	R1207	63-10235-65	510 Ω, 1/4-watt, 5%
Diodes			R1211	63-10235-73	1.1 k Ω , 1/4-watt, 5%
riodes			R1212	63-10235-84	3.3 k Ω , 1/4-watt, 5%
CR1301	103-142-01	Low voltage, general	R1213	63-10235-88	4.7 k Ω , 1/4-watt, 5%
	100 142 01	Low vollage, general	2.0	00 10200 00	4.7 Mas, 174 Watt, 070
CR2254	103-142-01	Low voltage, general	R1214	63-10235-86	3.9 k Ω , 1/4-watt, 5%
CR2255	103-142-01	Low voltage, general	R1216	63-10235-78	1.8 k Ω , 1/4-watt, 5%
R2256	103-142-01	Low voltage, general	R1217	63-10235-70	820 Ω , 1/4-watt, 5%
R2400	103-279-29	Zener diode	R1301	63-10236-26	180 k Ω , 1/4-watt, 5%
R2401	103-279-09	Zener diode; 4.7V, .5 watt	R1302	63-10235-74	1.2 k Ω , 1/4-watt, 5%
		, ,	R1303	63-10235-80	2.2 k Ω , 1/4-watt,5%
ntegrated Circ	uits		R1304	63-10236-28	220 k Ω , 1/4-watt, 5%
-		_	R1306	63-10236-08	33 k Ω , 1/4-watt, 5%
C1301	221-105	Sync scan processor	R1452	63-10235-76	1.5 kΩ, 1/4-watt, 5%
C1451	221-98	Audio, monolithic	R1453	63-10236-04	22 kΩ, 1/4-watt, 5%
J. 1 01	L_1-00	Addio, Hiorighano	R1454	63-10243	1 Ω, 1/3-watt, 5%
C2376	221-179	Chroma/luminance processor	R1455	63-10235-46	82 Ω , 1/4-watt, 5%
	78-3014-07	Socket for IC2376	D1450	60 40005 70	1.01-0. 4/4 50/
			R1456	63-10235-78	1.8 kΩ, 1/4-watt, 5%
nductors			RX1457	63-10236-46	82 Ω2-watt, 5%
			R1463	63-10235-80	2.2 kΩ, 1/4-watt, 5%
1202	20-3907-16	Coil	R1464	63-10236-36	470 k Ω , 1/4-watt, 5%
2276	20-4136	Coil, delay line	R1830	63-10236	15 k Ω , 1/4-watt, 5%
2277	20-3907-21	Coil			
2278	20-3919	Coil, tunable			
2210					

Parts List Page 6-3

Table 6-3 (Continued)9-390 Interface Module (see Figure 4-4)

Table 6-3 (Continued)9-390 Interface Module (see Figure 4-4)

REFERENCE	ZDS PART		REFERENCE	ZDS PART	
DESIGNATOR	NUMBER	DESCRIPTION	DESIGNATOR	NUMBER	DESCRIPTION
R2215	63-10235-78	1.8 kΩ, 1/4-watt, 5%	R2400	63-10235-86	3.9 kΩ, 1/4-watt, 5%
R2216	63-10236-12	47 kΩ, 1/4-watt, 5%	R2401	63-10235-86	3.9 kΩ, 1/4-watt, 5%
R2234	63-10236-04	22 kΩ, 1/4-watt, 5%	R2402	63-10235-86	3.9 kΩ, 1/4-watt, 5%
R2235	63-10235-95	9.1 kΩ, 1/4-watt, 5%	R2403	63-10235-72	1 kΩ, 1/4-watt, 5%
R2236	63-10235-90	5.6 kΩ, 1/4-watt, 5%	R2404	63-10236-07	30 kΩ, 1/4-watt, 5%
R2237	63-10235-74	1.2 k Ω , 1/4-watt, 5%	R2405	63-10857-33	Control
R2238	63-10235-72	1 kΩ, 1/4-watt, 5%	R2406	63-10857-32	Control
R2239	63-10236-01	16 k Ω , 1/4-watt, 5%	R2407	63-10857-31	Control
R2240	63-10235-89	5.1 kΩ, 1/4-watt, 5%	R2408	63-10235-42	56 Ω, 1/4-watt, 5%
R2241	63-10235-74	$1.2 \mathrm{k}\Omega$, $1/4$ -watt, 5%	R2409	63-10235-89	5.1 kΩ, 1/4-watt, 5%
R2242	63-10235-72	1 kΩ, 1/4-watt, 5%	R2410	63-10235-89	5.1 kΩ, 1/4-watt, 5%
R2243	63-10235-71	910 kΩ, 1/4-watt, 5%			
	-		R2411	63-10235-72	1 k Ω , 1/4-watt, 5%
R2244	63-10235-48	100 Ω , 1/4-watt, 5%	R2412	63-10235-89	5.1 k Ω , 1/4-watt, 5%
R2245	63-10235-48	100 Ω , 1/4-watt, 5%	R2413	63-10235-43	62 Ω , 1/4-watt, 5%
R2251	63-10235-74	1.2 k Ω , 1/4-watt, 5%	R2414	63-10235-88	4.7 k Ω , 1/4-watt, 5%
R2254	63-10236-38	560 k Ω 1/4-watt, 5%	_		
			R2415	63-10235-88	4.7 k Ω , 1/4-watt, 5%
R2255	63-10235-84	3.3 k Ω , 1/4-watt, 5%	R2416	63-10235-88	4.7 k Ω , 1/4-watt, 5%
R2256	63-10235-72	1 k Ω , 1/4-watt, 5%	R2417	63-10235-72	1 kΩ, 1/4-watt, 5%
R2257	63-10235-72	1 k Ω , 1/4-watt, 5%	R2418	63-10243-56	220 Ω , 1/2-watt, 5%
R2276	63-10235-74	1.2 k Ω , 1/4-watt, 5%	R2419	63-10235-72	1 kΩ, 1/4-watt, 5%
R2278	63-10235-78	1.8 kΩ, 1/4-watt, 5%	R2420	63-10243-56	220 Ω, 1/2-watt, 5%
R2285	63-10235-96	10 kΩ, 1/4-watt, 5%	R2421	63-10235-72	1 kΩ, 1/4-watt, 5%
R2286	63-10235-72	1 kΩ, 1/4-watt, 5%	R2422	63-10243-56	220 Ω, 1/2-watt, 5%
		•	R2423	63-10235-31	20 Ω, 1/4-watt, 5%
R2287	63-10236	15 kΩ, 1/4-watt, 5%			
R2288	63-10236-38	560 k Ω , 1/4-watt, 5%	R2424	63-10235-31	20 Ω , 1/4-watt, 5%
R2297	63-10235-91	$6.2 \mathrm{k}\Omega$, 1/4-watt, 5%	R2425	63-10235-31	20 Ω , 1/4-watt, 5%
			R2427	63-10235-64	470 Ω , 1/4-watt, 5%
R2354	63-10235-64	470 Ω , 1/4-watt, 5%	R2428	63-10833-07	30 k Ω , 1-watt, 5%
R2355	63-10235-70	820 Ω , 1/4-watt, 5%			
R2356	63-10235-70	820 Ω , 1/4-watt, 5%	R2429	63-10236-04	22 k Ω , 1/4-watt, 5%
R2357	63-10235-94	8.2 k Ω , 1/4-watt, 5%	R2430	63-10235-87	4.3 k Ω , 1/4-watt, 5%
			R2431	63-10235-79	2 kΩ, 1/4-watt, 5%
R2358	63-10235-72	1 kΩ, 1/4-watt, 5%	R2432	63-10235-80	2.2 k Ω , 1/4-watt, 5%
R2376	63-10235-71	910 Ω , 1/4-watt, 5%			
R2378	63-10235-94	8.2 k Ω , 1/4-watt, 5%	R2433	63-10235-79	2 kΩ, 1/4-watt, 5%
R2379	63-10235-65	510 Ω , 1/4-watt, 5%	R2434	63-10235-88	4.7 kΩ, 1/4-watt, 5%
			R2450	63-10243-52	150 Ω, 1/4-watt, 5%
R2381	63-10235-64	470 Ω , 1/4-watt, 5%			
R2382	63-10236-04	22 k Ω , 1/4-watt, 5%	N/A	78-3039-06	Connector, 6 circuit
R2383	63-10235-48	100 Ω, 1/4-watt, 5%	N/A	78-3042-06	Connector, multi 6 circuit chain
R2385	63-10235-04	3.3 k Ω , 1/4-watt, 5%	N/A	86-799	Terminal, pin 0.045 inch square
R2387	63-10235-64	470 Ω, 1/4-watt, 5%			
R2388	63-10236-46	1.2 m Ω , 1/4-watt, 5%			
R2389	63-10235-88	4.7 k Ω , 1/4-watt, 5%			

Page 6-4 Parts List

Table 6-4 Table 6-4 (Continued)
9-155-25 Video Output Module (see Figure 4-13)
9-155-25 Video Output Module (see Figure 4-13)

REFERENCE	ZDS PART		REFERENCE	ZDS PART	
DESIGNATION	NUMBER	DESCRIPTION	DESIGNATION	NUMBER	DESCRIPTION
apacitors			R5106	63-7785	1 kΩ, 1/2-watt, 10%
•			R5107	63-7785	1 kΩ, 1/2-watt, 10%
5101	22-4671	.01 μF disc	R5109	63-7785	1 k Ω , 1/2-watt, 10%
5102	22-4671	.01 μF, disc	R5111	63-7785	1 k Ω , 1/2-watt, 10%
5103	22-7742-02	220 pF, tubular	NOTTI	03-7703	1 K12, 1/2-Wall, 10/6
5104	22-7742-02	220 pF, tubular	R5112 R5113	63-10840-88	4.7 kΩ, 3-watt, 5%
5105	22-7742-02	220 pF, tubular	R5114	63-10235-54	180 Ω , 1/4-watt, 5%
5106	22-4671	.01 μF, disc	R5115	63-10235-54	180 Ω , 1/4-watt, 5%
		,	110110	00 10200 04	100 12, 1/4 Wall, 5/6
park Gap			R5120		
			through		
5101			R5122	63-10235-97	11 k Ω , 1/4-watt, 5%
rough			R5124	63-10235-32	22 Ω, 1/4-watt, 5%
5103	52-2240-06	Spark gap	R5125	63-10235-32	22 Ω , 1/4-watt, 5%
ductors			Miscellaneous		
5101 5102		Wire	N/A	A-11056-02	CRT socket and connector assembly
rough			NI/A	40 4004 00	•
•	20-3907-25	Coil	N/A	43-1821-02	Housing connector, focus
5104		Coil	N/A	54-952	Nut 4-40 \times .25
5104	20-3907-25			70 0000 04	ODT analysis
5105	20-3907-25		N/A	78-2993-04	CRT socket
.5104 .5105 nrough .5107	20-3907-25	Coil			
5105 Irough 5107		Coil	N/A	Tal	CRT socket DIE 6-5 dule (see Figure 4-7)
5105 rough 5107 ransistors	20-3907-18		N/A <i>9-39</i>	Tal 11 Sweep Mo	ole 6-5
5105 rough 5107 ransistors 5101	20-3907-18 121-01034	NPN	9-39 REFERENCE	Tal 21 Sweep Mod ZDS PART	ble 6-5 dule (see Figure 4-7)
5105 rough 5107 ransistors 5101	20-3907-18 121-01034 126-02169	NPN Heat sink for Q5101	N/A <i>9-39</i>	Tal 21 Sweep Mod ZDS PART	ole 6-5
5105 rough 5107 ransistors 5101 /A	20-3907-18 121-01034 126-02169 114-01403	NPN Heat sink for Q5101 Screw for Q5101	9-39 REFERENCE DESIGNATOR	Tal 21 Sweep Mod ZDS PART	ble 6-5 dule (see Figure 4-7)
in 105 rough in 107 ransistors 5101 A A	20-3907-18 121-01034 126-02169 114-01403 93-02110	NPN Heat sink for Q5101 Screw for Q5101 Washer for Q5101	9-39 REFERENCE	Tal 21 Sweep Mod ZDS PART	ble 6-5 dule (see Figure 4-7)
in 105 rough in 107 ransistors 5101 A A	20-3907-18 121-01034 126-02169 114-01403	NPN Heat sink for Q5101 Screw for Q5101	9-39 REFERENCE DESIGNATOR Capacitors	Tal 21 Sweep Mod ZDS PART NUMBER	ole 6-5 dule (see Figure 4-7) DESCRIPTION
5105 rough 5107 ransistors 5101 /A /A	20-3907-18 121-01034 126-02169 114-01403 93-02110 54-00952	NPN Heat sink for Q5101 Screw for Q5101 Washer for Q5101 Nut for Q5101	9-39 REFERENCE DESIGNATOR Capacitors C2121	Tal 21 Sweep Mod ZDS PART NUMBER 22-7862	Die 6-5 dule (see Figure 4-7) DESCRIPTION .47 µF electrolytic
5105 rough 5107 ransistors 5101 /A /A /A	20-3907-18 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034	NPN Heat sink for Q5101 Screw for Q5101 Washer for Q5101 Nut for Q5101	9-39 REFERENCE DESIGNATOR Capacitors C2121 C2122	Tal 21 Sweep Mod ZDS PART NUMBER 22-7862 22-7774-14	DIE 6-5 dule (see Figure 4-7) DESCRIPTION .47 µF electrolytic .015 µF polyester
5105 rough 5107 ransistors 5101 /A /A /A /A /A	20-3907-18 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169	NPN Heat sink for Q5101 Screw for Q5101 Washer for Q5101 Nut for Q5101 NPN Heat sink for Q5102	9-39 REFERENCE DESIGNATOR Capacitors C2121 C2122 C2123	Tal 21 Sweep Mod ZDS PART NUMBER 22-7862 22-7774-14 22-7862-07	DIE 6-5 dule (see Figure 4-7) DESCRIPTION .47 µF electrolytic .015 µF polyester 33 µF electrolytic
5105 rough 5107 ransistors 5101 /A /A /A /A /A /A /A	20-3907-18 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403	NPN Heat sink for Q5101 Screw for Q5101 Washer for Q5101 Nut for Q5101 NPN Heat sink for Q5102 Screw for Q5102	9-39 REFERENCE DESIGNATOR Capacitors C2121 C2122	Tal 21 Sweep Mod ZDS PART NUMBER 22-7862 22-7774-14	DIE 6-5 dule (see Figure 4-7) DESCRIPTION .47 µF electrolytic .015 µF polyester
5105 rough 5107 ransistors 5101 /A /A /A /A /A /A /A /A	20-3907-18 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403 93-02110	NPN Heat sink for Q5101 Screw for Q5101 Washer for Q5101 Nut for Q5101 NPN Heat sink for Q5102 Screw for Q5102 Washer for Q5102	REFERENCE DESIGNATOR Capacitors C2121 C2122 C2123 C2124	Tal 21 Sweep Mod ZDS PART NUMBER 22-7862 22-7774-14 22-7862-07 22-7802-07	DIE 6-5 dule (see Figure 4-7) DESCRIPTION .47 μF electrolytic .015 μF polyester 33 μF electrolytic .01 μF tubular
5105 rough 5107 ransistors 5101 /A /A /A /A 5102 /A	20-3907-18 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403	NPN Heat sink for Q5101 Screw for Q5101 Washer for Q5101 Nut for Q5101 NPN Heat sink for Q5102 Screw for Q5102	REFERENCE DESIGNATOR Capacitors C2121 C2122 C2123 C2124 C2125	Tal 21 Sweep Mod ZDS PART NUMBER 22-7862 22-7774-14 22-7862-07 22-7802-07 22-7774-17	Die 6-5 dule (see Figure 4-7) DESCRIPTION .47 μF electrolytic .015 μF polyester 33 μF electrolytic .01 μF tubular .027 μF polyester
5105 rough 5107 ransistors 5101 /A /A /A 5102 /A /A	20-3907-18 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403 93-02110 54-00952	NPN Heat sink for Q5101 Screw for Q5101 Washer for Q5101 Nut for Q5101 NPN Heat sink for Q5102 Screw for Q5102 Washer for Q5102 Nut for Q5102	9-39 REFERENCE DESIGNATOR Capacitors C2121 C2122 C2123 C2124 C2125 C2127	Tal 21 Sweep Mod ZDS PART NUMBER 22-7862 22-7774-14 22-7862-07 22-7802-07	Die 6-5 dule (see Figure 4-7) DESCRIPTION .47 μF electrolytic .015 μF polyester 33 μF electrolytic .01 μF tubular .027 μF polyester .022 μF polyester
5105 rough 5107 ransistors 5101 /A /A /A /A /A /A /A /A	20-3907-18 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034	NPN Heat sink for Q5101 Screw for Q5101 Washer for Q5101 Nut for Q5101 NPN Heat sink for Q5102 Screw for Q5102 Washer for Q5102 Nut for Q5102	9-39 REFERENCE DESIGNATOR Capacitors C2121 C2122 C2123 C2124 C2125 C2127 C2131	Tal 21 Sweep Mod ZDS PART NUMBER 22-7862 22-7774-14 22-7862-07 22-7802-07 22-7774-17	Die 6-5 dule (see Figure 4-7) DESCRIPTION .47 μF electrolytic .015 μF polyester 33 μF electrolytic .01 μF tubular .027 μF polyester .022 μF polyester 10 μF electrolytic
5105 rough 5107 ransistors 5101 /A /A /A /A /A /A /A /A	20-3907-18 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169	NPN Heat sink for Q5101 Screw for Q5101 Washer for Q5101 Nut for Q5101 NPN Heat sink for Q5102 Screw for Q5102 Washer for Q5102 Nut for Q5102	9-39 REFERENCE DESIGNATOR Capacitors C2121 C2122 C2123 C2124 C2125 C2127	Tal 21 Sweep Mod ZDS PART NUMBER 22-7862 22-7774-14 22-7862-07 22-7802-07 22-7774-17 22-7774-16	Die 6-5 dule (see Figure 4-7) DESCRIPTION .47 μF electrolytic .015 μF polyester 33 μF electrolytic .01 μF tubular .027 μF polyester .022 μF polyester
5105 rough 5107 ransistors 5101 /A /A /A 5102 /A /A /A	20-3907-18 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034	NPN Heat sink for Q5101 Screw for Q5101 Washer for Q5101 Nut for Q5101 NPN Heat sink for Q5102 Screw for Q5102 Washer for Q5102 Nut for Q5102	9-39 REFERENCE DESIGNATOR Capacitors C2121 C2122 C2123 C2124 C2125 C2127 C2131	Tal 21 Sweep Mod ZDS PART NUMBER 22-7862 22-7774-14 22-7862-07 22-7802-07 22-7774-16 22-7862-05	Die 6-5 dule (see Figure 4-7) DESCRIPTION .47 μF electrolytic .015 μF polyester 33 μF electrolytic .01 μF tubular .027 μF polyester .022 μF polyester 10 μF electrolytic
5105 rough 5107 ransistors 5101 /A /A /A /A /A /A /A /A /A /A /A	20-3907-18 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169	NPN Heat sink for Q5101 Screw for Q5101 Washer for Q5101 Nut for Q5101 NPN Heat sink for Q5102 Screw for Q5102 Washer for Q5102 Nut for Q5102 NPN Heat sink for Q5103	9-39 REFERENCE DESIGNATOR Capacitors C2121 C2122 C2123 C2124 C2125 C2127 C2131 C2146	Tal 21 Sweep Mod ZDS PART NUMBER 22-7862 22-7774-14 22-7862-07 22-7774-17 22-7774-16 22-7862-05 22-7742-10	DIE 6-5 dule (see Figure 4-7) DESCRIPTION .47 μF electrolytic .015 μF polyester 33 μF electrolytic .01 μF tubular .027 μF polyester .022 μF polyester 10 μF electrolytic 1000 Pf tubular
5105 rough 5107 ransistors 5101 /A /A /A /A /A /A /A /A /A /A /A	20-3907-18 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403	NPN Heat sink for Q5101 Screw for Q5101 Washer for Q5101 Nut for Q5101 NPN Heat sink for Q5102 Screw for Q5102 Washer for Q5102 Nut for Q5102 NPN Heat sink for Q5103 Screw for Q5103	9-39 REFERENCE DESIGNATOR Capacitors C2121 C2122 C2123 C2124 C2125 C2127 C2131 C2146 C2147	Tai 21 Sweep Mod ZDS PART NUMBER 22-7862 22-7774-14 22-7862-07 22-77802-07 22-7774-16 22-7862-05 22-7742-10 22-7773-10	DIE 6-5 dule (see Figure 4-7) DESCRIPTION .47 μF electrolytic .015 μF polyester .01 μF tubular .027 μF polyester .022 μF polyester 10 μF electrolytic 1000 Pf tubular
5105 rough 5107 ransistors 5101 /A /A /A /A /A /A /A /A /A /A /A	20-3907-18 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403 93-02110	NPN Heat sink for Q5101 Screw for Q5101 Washer for Q5101 Nut for Q5101 NPN Heat sink for Q5102 Screw for Q5102 Washer for Q5102 Nut for Q5102 NPN Heat sink for Q5103 Screw for Q5103 Washer for Q5103 Washer for Q5103	9-39 REFERENCE DESIGNATOR Capacitors C2121 C2122 C2123 C2124 C2125 C2127 C2131 C2146 C2147 C2148	Tai 21 Sweep Mod ZDS PART NUMBER 22-7862 22-7774-14 22-7862-07 22-7774-16 22-7862-05 22-7742-10 22-7773-10 22-7860-29	DESCRIPTION .47 μF electrolytic .015 μF polyester .01 μF tubular .027 μF polyester .022 μF polyester 10 μF electrolytic 1000 Pf tubular .0086 μF polyester 680 μF electrolytic
5105 rough 5107 ransistors 5101 /A /A /A /A /A /A /A /A /A /A /A	20-3907-18 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403 93-02110	NPN Heat sink for Q5101 Screw for Q5101 Washer for Q5101 Nut for Q5101 NPN Heat sink for Q5102 Screw for Q5102 Washer for Q5102 Nut for Q5102 NPN Heat sink for Q5103 Screw for Q5103 Washer for Q5103 Washer for Q5103	9-39 REFERENCE DESIGNATOR Capacitors C2121 C2122 C2123 C2124 C2125 C2127 C2131 C2146 C2147	Tai 21 Sweep Mod ZDS PART NUMBER 22-7862 22-7774-14 22-7862-07 22-7774-17 22-7774-16 22-7862-05 22-7742-10 22-7773-10	DIE 6-5 dule (see Figure 4-7) DESCRIPTION .47 μF electrolytic .015 μF polyester .01 μF tubular .027 μF polyester .022 μF polyester 10 μF electrolytic 1000 Pf tubular
5105 hrough 5107 ransistors 5101 /A /A /A /A /A /A /A /A /A /A /A /A /A	20-3907-18 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403 93-02110 54-00952	NPN Heat sink for Q5101 Screw for Q5101 Washer for Q5101 Nut for Q5101 NPN Heat sink for Q5102 Screw for Q5102 Washer for Q5102 Nut for Q5102 NPN Heat sink for Q5103 Screw for Q5103 Screw for Q5103 Nut for Q5103 Nut for Q5103	9-39 REFERENCE DESIGNATOR Capacitors C2121 C2122 C2123 C2124 C2125 C2127 C2131 C2146 C2147 C2148 C2149 C2152	Tal 21 Sweep Mod ZDS PART NUMBER 22-7862 22-7774-14 22-7862-07 22-7802-07 22-7774-16 22-7862-05 22-7742-10 22-7760-29 22-7861-09 22-7862-02	DIE 6-5 dule (see Figure 4-7) DESCRIPTION .47 μF electrolytic .015 μF polyester .01 μF tubular .027 μF polyester .022 μF polyester 10 μF electrolytic 1000 Pf tubular .0086 μF polyester 680 μF electrolytic 100 μF electrolytic 2.2 μF electrolytic
5105 rough 5107 ransistors 5101 /A	20-3907-18 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403 93-02110 54-00952 63-10840-88	NPN Heat sink for Q5101 Screw for Q5101 Washer for Q5101 Nut for Q5101 NPN Heat sink for Q5102 Screw for Q5102 Washer for Q5102 Nut for Q5102 NPN Heat sink for Q5103 Screw for Q5103 Washer for Q5103 Nut for Q5103 Vasher for Q5103 Vasher for Q5103 Vasher for Q5103 Vasher for Q5103	9-39 REFERENCE DESIGNATOR Capacitors C2121 C2122 C2123 C2124 C2125 C2127 C2131 C2146 C2147 C2148 C2149 C2152 CX3204	Tal 21 Sweep Mod ZDS PART NUMBER 22-7862 22-7774-14 22-7862-07 22-7802-07 22-7774-16 22-7862-05 22-7742-10 22-7760-29 22-7861-09 22-7862-02 22-7862-02	DIE 6-5 dule (see Figure 4-7) DESCRIPTION .47 μF electrolytic .015 μF polyester .03 μF electrolytic .01 μF tubular .027 μF polyester .022 μF polyester 10 μF electrolytic 1000 Pf tubular .0086 μF polyester 680 μF electrolytic 100 μF electrolytic 2.2 μF electrolytic
5105 brough 5107 ransistors 5101 /A /A /A /A /A /A /A /A /A /A	20-3907-18 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403 93-02110 54-00952 63-10840-88 63-7785	NPN Heat sink for Q5101 Screw for Q5101 Washer for Q5101 Nut for Q5101 NPN Heat sink for Q5102 Screw for Q5102 Washer for Q5102 Nut for Q5102 NPN Heat sink for Q5103 Screw for Q5103 Washer for Q5103 Vasher for Q5103 Vasher for Q5103 V	9-39 REFERENCE DESIGNATOR Capacitors C2121 C2122 C2123 C2124 C2125 C2127 C2131 C2146 C2147 C2148 C2149 C2152 CX3204 C3206	Tal 21 Sweep Mod ZDS PART NUMBER 22-7862 22-7774-14 22-7862-07 22-7802-07 22-7774-16 22-7862-05 22-7742-10 22-7760-29 22-7861-09 22-7862-02 22-7862-02 22-7672-18 22-7523-01	DIE 6-5 dule (see Figure 4-7) DESCRIPTION .47 μF electrolytic .015 μF polyester .01 μF tubular .027 μF polyester .022 μF polyester 10 μF electrolytic 1000 Pf tubular .0086 μF polyester 680 μF electrolytic 100 μF electrolytic .2.2 μF electrolytic .0068 μF polypropylene .01 μF disc
5105 rough 5107 ansistors 5101 A A A A A 5102 A A A A A A A Since A A A A A A A A A A A A A A A A A A A	20-3907-18 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403 93-02110 54-00952 121-01034 126-02169 114-01403 93-02110 54-00952 63-10840-88	NPN Heat sink for Q5101 Screw for Q5101 Washer for Q5101 Nut for Q5101 NPN Heat sink for Q5102 Screw for Q5102 Washer for Q5102 Nut for Q5102 NPN Heat sink for Q5103 Screw for Q5103 Washer for Q5103 Nut for Q5103 Vasher for Q5103 Vasher for Q5103 Vasher for Q5103 Vasher for Q5103	9-39 REFERENCE DESIGNATOR Capacitors C2121 C2122 C2123 C2124 C2125 C2127 C2131 C2146 C2147 C2148 C2149 C2152 CX3204	Tal 21 Sweep Mod ZDS PART NUMBER 22-7862 22-7774-14 22-7862-07 22-7802-07 22-7774-16 22-7862-05 22-7742-10 22-7760-29 22-7861-09 22-7862-02 22-7862-02	DIE 6-5 dule (see Figure 4-7) DESCRIPTION .47 μF electrolytic .015 μF polyester .03 μF electrolytic .01 μF tubular .027 μF polyester .022 μF polyester 10 μF electrolytic 1000 Pf tubular .0086 μF polyester 680 μF electrolytic 100 μF electrolytic 2.2 μF electrolytic

Page **6-5** Parts List

Table 6-5 (Continued)9-391 Sweep Module (see Figure 4-7)

Table 6-5 (Continued)

9-391 Sweep Module (see Figure 4-7)

REFERENCE	ZDS PART		REFERENCE	ZDS PART	
DESIGNATOR	NUMBER	DESCRIPTION	DESIGNATOR	NUMBER	DESCRIPTION
C3209	22-7680	47 μF electrolytic	CR3401	103-142-01	Low voltage general
3210	22-7863-08	47 μF electrolytic			Low voltage, general
3211	22-7395	470 pF disc	CR3402	103-142-01	Low voltage, general
		•	CR3403	103-142-01	Low voltage, general
3212	22-7395	470 pF disc	CR3404	103-279	Zener, 2.4 V, 1/2-watt
C3213	22-7566-24	.1 μF polyester	Integrated Circ	uits	
C3215	22-7773-24	.1 μF polyester			
3217	22-7128	.68 μF polyester	IC3401	221-351	Vertical/horizontal processor
3218	22-2703	220 pF disc			
		p	Inductors		
3219	22-7860-13	1000 μF electrolytic			
3220	22-7395	470 pF disc	L1001	149-454	Core, ferrite bead
					•
3221	22-7395	470 pF disc	LX3261	20-3968	Coil, width control
3222	22-7832-10	100 μF electrolytic	LX3262	20-4142-01	Coil, linearity
3401	22-7562-36	1 μF polyester	Transistors		
3402	22-7860-09	100 μF electrolytic			
C3403	22-7773-10	.0068 μF polyester	Q1001	121-1114	Horizontal output transistor
3404	22-7862-01	1 μF electrolytic	N/A	126-2284	Heat sink for Q1001
			N/A	78-3080-01	Socket for Q1001
3405	22-7862-01	1 μF polyester	N/A	86-775	Terminal (female) for Q1001
		.01 μF polyester			
3406	22-7774-12		N/A	112-2367	Screw for Q1001
3407	22-7773-10	.0068 μF polyester	N/A	114-802	Screw (bronze) for Q1001
C3408	22-7862-01	1 μF electrolytic			
3410	22-7774-12	.01 μF polyester	Q2147	121-975	NPN
C3411	22-7773-16	.022 µF polyester	Q2148	121-1064	PNP
C3414	22-7702-09	.0056 μF polypropylene	<u> </u>		
C3415	22-7775-26	.015 μF polyester	Q2149	121-1072-01	NPN transistor
23413	22-1113-20	.015 μι polyester	N/A		
		050 E l l		126-2131-01	Heat sink
C3418	22-7774-21	.056 μF polyester	N/A	54-952	Nut for Q2149
C3419	22-7774-14	.015 μF polyester	N/A	114-1403	Screw for Q2149
3420	22-7773026	.15 μF polyester			
			Q3204	121-973	PNP
23421	22-7773-12	.01 μF polyester	Q3205	121-973	PNP
C3449	22-7613-10	680 pF disc	Q3206	121-1037	NPN
3450	22-7860-09	100 μF electrolytic		-	
			Q3401	121-1019	PNP
Diodes			Q3402	121-1096	NPN
- · - -			Q3403	121-1059	PNP
CR2122	103-254-01	Low voltage, general	Q3404	121-1039	NPN
			WO404	121-1020	TALLY
CR2123	103-254-01	Low voltage, general	0040=	104 00=	AIDAI
CR2149	103-254-01	Low voltage, general	Q3405	121-895	NPN
CR2150	103-142-01	Low voltage, general	Q3406	121-1019	PNP
CR2151	103-142-01	Low voltage, general	Q3407	121-1019	PNP
CRX3202	103-142-01	Low voltage, general	Resistors		
CRX3204	103-336-19	Zener, 10.0 V, 1/2-watt			
CRX3205	103-254-01	Low voltage, general	R1002	63-10852-01	.18 Ω, 3-watt, 10%
		5 / 5	TIVUZ	US-10052-01	. 10 12, 3-wall, 10%
CRX3206	103-344-02	Low voltage, general	R2101	62-10225 00	2.2 kO 1/4 wet 50/
DD0007	100.001	Laurellana nament		63-10235-80	2.2 kΩ, 1/4-watt, 5%
CR3207	103-284	Low voltage, general	R2102	63-10235-79	$2 k\Omega$, 1/4-watt, 5%
CR3208	103-254-01	Low voltage, general	R2103	63-10243-55	200 Ω , 1/2-watt, 5%
CR3210	103-326	Low voltage, general	R2110	63-10235-52	150 Ω , 1/4-watt, 5%
CR3211	103-284	Low voltage, general			

Page 6-6 Parts List

Table 6-5 (Continued)9-391 Sweep Module (see Figure 4-7)

Table 6-5 (Continued)9-391 Sweep Module (see Figure 4-7)

REFERENCE	ZDS PART		REFERENCE	ZDS PART	
DESIGNATOR	NUMBER	DESCRIPTION	DESIGNATOR	NUMBER	DESCRIPTION
R2111	63-10235-92	6.8 kΩ, 1/4-watt, 5%	R3233	63-10565-14	3.9 Ω, 1/2-watt, 5%
R2112	63-10236	15 k Ω , 1/4-watt, 5%	R3234	63-10565-14	3.9 Ω , 1/2-watt, 5%
R2113	63-10938-61	35.7 k Ω , 1/4-watt, 5%	R3237	63-10460-48	10 Ω , 10-watt, 10%
R2114	63-10235-59	300 Ω , 1/4-watt, 5%	R3238	63-10235-40	47 Ω , 1/4-watt, 5%
R2117	63-10235-64	470 Ω , 1/4-watt, 5%	R3239	63-10235-48	100 Ω, 1/4-watt, 5%
R2118	63-10243-56	220 Ω , 1/2-watt, 5%	R3261	63-10235-48	4.7 k Ω , 3-watt, 5%
RX2120	63-10565	1 Ω, 1/2-watt, 5%	113201	93-2104	Washer for R3261
RX2122	63-10565	1 Ω, 1/2-watt, 5%		93-2104	Washer for h3201
R2124	63-10243-60	330 Ω , 1/2-watt, 5%	RX3262	63-10565-65	510 Ω, 1/2-watt, 5%
R2125	63-10651-09	Control	RX3263	63-10565-65	510 Ω , 1/2-watt, 5%
RX2126	63-10565-59	300 Ω, 1/2-watt, 5%	D0404	00 40040 70	01:0 4/0 wet 50/
RX2128	63-10565-72	1 k Ω , 1/2-watt, 5%	R3401	63-10243-79	$2 k\Omega$, $1/2$ -watt, 5%
TOTETES	00 10000 72	, 142, 172 Wall, 070	R3402	63-10243-79	$2 k\Omega$, 1/2-watt, 5%
RX2129	63-10565-59	300 Ω, 1/2-watt, 5%	R3403	63-10235-88	4.7 k Ω , 1/4-watt, 5%
R2139	63-10235-60	330 Ω , 1/4-watt, 5%	R3404	61-10235-92	$6.8 \text{ k}\Omega$, $1/4$ -watt, 5%
RX2140	63-10565-52	150 Ω, 1/2-watt, 5%	R3405	63-10651-18	Control
RX2141	63-10565-52	150 Ω, 1/2-watt, 5%	R3406	63-10236-13	51 k Ω , 1/4-watt, 5%
		,	R3407	63-10234-14	56 k Ω , 1/4-watt, 2%
R2142	63-10235-54	180 Ω, 1/4-watt, 5%	R3408	63-10235-90	$5.6 \text{ k}\Omega$, $1/4$ -watt, 5%
R2143	63-10235-88	4.7 k Ω , 1/4-watt, 5%	110400	00 10200 00	5.5 Kaz, 1/4 Watt, 5/5
R2144	63-10235-80	2.2 kΩ, 1/4-watt, 5%	R3409	63-10235-72	1 kΩ, 1/4-watt, 5%
R2145	63-10235-88	4.7 k Ω , 1/4-watt, 5%	R3410	63-10235-84	3.3 k Ω , 1/4-watt, 5%
112140	00 10200 00		R3411	63-10235-90	5.6 k Ω , 1/4-watt, 5%
R2146	63-10243-12	3.3 Ω , 1/2-watt, 5%	R3412	63-10235-82	2.7 k Ω , 1/4-watt, 5%
R2148	63-10243-68	600 Ω , 1/2-watt, 5%	110412	03-10233-02	2.7 K12, 1/4-Wall, 5/6
RX2170	63-10565-08	2.2 Ω, 1/2-watt, 5%	D2/12	62 10225 02	2.7kO 1/4 watt 59/
R2171	63-10235-52	150 Ω , 1/4-watt, 5%	R3413	63-10235-82	2.7 kΩ, 1/4-watt, 5%
R2172	63-10651-24	Control	R3414	63-10938-35	21.5 kΩ, 1/4-watt, 1%
N21/2	03-10031-24	Control	R3415	63-10938-26	17.8 kΩ, 1/4-watt, 1%
R3201	63-10235-64	470 Ω, 1/4-watt, 5%	R3417	63-10235-70	820 Ω , 1/4-watt, 5%
R3202	63-10235-72	1 k Ω , 1/4-watt, 5%	D0440	00 40005 00	0.01:0.4/4
R3203	63-10442-86	390Ω , 5-watt, 5%	R3418	63-10235-86	3.9 kΩ, 1/4-watt, 5%
		15 Ω , 1/2-watt, 5%	R3420	63-10938-11	12.7 kΩ, 1/4-watt, 1%
R3204	63-10243-28	1311, 1/2-wall, 3/6	R3421	63-10235-48	100 Ω, 1/4-watt, 5%
R3207	63-10235-85	3.6 kΩ, 1/4-watt, 5%	R3422	63-10236-23	130 k Ω , 1/4-watt, 5%
		•	D0.105	00 10051 01	
R3208	63-10243-78	1.8 kΩ, 1/2-watt, 5%	R3425	63-10651-24	Control
R3210	63-10235-90	5.6 k Ω , 1/4-watt, 5% 270 Ω 1/2-watt, 5%	R3430	63-10235-82	2.7 kΩ, 1/4-watt, 5%
R3211	63-10243-58	2/011 1/2-watt, 5%	R3431	63-10235-44	68Ω, 1/4-watt, 5%
R3212	63-10422-24	1 Ω , 2-watt, 5%	R3432	63-10828-36	33 Ω ,1/2-watt, 5%
R3213	63-10235-90	5.6 k Ω , 1/4-watt, 5%	R3433	63-10828-36	33 Ω 1/2-watt, 5%
R3214	63-10235-72	1 k Ω , 1/4-watt, 5%	R3434	63-10828-36	33 Ω 1/2-watt, 5%
R3215	63-10235-98	12 k Ω , 1/4-watt, 5%	R3435	63-10235-48	100 Ω , 1/4-watt, 5%
R3216	63-10810-06	1.2kΩ, 1/2-watt, 5%	R3436	63-10235-48	100 Ω, 14-watt, 5%
R3217	63-10236-07	30 kΩ, 1/4-watt, 5%	R3437	63-10235-48	4.7 kΩ 1/4-watt, 5%
R3218	63-10810-07	$3 k\Omega$, 1/2-watt, 5%	R3438	63-10255-66	Control
R3219	63-10832-49	110 Ω, 1-watt, 5%	R3439	63-10051-12	470 Ω , 1/4-watt, 5%
R3220	63-10565-07	2 Ω, 1/2-watt, 5%	D2440	69 10040 00	1040 1/2 59/
R3221	63-10565-07	2 Ω, 1/2-watt, 5%	R3440	63-10243-86	1.9 kΩ, 1/2-watt, 5%
R3222	63-10244-20	100 k Ω , 1/2-watt, 5%	R3442	63-10235-96	10 kΩ, 1/4-watt, 5%
R3223	63-10430-28	1.5 Ω , 3-watt, 10%	R3443 R3444	63-10235-96 63-10235-88	10 k Ω , 1/4-watt, 5% 4.7 k Ω , 1/4-watt, 5%
R3224	63-7805	3,3 kΩ, 1/2-watt, 5%			
		2.7 k Ω , 1/4-watt, 5%			
R3230	63-10235-82	$2.7 \text{KHz}, 1/4\text{-wall}, 5\%$ $470 \Omega, 1/4\text{-walt}, 5\%$			
R3231	63-10235-64	1 Ω , 2-watt, 10%			
R3232	63-10422-24	1 12, 2-Wall, 10/0			

Parts List Page 6-7

Table 6-5 (Continued)
9-391 Sweep Module (see Figure 4-7)

REFERENCE	ZDS PART	
DESIGNATOR	NUMBER	DESCRIPTION
R3445	63-10235-96	10 kΩ, 1/4-watt, 5%
R3446	63-10235-67	620 $Ω$, 1/4-watt, 5%
R3447	63-10235-73	1.1 kΩ, 1/4-watt, 5%
R3448	63-10236-23	130 k Ω , 1/4-watt, 5%
R3449	63-10235-96	10 kΩ, 1/4-watt, 5%
R3450	63-10235-96	10 k Ω , 1/4-watt, 5%
R3451	63-10235-88	4.7 k Ω , 1/4-watt, 5%
Transformers		
TX3204	95-3786	Sweep, final display
TX3205	95-3670-03	Horizontal driver
N/A	64-519-01	Eyelet for TX3205

Table 6-6A-13284 Heat Sync Assembly (see Figure 4-10)

REFERENCE DESIGNATOR	ZDS PART NUMBER	DESCRIPTION
Integrated Circ	uit Parts	
ICX3201 N/A N/A	223-18 78-03169 194-678-02	Voltage regulator Socket for ICX3201 Insulating strip for ICX3201
N/A N/A	93-2113 112-2367-02	Lock washer for ICX3201 Screw for ICX3201
Miscellaneous		
RX3205 N/A	63-10482-75 19-1085	130 Ω , 20-watt, 5% resistor Clip for resistor
3D3	50-216-65	Connector and cable assembly
N/A	12-8562	Metal bracket for heat sync

Table 6-7A-12842 Capacitor and Cable Assembly (see Figure 4-10)

REFERENCE DESIGNATOR	ZDS PART NUMBER	DESCRIPTION
Capacitors		
C3249	22-7819-10	470 μF, electrolytic
Cable		
3M8	50-222-03	Connector and cable assembly

Table 6-89-293-03 Power Supply Module (see Figure 4-11)

apacitors		
3202	22-7962-14	33 μF electrolytic
3205	22-7962-14	33 μF electrolytic
3210	22-7857-10	220 μF electrolytic
3213	22-7777-11	.0082 μF polyester
3220	22-7786-01	220 pF disc
3224	22-7786-01	220 pF disc
3225	22-7431-06	.0047 μF disc
X3240	22-7431-06	.0047 μF disc
3270	22-7811	1000 pF disc
3271	22-7811	1000 pF disc
3273	22-7811	1000 pF disc
K3299	22-7431-06	.0047 μF disc
odes		
3216	103-295-02	Low voltage, general
R3220	103-275-16	Zener 8.2 V, 1/2-watt
RX3271		
rough		
RX3274	103-345-06	Low voltage, general
egrated Circ	uits	
3201	221-297	Regulator driver, 150 V
A	126-2131-01	Heat sink for IC3201
ansistors		
3210	126-978-01	PNP
3213	121-1101	PNP
3224	121-1101	PNP
sistors		
(3201	63-10828-96	10 kΩ, 1/2-watt, 5%
202	63-10559-40	47 Ω, 1/4-watt, 5%
204	63-10449-31	2 Ω, 7-watt, 5%
206	63-10244-02	18 k Ω , 1/2-watt, 5%
210	63-10533-16	1 kΩ, 1/4-watt, 1%
211	63-10533-33	150 kΩ, 1/4-watt, 1%
212	63-10460-46	8.2 Ω,10-watt, 10%
213	63-10244-20	100 k Ω , 1/2-watt, 5%
214	63-10236-22	120 kΩ, 1/4-watt, 5%
215	63-10236-36	470 kΩ, 1/4-watt, 5%
(3216	63-10828-72	1 kΩ, 1/2-watt, 5%
248	63-10458-31	2 Ω, 10-watt, 5%

Page 6-8 Parts List

Table 6-8 (Continued)9-293-03 Power Supply Module (see Figure 4-11)

REFERENCE DESIGNATOR	ZDS PART NUMBERS	DESCRIPTION
R3249 RX3274 R3296	63-10837-02 63-10657-03 63-10710	18 k Ω , 2-watt, 5% 1.2 M Ω , 1/2-watt, 20% Thermistor
Inductor		
TX3298	95-3439	Coil, line filter

Table 6-9
A-9522-06 Secondary Control Panel (see Figure 4-16)

REFERENCE DESIGNATOR	ZDS PART NUMBER	DESCRIPTION
Resistors		
R7101	63-10750	Control
R7102	63-10754	Control
R7103	63-10766-01	Control
R7104	63-10751	Control
R7105	63-10766-01	Control
R7131	63-10857-11	Control
R7137	63-10235-72	1 k Ω , 1/4-watt, 5%
Cables		
2B7	A-9917-46	Cable and housing assembly
2A7	A-9919-43	Cable and housing assembly
N/A	A-10322	Cable assembly with housing
N/A	19-733-01	Cable tie
N/A	43-1203	Housing; connector, female
2B7	50-216-43	Connector and cable assembly
2A7	50-218-51	Connector and cable assembly
N/A	50-738	Connector and cable assembly
N/A	78-3039-05	Connector, 5 circuit
N/A	78-3039-06	Connector, 6 circuit
N/A	78-3042-05	Connector, 5 circuit chain
N/A	78-3042-06	Connector, 6 circuit chain
N/A	86-389	Female terminal
N/A	157-44	Fastener, push-in

Table 6-10A-13042 Primary Control Board (see Figure 4-18)

REFERENCE DESIGNATOR	ZDS PART NUMBER	DESCRIPTION
SW 1	85-1559-02	Switch, power on/off
N/A	63-10772-04	Control, volume
N/A	19-733-06	Cable tie
N/A	12-7926-01	Metal bracket
3S8	A-10150-05	Cable and housing assembly
TP7	A-9911-79	Cable and housing assembly

Table 6-11A-13444 Input Panel (see Figure 4-20)

REFERENCE DESIGNATOR	ZDS PART NUMBER	DESCRIPTION
Resistors		· · · · · · · · · · · · · · · · · · ·
N/A	63-10235-45	75 Ω, 1/4-watt, 5%
N/A	63-10235-45	75 Ω , 1/4-watt, 5%
N/A	63-10235-45	75 Ω , 1/4-watt, 5%
Cables, Conne	ctors, and Jack	s s
9H2	52-2571-19	Cable and plug
9G3	50-261-13	Connector and cable assembly
9E4	50-261-12	Connector and cable assembly
9F2	50-261-11	Connector and cable assembly
N/A	A-11642-03	Jack and switch assembly (Luma In jack and Hi Z-75 Ω Switch)
N/A	78-2399	Jack, audio in
N/A	19-733-01	Cable tie




Figure 6-1
Exploded View